

# # ENGINEERING — Road Repair Technical Report

## ## 1. System Overview

The MBT (Type 99A) is a critical asset in engineering operations. This document covers road repair analysis for the MBT platform.

## ## 2. Technical Parameters

- Comm Range: 30 km
- Standby Power: 2 W
- Operating Temp: -40~+55 °C
- Hop Rate: 500 hop/s
- MTTR: 2 h

## ## 3. Operational Procedures

### ### 3.1 Pre-Operation Checks

1. Verify power supply voltage is within specified range
2. Run Built-In Test (BIT) and confirm all PASS
3. Establish communication link with command post
4. Confirm GPS lock with CEP < 10m
5. Log start-up time and initial parameters

### ### 3.2 Mission Execution

Monitor system performance indicators continuously. Report any anomaly exceeding threshold within 5 minutes. Maintain log entries at minimum 15-minute intervals

.

## ## 4. Fault Diagnosis

- ERR-008: Nav accuracy degraded -> Check subsystem logs and replace module
- ERR-001: Transmitter power low -> Check subsystem logs and replace module
- ERR-009: FCS computation error -> Check subsystem logs and replace module

## ## 5. Maintenance Schedule

- Monthly Maintenance: Perform ■■
- Quarterly Maintenance: Perform ■■■
- Daily Maintenance: Perform ■■

## ## 6. Safety Precautions

- Ensure all personnel maintain safe distance during high-power transmission
- Follow lock-out/tag-out procedures before maintenance
- Report all near-miss incidents within 24 hours
- Maintain radiation exposure records for all personnel

Document ID: ENGINEER-RoadRepair-017

Classification: UNCLASSIFIED // FOR OFFICIAL USE ONLY