

makeCNC




GE AC4400CW LOCOMOTIVE



makeCNC
Robotic Tools & other Machines

www.makecnc.com




PARTS LIST



IT IS RECOMMENDED TO GO THROUGH ALL THE PAGES
AND SEE EACH STEP BEFORE STARTING THE ASSEMBLY


makeCNC



ASSEMBLY STEPS




www.makecnc.com




ASSEMBLY STEPS






ASSEMBLY STEPS





ASSEMBLY STEPS






ASSEMBLY STEPS






ASSEMBLY STEPS





ASSEMBLY STEPS





ASSEMBLY STEPS





COMPLETE



www.makecnc.com



COMPLETE



www.makecnc.com