


**makeCNC**



**makeCNC**

Robotic Tools & other Machines

[www.makecnc.com](http://www.makecnc.com)

**THUNDER DOME**

Thunder  
Live Dome

makeCNC




makeCNC

Robotic Tools & other Machines

[www.makecnc.com](http://www.makecnc.com)

THUNDER DOME






## PARTS LIST



[www.makecnc.com](http://www.makecnc.com)

THE HOOK SHOULD BE PLACE  
IN ROUND COMPONENT  
BEFORE PLACE THE MAIN  
STRUTS.






## ASSEMBLY STEPS



**makeCNC**



## ASSEMBLY STEPS




[www.makecnc.com](http://www.makecnc.com)




## ASSEMBLY STEPS






**ASSEMBLY STEPS**



## ASSEMBLY STEPS









## ASSEMBLY STEPS




[www.makecnc.com](http://www.makecnc.com)



## ASSEMBLY STEPS








## ASSEMBLY STEPS



[www.makecnc.com](http://www.makecnc.com)




**ASSEMBLY STEPS**



## ASSEMBLY STEPS







## ASSEMBLY STEPS




[www.makecnc.com](http://www.makecnc.com)





## ASSEMBLY STEPS





## ASSEMBLY STEPS





## ASSEMBLY STEPS





## ASSEMBLY STEPS



[www.makecnc.com](http://www.makecnc.com)

**makeCNC**



**COMPLETE**



[www.makecnc.com](http://www.makecnc.com)

**makeCNC**



**COMPLETE**



[www.makecnc.com](http://www.makecnc.com)