


Home


Contact

Walkthrough
Schematic Editors
About VeeCAD
Gallery
Resources
User comments
Downloads
Forums

1. Draw Schematic and Export Netlist




2. Import Netlist into VeeCAD




During import libraries are searched for component footprints.


3. Move, Rotate and Resize Components




4. Add Links, Wires and Breaks




5. Move and Rotate Text



6. Auto Route (stripboard only)



7. Check Errors and Trace Nets



8. Print

