


Q-2 weighing indicator



- Large display
 1" bright LED (6 digits)
- Rechargeable battery
 6V 4AH battery-powered
- HI/LO alarm
 Set the limit for checkweigh
- HOLD function
 For weighing moving objects



Simple and elegant weighing indicator for your industrial needs.

Models	IQ-2
Resolution	1/3000 ~ 1/30000
Response	3 sec
Tare range	100% of capacity
Zero range	4% of capacity
Power Source	6V 4AH Rechargeable battery 220VAC 12VDC 500mA Adaptor
Power consumption	Normal: 100mA Sleeping: <20mA
Temperature	Storage: -10 ~ 50°C Operating: 0 ~ 40°C
Humidity	Storage: 5% ~ 90% R.H Operating: 10% ~ 80% R.H
Display	1" LED (6 digits)
Designators	ZERO, STABLE, TARE, LO-BAT, kg, g, lb, oz
Product weight	Gross: 2.18kg Nett: 1.98kg