



Distribution of operational parameters with fitted normal curves


Air temp. [K]




Process temp. [K]



Rot. speed [rpm]



Torque [Nm]



Tool wear [min]

