




Defect Analysis Report

Total Defects Found: 53 | Screenshots Captured: 53


Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building1	122	11	1	00:00:23	top front crack	
building1	122	10	1	00:00:34	top rear crack	
building1	122	18	1	00:00:56	bottom rear crack	
building1	122	17	1	00:01:01	bottom rear crack	
building1	122	16	1	00:01:04	bottom rear crack	
building1	122	15	1	00:01:08	bottom rear crack	
building1	122	14	1	00:01:13	bottom rear crack	
building1	122	13	1	00:01:22	bottom rear crack	

Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building1	122	12	1	00:01:32	bottom rear crack	
building1	122	11	1	00:01:37	bottom rear crack	
building1	122	10	1	00:01:40	bottom rear crack	
building2	112	9	2	00:02:12	top front and rear crack	
building2	112	10	1	00:02:33	top rear crack	
building2	112	N/A	1	00:02:57	N/A	
building3	118	18	1	00:03:35	bottom rear crack	
building3	118	17	1	00:03:39	bottom rear crack	
building3	118	16	2	00:03:42	bottom rear crack	
building3	118	15	2	00:03:46	bottom rear crack	

Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building3	118	9	1	00:03:56	bottom rear crack	
building3	118	8	1	00:03:59	bottom rear crack	
building3	118	1	2	00:04:09	rear crack	
building3	118	8	1	00:04:33	top rear crack	
building3	118	9	2	00:04:44	top rear crack	
building3	118	18	1	00:04:58	top rear crack	
building4	126	18	2	00:05:06	bottom rear crack	
building4	126	17	2	00:05:11	bottom rear crack	
building4	126	9	1	00:05:20	bottom rear crack	
building4	126	8	1	00:05:29	bottom rear crack	

Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building4	126	2	1	00:05:43	bottom rear crack	
building4	126	1	1	00:05:47	bottom rear crack	
building4	126	2	2	00:06:06	top center crack	
building4	126	3	1	00:06:38	bottom rear crack	
building5	137	16	1	00:06:49	top front and rear crack	
building5	137	8	2	00:07:09	top front and rear crack	
building5	137	5	2	00:07:15	top front and rear crack	
building5	137	4	2	00:07:17	top front and rear crack	
building5	137	16	1	00:07:29	bottom rear crack	
building5	137	8	2	00:07:43	bottom rear crack	

Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building5	137	7	3	00:07:47	bottom rear crack	
building6	117	17	2	00:08:12	top front and rear crack	
building6	117	7	1	00:08:34	bottom front and rear crack	
building6	117	1	2	00:08:57	top front and rear crack	
building6	117	2	1	00:09:04	top front rear crack	
building6	117	3	1	00:09:12	top rear crack	
building6	117	4	1	00:09:16	top front crack	
building6	117	5	1	00:09:22	top front and rear crack	
building6	117	6	1	00:09:26	top front crack	
building6	117	7	1	00:09:31	top front and rear crack	

Building	Apartment	Read Number	Priority	Timestamp (s)	Description	Screenshot
building6	117	9	1	00:09:36	top front crack	
building6	117	10	1	00:09:57	top front and rear crack	
building6	117	11	1	00:10:35	top front and rear crack	
building6	117	N/A	2	00:11:01	N/A	
building7	226	8	N/A	00:11:37	N/A	

Report generated on 2025-10-17 20:34:14