Network Trouble Shooting (Modem Indications)

	ROUTER		MODEM					I	AN EX	TENDI	ER	SWITCH		PC		
S.N o	Status	Power	AC T	Power	TD	RD	LOS	Pow er	AC T	WA N/D SL	LAN/ ETH	Powe r	Port	Monit or(IC ON)	CPU (NI C Card	Remarks/Action
1.	Normal Working	Green	Flic keri ng	Green	Flicke ring	Flick ering	No	Gree n	Gre en	Flick ering	Flicke ring	Red	Gree n	Presen t	Flasi ng	Normal working
2.	LAN Disabled	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes	Yes	Absen t	Abs ent	LAN Disabled in PC. Enable the LAN
3.	LAN Cable Unplugg ed/LAN Cable disconne cted	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes	Yes	Cross Mark in ICON	Abs ent	Check LAN Cable, RJ45 and CAT Cable continituity. Test NIC Card by Ping 127.0.0.1 also
4.	Switch Port Failure	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes	LED not Glo win g	Cross Mark in ICON	Abs ent	Change the port
5.	Switch power OFF	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Abse nt	LED not Glo win g	Cross Mark in ICON	Abs ent	Check Power Supply

		ROUTER		MODEM			I	LAN EX	TENDI	ER	SWITCH		PC			
S.N o	Status	Power	AC T	Power	TD	RD	LOS	Pow er	AC T	WA N/D SL	LAN/ ETH	Powe r	Port	Monit or(IC ON)	CPU (NI C Card	Remarks/Action
7.	DSL/WA M No Indicatio n	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Abse nt	Yes	Yes	Yes	Yes	Yes	Local Cable Pair disconnected. Check Line and RJ 11 Card. Reset the modem. Check Modem Configuration also.
8.	ACT Not Glowing	Yes	Yes	Yes	Yes	Yes	No	Yes	Abs ent	Abse nt	Yes	Yes	Yes	Yes	Yes	Modem Not Sync. Check Cable Pair. Check Modem configuration. Reset and Re- configure the modem
9.	No Power in Lan Extender	Yes	Yes	Yes	Yes	Yes	No	Abs ent	Abs ent	Abse nt	Absen t			Cross Mark in ICON	No	Check Power to Lan Extender

		ROUTER		UTER MODEM					LAN EX	KTENDI	ER	SWITCH		PC		
S.N o	Status	Power	AC T	Power	TD	RD	LOS	Pow er	AC T	WA N/D SL	LAN/ ETH	Powe r	Port	Monit or(IC ON)	CPU (NI C Card	Remarks/Action
11.	No RD in V.35	Yes	Yes	Yes	Yes	No	No					Yes	Yes	Yes	Yes	No Data from G.703. Local wiring at G.703 May be problem
12.	No TD in V.35	Yes	Yes	Yes	No	Yes	No					Yes	Yes	Yes	Yes	No Data from Router. Check V.35 Cable. Sometimes Router Port may faulty
13.	No RD in G.703	Yes	Yes	Yes	Yes	No	No					Yes	Yes	Yes	Yes	No Data from V.35. Local wiring at V.35 May be problem
14.	No TD in G.703	Yes	Yes	Yes	No	Yes	No					Yes	Yes	Yes	Yes	No Data from MUX Side. Channel problem