

Signed Dimensional Deviation (Measured – Nominal)
Signed Deviation (mm)
0.1
0
-0.1
-0.2
-0.3
-0.4
-0.5
-0.6
-0.7
Length
Width
Height
PS01
PS02
PS03
PS04
PS05
PS06
PS07
PS08
PS09
Parameter Setting