Aspire Wiki - ObjectWeb - MultimeterDVM1200

Aspire :: Bundles :: Velleman DVM 1200

Aspire :: Bundles :: Velleman DVM 1200 Producer

- 1 Context
- 2 Dependencies
- 3 Build
 - ° 3.1 Sources
- 4 Installation
- 5 Test
- <u>6 Configuration</u>
- <u>7 Data</u>
- 8 Troubleshooting
- 9 Links
- 10 Gallery

This section describes the bundle for USB Multimeter Velleman DVM 1200 sensor

1 Context

The USB Multimeter Velleman DVM 1200 is a USB-to-serial multimeter. It can measure current (AC/DC), voltage (AC/DC), frequency, resistance, temperature, capacitance ... The DVM1200 costs approx. 60 euros VAT.

The DVM1200MultimeterProducer bundle registers one Producer service producing Measurement, Double or String objects (unit is V, TBD). This producer can be used for Green Computing managers such as the VOVOJavaEE.

2 Dependencies

This bundle requires:

- OSGi R4 Compendium, available from OBR in Felix Shell
- RXTX, available from Aspire SVN Repository/bundles/common/rxtx

3 Build

3.1 Sources

• here

4 Installation

You must install previously the driver for the (optical) Serial-to-USB adapter (Sunplus SPCP 825).

5 Test

You can test with the RXTX command available from Aspire SVN Repository/bundles/common/rxtx.cmd

-> rxtx list Stable Library ================================== Native lib Version = RXTX-2.1-7 Java lib Version = RXTX-2.1-7 ... -> rxtx iowrapper org.ow2.aspirerfid.vellemandvm1200.wrapper.DVM1200MultimeterWrapper -> rxtx open COM15 2400 None None 8 1 Nonerxtx (226 bytes received): 0.22 A (error=+/-0.0) AC rxtx (14 bytes received): 0.221 A (error=+/-0.0) AC rxtx (14 bytes received): 0.221 A (error=+/-0.0) AC rxtx (14 bytes received): 0.221 A (error=+/-0.0) AC rxtx (14 bytes received): 0.219 A (error=+/-0.0) AC rxtx (14 bytes received): 0.219 A (error=+/-0.0) AC rxtx (14 bytes received): 0.219 A (error=+/-0.0) AC ... rxtx close

6 Configuration

In src/main/resources/IPOJO-INF/metadata.xml

portName

7 Data

The producer produces <u>org.osgi.util.measurement.Measurement</u> with the following <u>units</u> Unit.K, Unit.V, Unit.A, Unit.F, Unit.Hz, Unit.Ohm, Unit.Unity

8 Troubleshooting

Sometime, the OSGi platform must be shutdown when the bundle is updated.

9 Links

- DVM1200 User manual http://www.velleman.eu/downloads/1/dvm1200gbnlfresdplit.pdf
- Other Velleman USB-Serial multimeters
 - ° <u>DVM2000</u>: the data format for the DVM2000 is probably similar to the DVM1200 one. Please could you report this to the mailing list if you have a DVM2000.
- Other Velleman USB-Serial scopes
 - ° HPS40 (protocol
 - ° HPS50
 - ° APS230
 - ° PPS10

10 Gallery

Aspire Wiki - ObjectWeb - MultimeterDVM1200



Aspire :: Bundles :: Velleman DVM 1200 (en)
Creator: xwiki:XWiki.donsez Date: 2010/07/01 08:31
Last Author: xwiki:XWiki.donsez Date: 2010/07/05 14:03
Copyright (c) 2008-2010, Aspire