



Requirement for Steam Sterilizer:-

- Sterilizer Needs 18KW 3 phase power supply and needs 63 Amps 4 pole MCB with 10 Sq mm copper wire
- Steam has to be exhausted with in 5 meters from the exhaust port.
- 3. Hot water drain requires GI or CPVC plumbing
- Need RO water with low TDS for steam sterilizers.

Note:-

- Sterile area should have AHU for air quality.
- 2. All Dimensions are in Inches (Millimetres)

Prepared by
Cistron Systems Private Limited