
```
====WATER FILTRATION ===
   X 0
                X 1
                             X 2
                                                                                                                                        ___( M 0 )
start
                        e-stop
                                                                                                                                          run system
   М 0
  \dashv \vdash
run system
                                         ======TANK 1 LEVELING PROCESS======
                           M 1013
   М 0
                Х3
   +
                4 +
                             +\vdash
run system
            high level
                         1s clock p
            t1
                         ulse, 0.5s
                         On / 0.5s
Off
               M 24
               \dashv \vdash
            when the t
2 be low
                M 1
                                                                                                                 CNT
                                                                                                                             C0
                                                                                                                                          K10
                +1
                CO
                             X 5
                                                                                                                             SET
                                                                                                                                          Υ0
                             1/1
                         overload m
                                                                                                                                          motor 1
                                                                                                                             RST
                                                                                                                                          CO
   М 0
                Υ0
                           M 1013
   +\vdash
               \dashv \vdash
                             +
                                                                                                                                             M 2
run system motor 1
                         1s clock p
                         ulse, 0.5s
                         On / 0.5s
M 2
                                                                                                                                          K10
                             -11
                                                                                                                 CNT
                                                                                                                             C112
                           C112
                                                                                                                              RST
                                                                                                                                          Υ0
                             4 +
                                                                                                                                          motor 1
                                         X 6
                                                                                                                                          Y 1
                                         <del>1</del>/⊦
                                                                                                                              SET
                                     oveload m2
                                                                                                                                          motor 2
                Y 1
                           M 1013
   М 0
   \dashv \vdash
               \dashv \vdash
                             +
                                                                                                                                          _( M 3
run system motor 2
                         1s clock p
ulse, 0.5s
                         On / 0.5s
M 3
                                                                                                                 CNT
                                                                                                                             C113
                                                                                                                                          K10
                            -11
                           C113
                                                                                                                              SET
                                                                                                                                          Υ0
                            \dashv \vdash
                                                                                                                                          motor 1
                                                                                                                             RST
                                                                                                                                          Y 1
                                                                                                                                          motor 2
                                                                                                                             RST
                                                                                                                                          C113
```



```
SET
                                                                                                           М 7
                     ======TANK2 LEVELING PROCESS======
  М 0
            М 7
                                                   X 1 3
                    ATMR
                                                                                                  SET
                           T 5
                                      K60
                                                                                                           Y 4
  +
                                                    <del>1</del>/|
run system
                                                overload m
                                                                                                           motor 2-1
                                                2-1
             Y 4
                     M 1013
                      4 F
                                                                                                              M 8
         motor 2-1
                   1s clock p
                   ulse, 0.5s
                   On / 0.5s
            M 8
                   Off
                                                                                        CNT
                                                                                                 C117
                                                                                                           K10
            +1
           C117
                      X 1 4
                                                                                                 SET
                      <del>1</del>/|
                   overload m
                                                                                                           motor 2-2
                   2-2
                                                                                                 RST
                                                                                                           Y 4
                                                                                                           motor 2-1
   МΟ
            Y 5
                     M 1013
   +
                                                                                                              М 9
run system
         motor 2-2
                   1s clock p
                   ulse, 0.5s
                   On / 0.5s
            М 9
                   Off
                                                                                        CNT
                                                                                                 C118
                                                                                                           K10
            +1
           C118
                                                                                                  RST
                                                                                                           Y 5
            +
                                                                                                           motor 2-2
                                                                                                 RST
                                                                                                           C117
                                                                                                 RST
                                                                                                           C118
   М 0
            X 1 5
                    ATMR
                                                                                                 RST
                           Т3
                                      K30
                                                                                                           Y 4
   H +
            +
run system
                                                                                                           motor 2-1
         high level
            X 1 0
            4 +
         low level
         filter 1
            Т3
                                                                                                 SET
                                                                                                           M 24
                                                                                                           when the t
                                                                                                           2 be low
                                                                                                 RST
                                                                                                           Y 5
                                                                                                           motor 2-2
            М 0
            X 1 5
                                                                                        TMR
                                                                                                 T 1 0
                                                                                                           K60
  4 +
            +
```

```
X 1 0
              4 +
           low level
           filter 1
              T 1 0
                         T 1 1
                                                                                                                  ____( M 10 )
                         H/H
                         T 12
                                  ATMR
                                                       K30
                          <del>1</del>/|
                                                                                                                           _( M 1 1 )
                         M 1 1
                                                                                                     TMR
                                                                                                                T12
                                                                                                                           K60
                          +
              M 10
   М 0
                                                                                                    CNT
                                                                                                                C10
                                                                                                                           K 5
  \dashv \vdash
run system
                      C10
                                 K 1
                                                                                                                        ____( M 1 2 )
                     C10
                                 К3
                                 K 2
                                                                                                                         ___( M 1 3 )
                      C10
                                 K 4
                                                M 16
                                                                                                                SET
   М 0
              M 12
                         M 14
                                     Y 7
                                                X 4 1
                                                H/H
                                                                                                                           _( Y6
   +
run system
                                 mixer
                                            overload u
                                                                                                                           uv motor
                         M 14
                                                X42
              M 13
                                     Y 6
                                     1/
                                                H/\vdash
                                                                                                                           _( Y7
                                 uv motor
                                            overload m
                                                                                                                           mixer
                                            ixer
              М 0
              M 14
                                                           X43
                       ATMR
                                                                                                                SET
                                                                                                                           Y10
                                            K60
 \dashv \vdash
                                                        ---|/⊦
run system
                                                        overload 3
                                                                                                                           motor t3-1
                                                       -1 m
              Y10
                        M 1013
              \dashv \vdash
                        \dashv \vdash
                                                                                                                           _( M 2 0 )
                      1s clock p
           motor t3-1
                      ulse, 0.5s
On / 0.5s
              M 20
                      Off
                                                                                                    CNT
                                                                                                                C120
              \dashv \uparrow \vdash
                                                                                                                           K10
```

```
C120
                      overload 3
                          X44
                                                                                                                     SET
                                                                                                                                 Y11
                                                                                                                                 moto t3-2
                                                                                                                     RST
                                                                                                                                 Y10
                                                                                                                                 motor t3-1
                        M 1013
   М 0
               Y11
run system
          moto t3-2
                          \dashv \vdash
                                                                                                                                 _( M 2 1 )
                      1 s clock p
ulse, 0.5s
On / 0.5s
Off
              M 2 1
                                                                                                         CNT
                                                                                                                     C121
                                                                                                                                 K10
               -1\uparrow\uparrow
              C121
                                                                                                                     RST
                                                                                                                                 Y11
               +
                                                                                                                                 moto t3-2
                                                                                                                     RST
                                                                                                                                 C120
                                                                                                                     RST
                                                                                                                                 C121
           X 1 6
   М 0
                                                                                                                     RST
                                                                                                                                 M 14
run system low level
                                                                                                                     SET
                                                                                                                                 M 16
                                                                                                                     RST
                                                                                                                                 C10
                                                                                                                                 END
```