



KS erősítőfokozat munkapont-beállítása



U_{DS0}, I_{D0}, U_{GS0} munkaponti mennyiségek

$$U_{S0} = |U_{GS0}|$$

$$R_S = \frac{U_{S0}}{I_{D0}} = \frac{|U_{GS0}|}{I_{D0}}$$

$$R_D = \frac{U_T - U_{DS0} - U_{S0}}{I_{D0}}$$

$$R_G = 1 \dots 10 \text{ M}\Omega$$