Returns Inspection Report

IR-2026-00002 | Return R102 | SoundPeak Wireless Headphones Pro

Report ID	IR-2026-00002
Inspection record ID	2
Return ID	R102
Order ID	O102
Customer ID	C00102
Product	SoundPeak Wireless Headphones Pro (product P_R102)
Category	electronics
Inspection date	2026-03-13 12:00
Inspector	Kavya Iyer (WH-INS-014)
Site	Uluberia Fulfilment Hub, Kolkata (WB)

1. Identification

Purchased serial (order line)	HP9081
Returned serial (unit received)	HP9012
Serial match	No - MISMATCH

2. Timeline

Order date	2026-02-23
Delivered	2026-02-28
Return requested	2026-03-08 (8 days after delivery; within the 30-day electronics window)
Received at warehouse	2026-03-12
Return reason (recorded)	not_functioning
Price paid	INR 4,999.00

3. Condition summary

Product condition	defective
Accessories expected	USB-C charging cable, 3.5 mm audio cable, carry case, quick-start guide
Accessories complete	Yes
Defect verified	No
Inspection result	INCONCLUSIVE

4. Findings

Serial mismatch: the order line for O102 records purchased serial HP9081. The unit received at the warehouse carries serial HP9012 on its internal label and on the outer box sticker. The two serial numbers do not match.

The serial label on the unit is intact, legible and shows no sign of removal or reprinting. The headphones are the same model as the order line (SoundPeak Wireless Headphones Pro) and all accessories are present.

On power-up the unit pairs over Bluetooth, but the left driver produces no audio at any volume (condition: defective). Because the identity of the returned unit could not be matched to the purchase record, the defect was not verified against the purchased item (defect verified: No).

Photographs of the serial label (front and rear), the box sticker and the accessory tray are attached to the inspection record.

5. Inspector system note (verbatim from inspection record)

"Returned unit serial HP9012 does not match purchase record HP9081. Additional verification required."

6. Recommended next step

Additional verification required. Hold the return; do not request or execute a refund while the serial mismatch is unresolved. Investigation case 1 (serial_mismatch, high priority) is assigned to analyst_02. Suggested checks: dispatch scan for O102, the customer's invoice or box photograph showing the serial, and whether HP9012 appears on any other order line.

Result codes (SOP WH-INS-07): PASS = inspection protocol completed and claim-relevant findings are conclusive; FAIL = findings do not support the claim as stated; INCONCLUSIVE = findings cannot be confirmed without further verification. Product condition codes follow the warehouse grading scale (new, like_new, open_box, damaged, defective, unsafe, for_parts).

Signed: Kavya Iyer, Uluberia Fulfilment Hub. This report records physical findings only; refund and recovery decisions are made by returns analysts under the applicable policy.