


No Capacitors, Resistors, or surface mount components.
Try to move traces out of these regions as much as possible.



ABSOLUTELY NOTHING can be put here. They will be crushed by the spring retention posts.

FRONT



DIMENSIC	THERWISE SPECIFIEDNS ARE IN MILLIME	FINISH:				DEBUR AND BREAK SHARP	DO NOT SCALE DRAWING REVISION		
SURFACE FINISH: TOLERANCES: LINEAR: ANGULAR:							EDGES		
	NAME	SIG	NATURE	DATE				TITLE:	
DRAWN	RAWN SolidWorks Educational License								
CHK'D	Instr								
APPV'D									
MFG									
Q.A			MATERIAL:			.:		DWIG NO.	
								bottomBoardAssembly	
\rightarrow		_							