NET SCANNING OPERATION PROCEDURES

- List
  - Select Programming Key (button 8)
  - Select Scan
  - Select List
  - Select Add (Net 01), Enter

NORM		**SCAN**
PORTS	SECUR	CFIG

USE ◄ ► TO SELECT ITEM


LIST	PRIORITY
CONFIG	

USE ◄ ► TO SELECT ITEM



NET SCANNING OPERATION PROCEDURES

- Priority
  - Select Priority
  - Select Priority Tx (01)
  - Select Enable Priority Rx (Yes)
  - Select Priority Rx Net (02)





NET SCANNING OPERATION PROCEDURES

- Configuration
  - Select Config (Enter)
  - Select Hang Time (3 seconds), Enter
  - Select Enable Hold Time (Yes)
  - Select Enable Hold Time (9sec)



