Bambu Lab P1S

HMS Error Code Quick Reference

Scan QR codes to access troubleshooting guides

Generated: 2/5/2026 by Antony Rinaldi



V1.3 / 3rd Edition

`


What is HMS

The Health Management System (HMS) is responsible for the collection & monitoring of the whole system status which includes:

1. Hardware connections and working status, for example, the hotend fan's speed is too low.
2. Mechanical status such as the belt tension;
3. Printing issues such as first layer scan failure and spaghetti.

Once an abnormal event occurs, HMS will notify the user what the problem is. Users can then take the proper action.

HMS Code Definition



1. Module ID

Module ID	Module Abbreviation	Module Name
03	MC	Motion Controller
05	AP	Main Board
07	AMS	Automated Material System
08	TH	Tool Head
0C	XCAM	Bambu Micro Lidar
10	Studio	Studio
11	APP	Handy
12	AMS Lite	Automated Material System Lite
18	AMS HT	Automated Material System Heater

2. Module No.

The number of modules. Usually it is 0, but it could be more than 0 if there are multiple modules connected to/in the printer, like the AMS.

3. Part ID

The id of part in specific module.

4. Part No.

The number of part in specific module.

5. Alert level

Level Definition
0000 Invalid alert
0001 Error (Printing task stopped, alert must be eliminated before starting a task)
0002 Warning (Printing task pause, alert must be eliminated before resuming the task)
0003 Info (Information only)

6. Error code ID

The ID of HMS alert algorithm.

HMS 0300-0100-0001-0003: The heatbed temperature is abnormal; the heater is over temperature.

X1 series/P1 series/ A1Mini/A1/H2 series/P2 series

Scan for article

HMS 0300-0100-0001-0006: The heatbed temperature is abnormal; the sensor may have an short circuit.

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-0100-0001-0007: The heatbed temperature is abnormal; the sensor may have an open circuit. circuit.

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-0100-0001-0008: An abnormality occurs during the heating process of the heatbed. The heating modules may be broken.

X1 series/P1 series/A1/ A1Mini

Scan for article

HMS 0300-0100-0001-000A: The heatbed temperature control is abnormal, the AC board may be broken.

X1 series/P1 series/ A1Mini/A1/H2 series

Scan for article

HMS 0300-0100-0003-0008: The temperature of the heated bed exceeds the limit and automatically adjusts to the limit temperature.

X1 series/P1 series/A1/ A1Mini

Scan for article

HMS 0300-0200-0001-0001: The nozzle temperature is abnormal, the heater may be short circuit.

X1 series/P1 series/A1 mini/A1

Scan for article

HMS 0300-0200-0001-0002: The nozzle temperature is abnormal,the heater may be open circuit.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0300-0200-0001-0003: The nozzle temperature is abnormal,the heater is over temperature.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0300-0200-0001-0006: The nozzle temperature is abnormal,the sensor may be short circuit.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0300-0200-0001-0007: The nozzle temperature is abnormal,the sensor may be open circuit.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0300-0300-0001-0001: The hotend cooling fan speed is too slow or stopped

X1 series/P1 series/A1/ A1 mini

Scan for article

HMS 0300-0300-0002-0002: The speed of hotend fan is slow.

X1 series/P1 series/A1/ A1 mini

Scan for article

HMS 0300-0400-0002-0001: The speed of part cooling fan if too slow or stopped.

Aliases: 0300-3100-0001-0001

X1 series/P1 series

Scan for article

HMS 0300-0600-0001-0001: Motor has an open-circuit. There may be a loose connection, or the motor may have failed.

Aliases: 0300-0700-0001-0001, 0300-0800-0001-0001

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-0600-0001-0002: Motor has a short-circuit. It may have failed.

Aliases: 0300-0700-0001-0002, 0300-0800-0001-0002

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-0600-0001-0003: The resistance of Motor is abnormal, the motor may have failed.

Aliases: 0300-0700-0001-0003, 0300-0800-0001-0003

X1 series/P1 series/A1 mini/H2 series

Scan for article

HMS 0300-0A00-0001-0001: The sensitivity of heatbed force sensor 1/2/3 is too high.

Aliases: 0300-0B00-0001-0001, 0300-0C00-0001-0001

X1 series/P1 series

Scan for article

HMS 0300-0A00-0001-0002: The sensitivity of heatbed force sensor 1/2/3 is low.

Aliases: 0300-0B00-0001-0002, 0300-0C00-0001-0002

X1 series/P1 series

Scan for article

HMS 0300-0A00-0001-0003: The sensitivity of heatbed force sensor 1/2/3 is too low.

Aliases: 0300-0B00-0001-0003, 0300-0C00-0001-0003

X1 series/P1 series

Scan for article

HMS 0300-0A00-0001-0004: An external disturbance was detected on force sensor 1. The heatbed plate may have touched something outside the heatbed.

Aliases: 0300-0B00-0001-0004, 0300-0C00-0001-0004

X1 series/P1 series

Scan for article

HMS 0300-0A00-0001-0005: Force Sensor detected unexpected continuous force. The heatbed may be stuck, or the analog front end may be broken.

Aliases: 0300-0B00-0001-0005, 0300-0C00-0001-0005

X1 series/P1 series

Scan for article

HMS 0300-0D00-0001-0003: The build plate is not placed properly.

Aliases: 0300-0D00-0001-0004, 0300-0D00-0001-0005, 0300-0D00-0001-0006, 0300-0D00-0001-0007, 0300-0D00-0001-0008, 0300-0D00-0001-0009, 0300-0D00-0001-000A, 0300-0D00-0002-0003, 0300-0D00-0002-0004, 0300-0D00-0002-0005, 0300-0D00-0002-0006, 0300-0D00-0002-0007, 0300-0D00-0002-0008, 0300-0D00-0002-0009, 0300-0D00-0002-000A

X1 series/P1 series/A1 mini/A1

Scan for article

HMS 0300-0D00-0001-000B: The Z axis motor seems to be stuck when moving. Please check if there is any foreign matter on the Z sliders or Z timing belt wheels.

X1 series/P1 series/A1/ A1 mini

Scan for article

HMS 0300-0D00-0002-0001: Heatbed homing abnormal: there may be a bulge on the heatbed or the nozzle tip may not be clean.

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-0F00-0001-0001: Abnormal accelerometer data detected. Please try to restart the printer.

X1 series/P1 series/A1

Scan for article

HMS 0300-1000-0002-0001: The 1st order mechanical resonance mode of X axis is low.

Aliases: 0300-1100-0002-0001

X1 series/P1 series/A1 mini/A1

Scan for article

HMS 0300-1000-0002-0002: The resonance frequency of the X axis differs greatly from last calibration. Please clean the carbon rod and rerun the machine calibration afterward

Aliases: 0300-1100-0002-0002

X1 series/P1 series/A1

Scan for article

HMS 0300-1200-0002-0001: The front cover of the toolhead fell off.

X1 series/P1 series

Scan for article

HMS 0300-1300-0001-0001: The current sensor of Motor is abnormal. This may be caused by a failure of the hardware sampling circuit.

Aliases: 0300-1400-0001-0001, 0300-1500-0001-0001

X1 series/P1 series

Scan for article

HMS 0300-1D00-0001-0001: The position sensor of extrusion motor is abnormal. The connection to sensor may be loose.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0300-4000-0002-0001: Data transmission over the serial port is abnormal; the software system may be faulty.

X1 series/P1 series/A1 mini

Scan for article

HMS 0300-4100-0001-0001: The system voltage is unstable; triggering the power failure protection function.

X1 series/P1 series/A1 mini/A1/H2 series/P2 series

Scan for article

HMS 0300-9100-0001-0006: The temperature of chamber Heater is abnormal. The sensor may have a short circuit.

Aliases: 0300-9200-0001-0006

X1 series/P1 series

Scan for article

HMS 0300-9100-0001-0007: The temperature of chamber Heater is abnormal. The sensor may have an open circuit.

Aliases: 0300-9200-0001-0007

X1 series/P1 series

Scan for article

HMS 0300-9400-0003-0001: Chamber cooling may be too slow. You can open the chamber to help cooling if the gas in chamber is non-toxic.

X1 series/P1 series

Scan for article

HMS 0300-A800-0001-0001: AMS power supply abnormality, possibly due to AMS damage or a short circuit in the AMS interface, or too many AMS connections. Please check if it is correctly connected.

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 0500-0100-0002-0001: The media pipeline is malfunctioning.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0100-0002-0002: USB camera is not connected.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0100-0002-0003: USB camera is malfunctioning.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0100-0003-0004: Not enough space in SD Card.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0100-0003-0005: Error in SD Card.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0100-0003-0006: Unformatted SD Card.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0200-0002-0001: Failed to connect internet, please check the network connection.

Aliases: 0500-0200-0002-0002, 0500-0200-0002-0003, 0500-0200-0002-0005

X1 series/P1 series/ A1Mini/H2 series/P2S

Scan for article

HMS 0500-0200-0002-0002: Failed to login device.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0200-0002-0004: Unauthorized user: please check your account information.

X1 series/P1 series/ A1Mini/H2 series/P2S

Scan for article

HMS 0500-0200-0002-0006: Liveview service is malfunctioning.

X1 series/P1 series/ A1Mini/H2 series

Scan for article

HMS 0500-0300-0001-0001: The MC module is malfunctioning. Please restart the device.

X1 series/P1 series/ A1Mini/A1

Scan for article

HMS 0500-0300-0001-0002: The toolhead is malfunctioning. Please restart the device.

X1 series/P1 series/ A1Mini/A1/H2 series/P2S

Scan for article

HMS 0500-0300-0001-0003: The AMS module is malfunctioning. Please restart the device.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0300-0001-0004: The Filament Buffer module is malfunctioning. Please restart the device.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0300-0001-000A: System state is abnormal. Please restore factory settings.

X1 series/P1 series/ A1Mini/P2S/H2 series

Scan for article

HMS 0500-0300-0001-000B: The screen is malfunctioning.

X1 series/P1 series/ A1Mini

Scan for article

HMS 0500-0300-0002-000C: Wireless hardware error: please turn off/on WiFi or restart the device.

X1 series/P1 series/ A1Mini/P2S

Scan for article

HMS 0500-0300-0002-000E: Some modules are incompatible with the printer's firmware version, which may affect use. Please go to the "Firmware" page to update after connected to the internet, or you may update offline according to wiki.

X1 series/P1 series/ A1Mini/A1/H2 series/P2S

Scan for article

Aliases: 0500-0500-0001-000E, 0500-0500-0001-000F, 0500-0500-0001-0011, 0500-0500-0001-0012, 0500-0400-0001-0046, 0500-0400-0001-0047, 0500-0400-0001-0048, 0500-0400-0001-0044, 0501-0400-0001-0044, 0502-0400-0001-0044, 0503-0400-0001-0044, 0500-0500-0001-0010, 0501-0500-0001-0010, 0502-0500-0001-0010, 0503-0500-0001-0010, 0580-0500-0001-0010, 0581-0500-0001-0010, 0582-0500-0001-0010, 0583-0500-0001-0010, 0584-0500-0001-0010, 0585-0500-0001-0010, 0586-0500-0001-0010, 0587-0500-0001-0010, 0580-0400-0001-0045, 0581-0400-0001-0045, 0582-0400-0001-0045, 0583-0400-0001-0045, 0584-0400-0001-0045, 0585-0400-0001-0045, 0586-0400-0001-0045, 0587-0400-0001-0045

HMS 0500-0300-0002-0055: User information has expired, please log in again.

X1 series/P1 series/ A1Mini/A1/H2 series

Scan for article

HMS 0500-0400-0001-0001: Failed to download print job. Please check your network connection.

X1 series/P1 series/H2 series

Scan for article

HMS 0500-0400-0001-0002: Failed to report print state. Please check your network connection.

X1 series/P1 series/P2S

Scan for article

HMS 0500-0400-0001-0003: The content of print file is unreadable. Please resend the print job.

X1 series/P1 series/H2 series/P2S

Scan for article

HMS 0500-0400-0001-0004: The print file is unauthorized.

X1 series/P1 series/P2S

Scan for article

HMS 0500-0400-0001-0006: Failed to resume previous print.

X1 series/P1 series/H2 series/P2S

Scan for article

HMS 0500-0400-0002-0007: The bed temperature exceeds the filament's vitrification temperature, which may cause a nozzle clog.

X1 series/P1 series

Scan for article

HMS 0500-0500-0001-0007: MQTT Command verification failed, please update Studio or Handy.

X1 series/P1 series/A1 mini/A1/H2 series

Scan for article

HMS 0500-0500-0001-0014: AMS certification failed. Please reconnect the cable or restart the printer.

Aliases: 0501-0500-0001-0014, 0502-0500-0001-0014, 0503-0500-0001-0014

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 0580-0500-0001-0017: AMS-HT certification failed. Please reconnect the cable or restart the printer.

Aliases: 0581-0500-0001-0017, 0582-0500-0001-0017, 0583-0500-0001-0017, 0584-0500-0001-0017, 0585-0500-0001-0017, 0586-0500-0001-0017, 0587-0500-0001-0017

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 0580-0500-0001-0017: AMS-HT certification failed. Please reconnect the cable or restart the printer.

Aliases: 0581-0500-0001-0017, 0582-0500-0001-0017, 0583-0500-0001-0017, 0584-0500-0001-0017, 0585-0500-0001-0017, 0586-0500-0001-0017, 0587-0500-0001-0017

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini

Scan for article

HMS 0700-0100-0001-0001: The AMS assist motor has slipped.The extrusion wheel may be worn down,or the filament may be too thin.

X1 series/P1 series

Scan for article

HMS 0700-0100-0001-0003: The AMS assist motor torque control is malfunctioning.The current sensor may be faulty.

X1 series/P1 series/P2S

Scan for article

HMS 0700-0100-0001-0004: The AMS assist motor speed control is malfunctioning.The speed sensor may be faulty.

X1 series/P1 series/P2S

Scan for article

HMS 0700-0100-0001-0005: AMS The current sensor of assist motor may be faulty.

Aliases: 0701-0100-0001-0005, 0702-0100-0001-0005, 0703-0100-0001-0005, 0704-0100-0001-0005, 0705-0100-0001-0005, 0706-0100-0001-0005, 0707-0100-0001-0005, 1800-0100-0001-0005, 1801-0100-0001-0005, 1802-0100-0001-0005, 1803-0100-0001-0005, 1804-0100-0001-0005, 1805-0100-0001-0005, 1806-0100-0001-0005, 1807-0100-0001-0005

H2 series/X1 series/P1 series/P2 series/A1/ A1Mini

Scan for article

HMS 0700-0100-0002-0002: The AMS assist motor is overloaded,The filament may be tangled or stuck.

Aliases: 0701-0100-0002-0002, 0702-0100-0002-0002, 0703-0100-0002-0002

X1 series/P1 series/P2S

Scan for article

HMS 0700-0100-0002-0007: AMS The assist motor encoder wires are not connected. The assist motor connector may have poor contact.

Aliases: 0701-0100-0002-0007, 0702-0100-0002-0007, 0703-0100-0002-0007, 1800-0100-0002-0007, 1801-0100-0002-0007, 1802-0100-0002-0007, 1803-0100-0002-0007, 1804-0100-0002-0007, 1805-0100-0002-0007, 1806-0100-0002-0007, 1807-0100-0002-0007

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 0700-0200-0001-0001: AMS filament speed and length error.The filament odometry may be faulty.

X1 series/P1 series/P2S

Scan for article

HMS 0700-1000-0001-0001: The AMS Slot motor has slipped.The

X1 series/P1 series

Scan for article

HMS 0700-1000-0001-0003: The AMS Slot motor torque control is malfunctioning.The current sensor may be faulty.

X1 series/P1 series

Scan for article

HMS 0700-1000-0002-0002: The AMS Slot motor is overloaded.The filament may be tangled or stuck.

X1 series/P1 series

Scan for article

HMS 0700-2000-0001-0081: Failed to read the filament information from AMS Slot X. The AMS main board may be malfunctioning.

X1 series/P1 series/P2S/ H2 series/A1/A1 mini/ AMS/AMS HT

Aliases: 0700-2100-0001-0081, 0700-2200-0001-0081, 0700-2300-0001-0081, 0701-2000-0001-0081, 0701-2100-0001-0081, 0701-2200-0001-0081, 0701-2300-0001-0081, 0702-2000-0001-0081, 0702-2100-0001-0081, 0702-2200-0001-0081, 0702-2300-0001-0081, 0703-2000-0001-0081, 0703-2100-0001-0081, 0703-2200-0001-0081, 0703-2300-0001-0081, 1800-2000-0001-0081, 1801-2000-0001-0081, 1802-2000-0001-0081, 1803-2000-0001-0081, 1804-2000-0001-0081, 1805-2000-0001-0081, 1806-2000-0001-0081, 1807-2000-0001-0081

Scan for article

HMS 0700-2000-0001-0083: Failed to read the filament information from AMS Slot X. The RFID tag may be damaged

X1 series/P1 series/P2S/ H2 series/A1/A1 mini/ AMS/AMS HT

Aliases: 0700-2100-0001-0083, 0700-2200-0001-0083, 0700-2300-0001-0083, 0701-2000-0001-0083, 0701-2100-0001-0083, 0701-2200-0001-0083, 0701-2300-0001-0083, 0702-2000-0001-0083, 0702-2100-0001-0083, 0702-2200-0001-0083, 0702-2300-0001-0083, 0703-2000-0001-0083, 0703-2100-0001-0083, 0703-2200-0001-0083, 0703-2300-0001-0083, 1800-2000-0001-0083, 1801-2000-0001-0083, 1802-2000-0001-0083, 1803-2000-0001-0083, 1804-2000-0001-0083, 1805-2000-0001-0083, 1806-2000-0001-0083, 1807-2000-0001-0083

Scan for article

HMS 0700-2000-0001-0084: Failed to read the filament information from AMS Slot X. The RFID tag may be damaged or positioned at the edge of the RFID detection device. Please remove 5cm filament and try again.

X1 series/P1 series/P2S/ H2 series/A1/A1 mini/ AMS/AMS HT

Aliases: 0700-2100-0001-0084, 0700-2200-0001-0084, 0700-2300-0001-0084, 0701-2000-0001-0084, 0701-2100-0001-0084, 0701-2200-0001-0084, 0701-2300-0001-0084, 0702-2000-0001-0084, 0702-2100-0001-0084, 0702-2200-0001-0084, 0702-2300-0001-0084, 0703-2000-0001-0084, 0703-2100-0001-0084, 0703-2200-0001-0084, 0703-2300-0001-0084, 1800-2000-0001-0084, 1801-2000-0001-0084, 1802-2000-0001-0084, 1803-2000-0001-0084, 1804-2000-0001-0084, 1805-2000-0001-0084, 1806-2000-0001-0084, 1807-2000-0001-0084

Scan for article

HMS 0700-2000-0001-0086: Failed to read the filament information from AMS Slot X. The RFID tag cannot rotate due to a jam during the filament loading or unloading. Please pull out the filament and try again.

H2 series/X1 series/P1 series/P2S

Scan for article

Aliases: 0700-2100-0001-0086, 0700-2200-0001-0086, 0700-2300-0001-0086, 0701-2000-0001-0086, 0701-2100-0001-0086, 0701-2200-0001-0086, 0701-2300-0001-0086, 0702-2000-0001-0086, 0702-2100-0001-0086, 0702-2200-0001-0086, 0702-2300-0001-0086

HMS 0700-2000-0002-0001: AMS Slot filament has run out.

X1 series/P1 series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0001, 0700-2200-0002-0001, 0700-2300-0002-0001, 0701-2000-0002-0001, 0701-2100-0002-0001, 0701-2200-0002-0001, 0701-2300-0002-0001, 0702-2000-0002-0001, 0702-2100-0002-0001, 0702-2200-0002-0001, 0702-2300-0002-0001, 0703-2000-0002-0001, 0703-2100-0002-0001, 0703-2200-0002-0001, 0703-2300-0002-0001, 0704-2000-0002-0001, 0704-2100-0002-0001, 0704-2200-0002-0001, 0704-2300-0002-0001, 0705-2000-0002-0001, 0705-2100-0002-0001, 0705-2200-0002-0001, 0705-2300-0002-0001, 0706-2000-0002-0001, 0706-2100-0002-0001, 0706-2200-0002-0001, 0706-2300-0002-0001, 0707-2000-0002-0001, 0707-2100-0002-0001, 0707-2200-0002-0001, 0707-2300-0002-0001, 1800-2000-0002-0001, 1800-2100-0002-0001, 1800-2200-0002-0001, 1800-2300-0002-0001, 1801-2000-0002-0001, 1801-2100-0002-0001, 1801-2200-0002-0001, 1801-2300-0002-0001, 1802-2000-0002-0001, 1802-2100-0002-0001, 1802-2200-0002-0001, 1802-2300-0002-0001, 1803-2000-0002-0001, 1803-2100-0002-0001, 1803-2200-0002-0001, 1803-2300-0002-0001, 1804-2000-0002-0001, 1804-2100-0002-0001, 1804-2200-0002-0001, 1804-2300-0002-0001, 1805-2000-0002-0001, 1805-2100-0002-0001, 1805-2200-0002-0001, 1805-2300-0002-0001, 1806-2000-0002-0001, 1806-2100-0002-0001, 1806-2200-0002-0001, 1806-2300-0002-0001, 1807-2000-0002-0001, 1807-2100-0002-0001, 1807-2200-0002-0001, 1807-2300-0002-0001

HMS 0700-2000-0002-0002: The AMS Slot is empty.

X1 series/P1 series/H2 series

Scan for article

Aliases: 0700-2100-0002-0002, 0700-2200-0002-0002, 0700-2300-0002-0002, 0701-2000-0002-0002, 0701-2100-0002-0002, 0701-2200-0002-0002, 0701-2300-0002-0002, 0702-2000-0002-0002, 0702-2100-0002-0002, 0702-2200-0002-0002, 0702-2300-0002-0002, 0703-2000-0002-0002, 0703-2100-0002-0002, 0703-2200-0002-0002, 0703-2300-0002-0002, 0704-2000-0002-0002, 0704-2100-0002-0002, 0704-2200-0002-0002, 0704-2300-0002-0002, 0705-2000-0002-0002, 0705-2100-0002-0002, 0705-2200-0002-0002, 0705-2300-0002-0002, 0706-2000-0002-0002, 0706-2100-0002-0002, 0706-2200-0002-0002, 0706-2300-0002-0002, 0707-2000-0002-0002, 0707-2100-0002-0002, 0707-2200-0002-0002, 0707-2300-0002-0002, 1800-2000-0002-0002, 1800-2100-0002-0002, 1800-2200-0002-0002, 1800-2300-0002-0002, 1801-2000-0002-0002, 1801-2100-0002-0002, 1801-2200-0002-0002, 1801-2300-0002-0002, 1802-2000-0002-0002, 1802-2100-0002-0002, 1802-2200-0002-0002, 1802-2300-0002-0002, 1803-2000-0002-0002, 1803-2100-0002-0002, 1803-2200-0002-0002, 1803-2300-0002-0002, 1804-2000-0002-0002, 1804-2100-0002-0002, 1804-2200-0002-0002, 1804-2300-0002-0002, 1805-2000-0002-0002, 1805-2100-0002-0002, 1805-2200-0002-0002, 1805-2300-0002-0002, 1806-2000-0002-0002, 1806-2100-0002-0002, 1806-2200-0002-0002, 1806-2300-0002-0002, 1807-2000-0002-0002, 1807-2100-0002-0002, 1807-2200-0002-0002, 1807-2300-0002-0002

HMS 0700-2000-0002-0003: The AMS Slot filament may be broken in AMS.

X1 series/P1 series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0003, 0700-2200-0002-0003, 0700-2300-0002-0003, 0701-2000-0002-0003, 0701-2100-0002-0003, 0701-2200-0002-0003, 0701-2300-0002-0003, 0702-2000-0002-0003, 0702-2100-0002-0003, 0702-2200-0002-0003, 0702-2300-0002-0003, 0703-2000-0002-0003, 0703-2100-0002-0003, 0703-2200-0002-0003, 0703-2300-0002-0003, 0704-2000-0002-0003, 0704-2100-0002-0003, 0704-2200-0002-0003, 0704-2300-0002-0003, 0705-2000-0002-0003, 0705-2100-0002-0003, 0705-2200-0002-0003, 0705-2300-0002-0003, 0706-2000-0002-0003, 0706-2100-0002-0003, 0706-2200-0002-0003, 0706-2300-0002-0003, 0707-2000-0002-0003, 0707-2100-0002-0003, 0707-2200-0002-0003, 0707-2300-0002-0003, 1800-2000-0002-0003, 1800-2100-0002-0003, 1800-2200-0002-0003, 1800-2300-0002-0003, 1801-2000-0002-0003, 1801-2100-0002-0003, 1801-2200-0002-0003, 1801-2300-0002-0003, 1802-2000-0002-0003, 1802-2100-0002-0003, 1802-2200-0002-0003, 1802-2300-0002-0003, 1803-2000-0002-0003, 1803-2100-0002-0003, 1803-2200-0002-0003, 1803-2300-0002-0003, 1804-2000-0002-0003, 1804-2100-0002-0003, 1804-2200-0002-0003, 1804-2300-0002-0003, 1805-2000-0002-0003, 1805-2100-0002-0003, 1805-2200-0002-0003, 1805-2300-0002-0003

HMS 0700-2000-0002-0004: The AMS Slot filament may be broken in the toolhead.

X1 series/P1 series/H2 series

Scan for article

Aliases: 0700-2100-0002-0004, 0700-2200-0002-0004, 0700-2300-0002-0004, 0701-2000-0002-0004, 0701-2100-0002-0004, 0701-2200-0002-0004, 0701-2300-0002-0004, 0702-2000-0002-0004, 0702-2100-0002-0004, 0702-2200-0002-0004, 0702-2300-0002-0004, 0703-2000-0002-0004, 0703-2100-0002-0004, 0703-2200-0002-0004, 0703-2300-0002-0004, 0704-2000-0002-0004, 0704-2100-0002-0004, 0704-2200-0002-0004, 0704-2300-0002-0004, 0705-2000-0002-0004, 0705-2100-0002-0004, 0705-2200-0002-0004, 0705-2300-0002-0004, 0706-2000-0002-0004, 0706-2100-0002-0004, 0706-2200-0002-0004, 0706-2300-0002-0004, 0707-2000-0002-0004, 0707-2100-0002-0004, 0707-2200-0002-0004, 0707-2300-0002-0004, 1800-2000-0002-0004, 1800-2100-0002-0004, 1800-2200-0002-0004, 1800-2300-0002-0004, 1801-2000-0002-0004, 1801-2100-0002-0004, 1801-2200-0002-0004, 1801-2300-0002-0004, 1802-2000-0002-0004, 1802-2100-0002-0004, 1802-2200-0002-0004, 1802-2300-0002-0004, 1803-2000-0002-0004, 1803-2100-0002-0004, 1803-2200-0002-0004, 1803-2300-0002-0004, 1804-2000-0002-0004, 1804-2100-0002-0004, 1804-2200-0002-0004, 1804-2300-0002-0004, 1805-2000-0002-0004, 1805-2100-0002-0004, 1805-2200-0002-0004, 1805-2300-0002-0004, 1806-2000-0002-0004, 1806-2100-0002-0004, 1806-2200-0002-0004, 1806-2300-0002-0004, 1807-2000-0002-0004, 1807-2100-0002-0004, 1807-2200-0002-0004, 1807-2300-0002-0004

HMS 0700-2000-0002-0005: AMS Slot filament has run out, and purging the old filament went abnormally; please check whether the filament is stuck in the tool head.

X1 series/P1 series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0005, 0700-2200-0002-0005, 0700-2300-0002-0005, 0701-2000-0002-0005, 0701-2100-0002-0005, 0701-2200-0002-0005, 0701-2300-0002-0005, 0702-2000-0002-0005, 0702-2100-0002-0005, 0702-2200-0002-0005, 0702-2300-0002-0005, 0703-2000-0002-0005, 0703-2100-0002-0005, 0703-2200-0002-0005, 0703-2300-0002-0005, 0704-2000-0002-0005, 0704-2100-0002-0005, 0704-2200-0002-0005, 0704-2300-0002-0005, 0705-2000-0002-0005, 0705-2100-0002-0005, 0705-2200-0002-0005, 0705-2300-0002-0005, 0706-2000-0002-0005, 0706-2100-0002-0005, 0706-2200-0002-0005, 0706-2300-0002-0005, 0707-2000-0002-0005, 0707-2100-0002-0005, 0707-2200-0002-0005, 0707-2300-0002-0005, 1800-2000-0002-0005, 1800-2100-0002-0005, 1800-2200-0002-0005, 1800-2300-0002-0005, 1801-2000-0002-0005, 1801-2100-0002-0005, 1801-2200-0002-0005, 1801-2300-0002-0005, 1802-2000-0002-0005, 1802-2100-0002-0005, 1802-2200-0002-0005, 1802-2300-0002-0005, 1803-2000-0002-0005, 1803-2100-0002-0005, 1803-2200-0002-0005, 1803-2300-0002-0005, 1804-2000-0002-0005, 1804-2100-0002-0005, 1804-2200-0002-0005, 1804-2300-0002-0005, 1805-2000-0002-0005, 1805-2100-0002-0005, 1805-2200-0002-0005, 1805-2300-0002-0005, 1806-2000-0002-0005, 1806-2100-0002-0005, 1806-2200-0002-0005, 1806-2300-0002-0005, 1807-2000-0002-0005, 1807-2100-0002-0005, 1807-2200-0002-0005, 1807-2300-0002-0005

HMS 0700-2000-0002-0006: PTFE tube detached during the feeding process. Please check if the PTFE tube is connected from AMS to extruder.

X1 series/P1 series/H2 series

Scan for article

Aliases: 0700-2100-0002-0006, 0700-2200-0002-0006, 0700-2300-0002-0006, 0701-2000-0002-0006, 0701-2100-0002-0006, 0701-2200-0002-0006, 0701-2300-0002-0006, 0702-2000-0002-0006, 0702-2100-0002-0006, 0702-2200-0002-0006, 0702-2300-0002-0006, 0703-2000-0002-0006, 0703-2100-0002-0006, 0703-2200-0002-0006, 0703-2300-0002-0006, 0704-2000-0002-0006, 0704-2100-0002-0006, 0704-2200-0002-0006, 0704-2300-0002-0006, 0705-2000-0002-0006, 0705-2100-0002-0006, 0705-2200-0002-0006, 0705-2300-0002-0006, 0706-2000-0002-0006, 0706-2100-0002-0006, 0706-2200-0002-0006, 0706-2300-0002-0006, 0707-2000-0002-0006, 0707-2100-0002-0006, 0707-2200-0002-0006, 0707-2300-0002-0006, 1800-2000-0002-0006, 1800-2100-0002-0006, 1800-2200-0002-0006, 1800-2300-0002-0006, 1801-2000-0002-0006, 1801-2100-0002-0006, 1801-2200-0002-0006, 1801-2300-0002-0006, 1802-2000-0002-0006, 1802-2100-0002-0006, 1802-2200-0002-0006, 1802-2300-0002-0006, 1803-2000-0002-0006, 1803-2100-0002-0006, 1803-2200-0002-0006, 1803-2300-0002-0006, 1804-2000-0002-0006, 1804-2100-0002-0006, 1804-2200-0002-0006, 1804-2300-0002-0006, 1805-2000-0002-0006, 1805-2100-0002-0006, 1805-2200-0002-0006, 1805-2300-0002-0006, 1806-2000-0002-0006, 1806-2100-0002-0006, 1806-2200-0002-0006, 1806-2300-0002-0006, 1807-2000-0002-0006, 1807-2100-0002-0006, 1807-2200-0002-0006, 1807-2300-0002-0006

HMS 0700-2000-0002-0010: AMS Slot feeds filament out of AMS timeout.

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini

Scan for article

Aliases: 0700-2100-0002-0010, 0700-2200-0002-0010, 0700-2300-0002-0010, 0701-2000-0002-0010, 0701-2100-0002-0010, 0701-2200-0002-0010, 0701-2300-0002-0010, 0702-2000-0002-0010, 0702-2100-0002-0010, 0702-2200-0002-0010, 0702-2300-0002-0010, 0703-2000-0002-0010, 0703-2100-0002-0010, 0703-2200-0002-0010, 0703-2300-0002-0010, 1800-2000-0002-0010, 1801-2000-0002-0010, 1802-2000-0002-0010, 1803-2000-0002-0010, 1804-2000-0002-0010, 1805-2000-0002-0010, 1806-2000-0002-0010, 1807-2000-0002-0010

HMS 0700-2000-0002-0011: AMS Slot pulls filament back to AMS timeout.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0011, 0700-2200-0002-0011, 0700-2300-0002-0011, 0701-2000-0002-0011, 0701-2100-0002-0011, 0701-2200-0002-0011, 0701-2300-0002-0011, 0702-2000-0002-0011, 0702-2100-0002-0011, 0702-2200-0002-0011, 0702-2300-0002-0011, 0703-2000-0002-0011, 0703-2100-0002-0011, 0703-2200-0002-0011, 0703-2300-0002-0011, 0704-2000-0002-0011, 0704-2100-0002-0011, 0704-2200-0002-0011, 0704-2300-0002-0011, 0705-2000-0002-0011, 0705-2100-0002-0011, 0705-2200-0002-0011, 0705-2300-0002-0011, 0706-2000-0002-0011, 0706-2100-0002-0011, 0706-2200-0002-0011, 0706-2300-0002-0011, 0707-2000-0002-0011, 0707-2100-0002-0011, 0707-2200-0002-0011, 0707-2300-0002-0011, 1800-2000-0002-0011, 1800-2100-0002-0011, 1800-2200-0002-0011, 1800-2300-0002-0011, 1801-2000-0002-0011, 1801-2100-0002-0011, 1801-2200-0002-0011, 1801-2300-0002-0011, 1802-2000-0002-0011, 1802-2100-0002-0011, 1802-2200-0002-0011, 1802-2300-0002-0011, 1803-2000-0002-0011, 1803-2100-0002-0011, 1803-2200-0002-0011, 1803-2300-0002-0011, 1804-2000-0002-0011, 1804-2100-0002-0011, 1804-2200-0002-0011, 1804-2300-0002-0011, 1805-2000-0002-0011, 1805-2100-0002-0011, 1805-2200-0002-0011, 1805-2300-0002-0011, 1806-2000-0002-0011, 1806-2100-0002-0011, 1806-2200-0002-0011, 1806-2300-0002-0011, 1807-2000-0002-0011, 1807-2100-0002-0011, 1807-2200-0002-0011, 1807-2300-0002-0011

HMS 0700-2000-0002-0012: AMS Slot feeder unit motor is stalled, cannot rotate the spool.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0012, 0700-2200-0002-0012, 0700-2300-0002-0012, 0701-2000-0002-0012, 0701-2100-0002-0012, 0701-2200-0002-0012, 0701-2300-0002-0012, 0702-2000-0002-0012, 0702-2100-0002-0012, 0702-2200-0002-0012, 0702-2300-0002-0012, 0703-2000-0002-0012, 0703-2100-0002-0012, 0703-2200-0002-0012, 0703-2300-0002-0012, 0704-2000-0002-0012, 0704-2100-0002-0012, 0704-2200-0002-0012, 0704-2300-0002-0012, 0705-2000-0002-0012, 0705-2100-0002-0012, 0705-2200-0002-0012, 0705-2300-0002-0012, 0706-2000-0002-0012, 0706-2100-0002-0012, 0706-2200-0002-0012, 0706-2300-0002-0012, 0707-2000-0002-0012, 0707-2100-0002-0012, 0707-2200-0002-0012, 0707-2300-0002-0012, 1800-2000-0002-0012, 1800-2100-0002-0012, 1800-2200-0002-0012, 1800-2300-0002-0012, 1801-2000-0002-0012, 1801-2100-0002-0012, 1801-2200-0002-0012, 1801-2300-0002-0012, 1802-2000-0002-0012, 1802-2100-0002-0012, 1802-2200-0002-0012, 1802-2300-0002-0012, 1803-2000-0002-0012, 1803-2100-0002-0012, 1803-2200-0002-0012, 1803-2300-0002-0012, 1804-2000-0002-0012, 1804-2100-0002-0012, 1804-2200-0002-0012, 1804-2300-0002-0012, 1805-2000-0002-0012, 1805-2100-0002-0012, 1805-2200-0002-0012, 1805-2300-0002-0012, 1806-2000-0002-0012, 1806-2100-0002-0012, 1806-2200-0002-0012, 1806-2300-0002-0012, 1807-2000-0002-0012, 1807-2100-0002-0012, 1807-2200-0002-0012, 1807-2300-0002-0012

HMS 0700-2000-0002-0013: AMS Slot feeder unit motor has no signal, which may be due to poor contact in the motor connector or a motor fault.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0013, 0700-2200-0002-0013, 0700-2300-0002-0013, 0701-2000-0002-0013, 0701-2100-0002-0013, 0701-2200-0002-0013, 0701-2300-0002-0013, 0702-2000-0002-0013, 0702-2100-0002-0013, 0702-2200-0002-0013, 0702-2300-0002-0013, 0703-2000-0002-0013, 0703-2100-0002-0013, 0703-2200-0002-0013, 0703-2300-0002-0013, 0704-2000-0002-0013, 0704-2100-0002-0013, 0704-2200-0002-0013, 0704-2300-0002-0013, 0705-2000-0002-0013, 0705-2100-0002-0013, 0705-2200-0002-0013, 0705-2300-0002-0013, 0706-2000-0002-0013, 0706-2100-0002-0013, 0706-2200-0002-0013, 0706-2300-0002-0013, 0707-2000-0002-0013, 0707-2100-0002-0013, 0707-2200-0002-0013, 0707-2300-0002-0013, 1800-2000-0002-0013, 1800-2100-0002-0013, 1800-2200-0002-0013, 1800-2300-0002-0013, 1801-2000-0002-0013, 1801-2100-0002-0013, 1801-2200-0002-0013, 1801-2300-0002-0013, 1802-2000-0002-0013, 1802-2100-0002-0013, 1802-2200-0002-0013, 1802-2300-0002-0013, 1803-2000-0002-0013, 1803-2100-0002-0013, 1803-2200-0002-0013, 1803-2300-0002-0013, 1804-2000-0002-0013, 1804-2100-0002-0013, 1804-2200-0002-0013, 1804-2300-0002-0013, 1805-2000-0002-0013, 1805-2100-0002-0013, 1805-2200-0002-0013, 1805-2300-0002-0013, 1806-2000-0002-0013, 1806-2100-0002-0013, 1806-2200-0002-0013, 1806-2300-0002-0013, 1807-2000-0002-0013, 1807-2100-0002-0013, 1807-2200-0002-0013, 1807-2300-0002-0013

HMS 0700-2000-0002-0014: AMS Slot odometer no signal - possible poor odometer connector contact or odometer failure.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0014, 0700-2200-0002-0014, 0700-2300-0002-0014, 0701-2000-0002-0014, 0701-2100-0002-0014, 0701-2200-0002-0014, 0701-2300-0002-0014, 0702-2000-0002-0014, 0702-2100-0002-0014, 0702-2200-0002-0014, 0702-2300-0002-0014, 0703-2000-0002-0014, 0703-2100-0002-0014, 0703-2200-0002-0014, 0703-2300-0002-0014, 0704-2000-0002-0014, 0704-2100-0002-0014, 0704-2200-0002-0014, 0704-2300-0002-0014, 0705-2000-0002-0014, 0705-2100-0002-0014, 0705-2200-0002-0014, 0705-2300-0002-0014, 0706-2000-0002-0014, 0706-2100-0002-0014, 0706-2200-0002-0014, 0706-2300-0002-0014, 0707-2000-0002-0014, 0707-2100-0002-0014, 0707-2200-0002-0014, 0707-2300-0002-0014, 1800-2000-0002-0014, 1800-2100-0002-0014, 1800-2200-0002-0014, 1800-2300-0002-0014, 1801-2000-0002-0014, 1801-2100-0002-0014, 1801-2200-0002-0014, 1801-2300-0002-0014, 1802-2000-0002-0014, 1802-2100-0002-0014, 1802-2200-0002-0014, 1802-2300-0002-0014, 1803-2000-0002-0014, 1803-2100-0002-0014, 1803-2200-0002-0014, 1803-2300-0002-0014, 1804-2000-0002-0014, 1804-2100-0002-0014, 1804-2200-0002-0014, 1804-2300-0002-0014, 1805-2000-0002-0014, 1805-2100-0002-0014, 1805-2200-0002-0014, 1805-2300-0002-0014, 1806-2000-0002-0014, 1806-2100-0002-0014, 1806-2200-0002-0014, 1806-2300-0002-0014, 1807-2000-0002-0014, 1807-2100-0002-0014, 1807-2200-0002-0014, 1807-2300-0002-0014

HMS 0700-2000-0002-0015: AMS Slot filament status is abnormal, which may be due to a filament breakage inside the AMS.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0015, 0700-2200-0002-0015, 0700-2300-0002-0015, 0701-2000-0002-0015, 0701-2100-0002-0015, 0701-2200-0002-0015, 0701-2300-0002-0015, 0702-2000-0002-0015, 0702-2100-0002-0015, 0702-2200-0002-0015, 0702-2300-0002-0015, 0703-2000-0002-0015, 0703-2100-0002-0015, 0703-2200-0002-0015, 0703-2300-0002-0015, 0704-2000-0002-0015, 0704-2100-0002-0015, 0704-2200-0002-0015, 0704-2300-0002-0015, 0705-2000-0002-0015, 0705-2100-0002-0015, 0705-2200-0002-0015, 0705-2300-0002-0015, 0706-2000-0002-0015, 0706-2100-0002-0015, 0706-2200-0002-0015, 0706-2300-0002-0015, 0707-2000-0002-0015, 0707-2100-0002-0015, 0707-2200-0002-0015, 0707-2300-0002-0015, 1800-2000-0002-0015, 1800-2100-0002-0015, 1800-2200-0002-0015, 1800-2300-0002-0015, 1801-2000-0002-0015, 1801-2100-0002-0015, 1801-2200-0002-0015, 1801-2300-0002-0015, 1802-2000-0002-0015, 1802-2100-0002-0015, 1802-2200-0002-0015, 1802-2300-0002-0015, 1803-2000-0002-0015, 1803-2100-0002-0015, 1803-2200-0002-0015, 1803-2300-0002-0015, 1804-2000-0002-0015, 1804-2100-0002-0015, 1804-2200-0002-0015, 1804-2300-0002-0015, 1805-2000-0002-0015, 1805-2100-0002-0015, 1805-2200-0002-0015, 1805-2300-0002-0015, 1806-2000-0002-0015, 1806-2100-0002-0015, 1806-2200-0002-0015, 1806-2300-0002-0015, 1807-2000-0002-0015, 1807-2100-0002-0015, 1807-2200-0002-0015, 1807-2300-0002-0015

HMS 0700-2000-0002-0016: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube between AMS and the printer.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0016, 0700-2200-0002-0016, 0700-2300-0002-0016, 0701-2000-0002-0016, 0701-2100-0002-0016, 0701-2200-0002-0016, 0701-2300-0002-0016, 0702-2000-0002-0016, 0702-2100-0002-0016, 0702-2200-0002-0016, 0702-2300-0002-0016, 0703-2000-0002-0016, 0703-2100-0002-0016, 0703-2200-0002-0016, 0703-2300-0002-0016, 0704-2000-0002-0016, 0704-2100-0002-0016, 0704-2200-0002-0016, 0704-2300-0002-0016, 0705-2000-0002-0016, 0705-2100-0002-0016, 0705-2200-0002-0016, 0705-2300-0002-0016, 0706-2000-0002-0016, 0706-2100-0002-0016, 0706-2200-0002-0016, 0706-2300-0002-0016, 0707-2000-0002-0016, 0707-2100-0002-0016, 0707-2200-0002-0016, 0707-2300-0002-0016, 1800-2000-0002-0016, 1800-2100-0002-0016, 1800-2200-0002-0016, 1800-2300-0002-0016, 1801-2000-0002-0016, 1801-2100-0002-0016, 1801-2200-0002-0016, 1801-2300-0002-0016, 1802-2000-0002-0016, 1802-2100-0002-0016, 1802-2200-0002-0016, 1802-2300-0002-0016, 1803-2000-0002-0016, 1803-2100-0002-0016, 1803-2200-0002-0016, 1803-2300-0002-0016, 1804-2000-0002-0016, 1804-2100-0002-0016, 1804-2200-0002-0016, 1804-2300-0002-0016, 1805-2000-0002-0016, 1805-2100-0002-0016, 1805-2200-0002-0016, 1805-2300-0002-0016, 1806-2000-0002-0016, 1806-2100-0002-0016, 1806-2200-0002-0016, 1806-2300-0002-0016, 1807-2000-0002-0016, 1807-2100-0002-0016, 1807-2200-0002-0016, 1807-2300-0002-0016

HMS 0700-2000-0002-0017: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube between AMS and the printer.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0017, 0700-2200-0002-0017, 0700-2300-0002-0017, 0701-2000-0002-0017, 0701-2100-0002-0017, 0701-2200-0002-0017, 0701-2300-0002-0017, 0702-2000-0002-0017, 0702-2100-0002-0017, 0702-2200-0002-0017, 0702-2300-0002-0017, 0703-2000-0002-0017, 0703-2100-0002-0017, 0703-2200-0002-0017, 0703-2300-0002-0017, 0704-2000-0002-0017, 0704-2100-0002-0017, 0704-2200-0002-0017, 0704-2300-0002-0017, 0705-2000-0002-0017, 0705-2100-0002-0017, 0705-2200-0002-0017, 0705-2300-0002-0017, 0706-2000-0002-0017, 0706-2100-0002-0017, 0706-2200-0002-0017, 0706-2300-0002-0017, 0707-2000-0002-0017, 0707-2100-0002-0017, 0707-2200-0002-0017, 0707-2300-0002-0017, 1800-2000-0002-0017, 1800-2100-0002-0017, 1800-2200-0002-0017, 1800-2300-0002-0017, 1801-2000-0002-0017, 1801-2100-0002-0017, 1801-2200-0002-0017, 1801-2300-0002-0017, 1802-2000-0002-0017, 1802-2100-0002-0017, 1802-2200-0002-0017, 1802-2300-0002-0017, 1803-2000-0002-0017, 1803-2100-0002-0017, 1803-2200-0002-0017, 1803-2300-0002-0017, 1804-2000-0002-0017, 1804-2100-0002-0017, 1804-2200-0002-0017, 1804-2300-0002-0017, 1805-2000-0002-0017, 1805-2100-0002-0017, 1805-2200-0002-0017, 1805-2300-0002-0017, 1806-2000-0002-0017, 1806-2100-0002-0017, 1806-2200-0002-0017, 1806-2300-0002-0017, 1807-2000-0002-0017, 1807-2100-0002-0017, 1807-2200-0002-0017, 1807-2300-0002-0017

HMS 0700-2000-0002-0018: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube near AMS.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0018, 0700-2200-0002-0018, 0700-2300-0002-0018, 0701-2000-0002-0018, 0701-2100-0002-0018, 0701-2200-0002-0018, 0701-2300-0002-0018, 0702-2000-0002-0018, 0702-2100-0002-0018, 0702-2200-0002-0018, 0702-2300-0002-0018, 0703-2000-0002-0018, 0703-2100-0002-0018, 0703-2200-0002-0018, 0703-2300-0002-0018, 0704-2000-0002-0018, 0704-2100-0002-0018, 0704-2200-0002-0018, 0704-2300-0002-0018, 0705-2000-0002-0018, 0705-2100-0002-0018, 0705-2200-0002-0018, 0705-2300-0002-0018, 0706-2000-0002-0018, 0706-2100-0002-0018, 0706-2200-0002-0018, 0706-2300-0002-0018, 0707-2000-0002-0018, 0707-2100-0002-0018, 0707-2200-0002-0018, 0707-2300-0002-0018, 1800-2000-0002-0018, 1800-2100-0002-0018, 1800-2200-0002-0018, 1800-2300-0002-0018, 1801-2000-0002-0018, 1801-2100-0002-0018, 1801-2200-0002-0018, 1801-2300-0002-0018, 1802-2000-0002-0018, 1802-2100-0002-0018, 1802-2200-0002-0018, 1802-2300-0002-0018, 1803-2000-0002-0018, 1803-2100-0002-0018, 1803-2200-0002-0018, 1803-2300-0002-0018, 1804-2000-0002-0018, 1804-2100-0002-0018, 1804-2200-0002-0018, 1804-2300-0002-0018, 1805-2000-0002-0018, 1805-2100-0002-0018, 1805-2200-0002-0018, 1805-2300-0002-0018, 1806-2000-0002-0018, 1806-2100-0002-0018, 1806-2200-0002-0018, 1806-2300-0002-0018, 1807-2000-0002-0018, 1807-2100-0002-0018, 1807-2200-0002-0018, 1807-2300-0002-0018

HMS 0700-2000-0002-0019: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube between AMS and the filament buffer.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0019, 0700-2200-0002-0019, 0700-2300-0002-0019, 0701-2000-0002-0019, 0701-2100-0002-0019, 0701-2200-0002-0019, 0701-2300-0002-0019, 0702-2000-0002-0019, 0702-2100-0002-0019, 0702-2200-0002-0019, 0702-2300-0002-0019, 0703-2000-0002-0019, 0703-2100-0002-0019, 0703-2200-0002-0019, 0703-2300-0002-0019, 0704-2000-0002-0019, 0704-2100-0002-0019, 0704-2200-0002-0019, 0704-2300-0002-0019, 0705-2000-0002-0019, 0705-2100-0002-0019, 0705-2200-0002-0019, 0705-2300-0002-0019, 0706-2000-0002-0019, 0706-2100-0002-0019, 0706-2200-0002-0019, 0706-2300-0002-0019, 0707-2000-0002-0019, 0707-2100-0002-0019, 0707-2200-0002-0019, 0707-2300-0002-0019, 1800-2000-0002-0019, 1800-2100-0002-0019, 1800-2200-0002-0019, 1800-2300-0002-0019, 1801-2000-0002-0019, 1801-2100-0002-0019, 1801-2200-0002-0019, 1801-2300-0002-0019, 1802-2000-0002-0019, 1802-2100-0002-0019, 1802-2200-0002-0019, 1802-2300-0002-0019, 1803-2000-0002-0019, 1803-2100-0002-0019, 1803-2200-0002-0019, 1803-2300-0002-0019, 1804-2000-0002-0019, 1804-2100-0002-0019, 1804-2200-0002-0019, 1804-2300-0002-0019, 1805-2000-0002-0019, 1805-2100-0002-0019, 1805-2200-0002-0019, 1805-2300-0002-0019, 1806-2000-0002-0019, 1806-2100-0002-0019, 1806-2200-0002-0019, 1806-2300-0002-0019, 1807-2000-0002-0019, 1807-2100-0002-0019, 1807-2200-0002-0019, 1807-2300-0002-0019

HMS 0700-2000-0002-0021: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube between the filament buffer and the toolhead.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0021, 0700-2200-0002-0021, 0700-2300-0002-0021, 0701-2000-0002-0021, 0701-2100-0002-0021, 0701-2200-0002-0021, 0701-2300-0002-0021, 0702-2000-0002-0021, 0702-2100-0002-0021, 0702-2200-0002-0021, 0702-2300-0002-0021, 0703-2000-0002-0021, 0703-2100-0002-0021, 0703-2200-0002-0021, 0703-2300-0002-0021, 0704-2000-0002-0021, 0704-2100-0002-0021, 0704-2200-0002-0021, 0704-2300-0002-0021, 0705-2000-0002-0021, 0705-2100-0002-0021, 0705-2200-0002-0021, 0705-2300-0002-0021, 0706-2000-0002-0021, 0706-2100-0002-0021, 0706-2200-0002-0021, 0706-2300-0002-0021, 0707-2000-0002-0021, 0707-2100-0002-0021, 0707-2200-0002-0021, 0707-2300-0002-0021, 1800-2000-0002-0021, 1800-2100-0002-0021, 1800-2200-0002-0021, 1800-2300-0002-0021, 1801-2000-0002-0021, 1801-2100-0002-0021, 1801-2200-0002-0021, 1801-2300-0002-0021, 1802-2000-0002-0021, 1802-2100-0002-0021, 1802-2200-0002-0021, 1802-2300-0002-0021, 1803-2000-0002-0021, 1803-2100-0002-0021, 1803-2200-0002-0021, 1803-2300-0002-0021, 1804-2000-0002-0021, 1804-2100-0002-0021, 1804-2200-0002-0021, 1804-2300-0002-0021, 1805-2000-0002-0021, 1805-2100-0002-0021, 1805-2200-0002-0021, 1805-2300-0002-0021, 1806-2000-0002-0021, 1806-2100-0002-0021, 1806-2200-0002-0021, 1806-2300-0002-0021, 1807-2000-0002-0021, 1807-2100-0002-0021, 1807-2200-0002-0021, 1807-2300-0002-0021

HMS 0700-2000-0002-0022: AMS Slot assist motor is stalledÿdue to excessive resistance in the tube near the toolhead.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0022, 0700-2200-0002-0022, 0700-2300-0002-0022, 0701-2000-0002-0022, 0701-2100-0002-0022, 0701-2200-0002-0022, 0701-2300-0002-0022, 0702-2000-0002-0022, 0702-2100-0002-0022, 0702-2200-0002-0022, 0702-2300-0002-0022, 0703-2000-0002-0022, 0703-2100-0002-0022, 0703-2200-0002-0022, 0703-2300-0002-0022, 0704-2000-0002-0022, 0704-2100-0002-0022, 0704-2200-0002-0022, 0704-2300-0002-0022, 0705-2000-0002-0022, 0705-2100-0002-0022, 0705-2200-0002-0022, 0705-2300-0002-0022, 0706-2000-0002-0022, 0706-2100-0002-0022, 0706-2200-0002-0022, 0706-2300-0002-0022, 0707-2000-0002-0022, 0707-2100-0002-0022, 0707-2200-0002-0022, 0707-2300-0002-0022, 1800-2000-0002-0022, 1800-2100-0002-0022, 1800-2200-0002-0022, 1800-2300-0002-0022, 1801-2000-0002-0022, 1801-2100-0002-0022, 1801-2200-0002-0022, 1801-2300-0002-0022, 1802-2000-0002-0022, 1802-2100-0002-0022, 1802-2200-0002-0022, 1802-2300-0002-0022, 1803-2000-0002-0022, 1803-2100-0002-0022, 1803-2200-0002-0022, 1803-2300-0002-0022, 1804-2000-0002-0022, 1804-2100-0002-0022, 1804-2200-0002-0022, 1804-2300-0002-0022, 1805-2000-0002-0022, 1805-2100-0002-0022, 1805-2200-0002-0022, 1805-2300-0002-0022, 1806-2000-0002-0022, 1806-2100-0002-0022, 1806-2200-0002-0022, 1806-2300-0002-0022, 1807-2000-0002-0022, 1807-2100-0002-0022, 1807-2200-0002-0022, 1807-2300-0002-0022

HMS 0700-2000-0002-0023: AMS Slot the tube inside the AMS is broken, or feed-out hall sensor is faulty and cannot detect the filament.

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

Aliases: 0700-2100-0002-0023, 0700-2200-0002-0023, 0700-2300-0002-0023, 0701-2000-0002-0023, 0701-2100-0002-0023, 0701-2200-0002-0023, 0701-2300-0002-0023, 0702-2000-0002-0023, 0702-2100-0002-0023, 0702-2200-0002-0023, 0702-2300-0002-0023, 0703-2000-0002-0023, 0703-2100-0002-0023, 0703-2200-0002-0023, 0703-2300-0002-0023, 1800-2000-0002-0023, 1801-2000-0002-0023, 1802-2000-0002-0023, 1803-2000-0002-0023, 1804-2000-0002-0023, 1805-2000-0002-0023, 1806-2000-0002-0023, 1807-2000-0002-0023

HMS 0700-2000-0002-0024: AMS Slot assist motor is stalledÿfailed to rotate the filament spool when pulling filament back to AMS.

X1 Series/P1 Series/H2 series

Scan for article

Aliases: 0700-2100-0002-0024, 0700-2200-0002-0024, 0700-2300-0002-0024, 0701-2000-0002-0024, 0701-2100-0002-0024, 0701-2200-0002-0024, 0701-2300-0002-0024, 0702-2000-0002-0024, 0702-2100-0002-0024, 0702-2200-0002-0024, 0702-2300-0002-0024, 0703-2000-0002-0024, 0703-2100-0002-0024, 0703-2200-0002-0024, 0703-2300-0002-0024, 0704-2000-0002-0024, 0704-2100-0002-0024, 0704-2200-0002-0024, 0704-2300-0002-0024, 0705-2000-0002-0024, 0705-2100-0002-0024, 0705-2200-0002-0024, 0705-2300-0002-0024, 0706-2000-0002-0024, 0706-2100-0002-0024, 0706-2200-0002-0024, 0706-2300-0002-0024, 0707-2000-0002-0024, 0707-2100-0002-0024, 0707-2200-0002-0024, 0707-2300-0002-0024, 1800-2000-0002-0024, 1800-2100-0002-0024, 1800-2200-0002-0024, 1800-2300-0002-0024, 1801-2000-0002-0024, 1801-2100-0002-0024, 1801-2200-0002-0024, 1801-2300-0002-0024, 1802-2000-0002-0024, 1802-2100-0002-0024, 1802-2200-0002-0024, 1802-2300-0002-0024, 1803-2000-0002-0024, 1803-2100-0002-0024, 1803-2200-0002-0024, 1803-2300-0002-0024, 1804-2000-0002-0024, 1804-2100-0002-0024, 1804-2200-0002-0024, 1804-2300-0002-0024, 1805-2000-0002-0024, 1805-2100-0002-0024, 1805-2200-0002-0024, 1805-2300-0002-0024, 1806-2000-0002-0024, 1806-2100-0002-0024, 1806-2200-0002-0024, 1806-2300-0002-0024, 1807-2000-0002-0024, 1807-2100-0002-0024, 1807-2200-0002-0024, 1807-2300-0002-0024

HMS 0700-2000-0002-0025: AMS Slot feed resistance is too high. Please reduce the feed resistance, decrease the rotation resistance of the spool, and avoid having the filament tube too long and excessively bent.

X1 Series/P1 Series/H2 series/P2S

Scan for article

Aliases: 0700-2100-0002-0025, 0700-2200-0002-0025, 0700-2300-0002-0025, 0701-2000-0002-0025, 0701-2100-0002-0025, 0701-2200-0002-0025, 0701-2300-0002-0025, 0702-2000-0002-0025, 0702-2100-0002-0025, 0702-2200-0002-0025, 0702-2300-0002-0025, 0703-2000-0002-0025, 0703-2100-0002-0025, 0703-2200-0002-0025, 0703-2300-0002-0025, 0704-2000-0002-0025, 0704-2100-0002-0025, 0704-2200-0002-0025, 0704-2300-0002-0025, 0705-2000-0002-0025, 0705-2100-0002-0025, 0705-2200-0002-0025, 0705-2300-0002-0025, 0706-2000-0002-0025, 0706-2100-0002-0025, 0706-2200-0002-0025, 0706-2300-0002-0025, 0707-2000-0002-0025, 0707-2100-0002-0025, 0707-2200-0002-0025, 0707-2300-0002-0025, 1800-2000-0002-0025, 1800-2100-0002-0025, 1800-2200-0002-0025, 1800-2300-0002-0025, 1801-2000-0002-0025, 1801-2100-0002-0025, 1801-2200-0002-0025, 1801-2300-0002-0025, 1802-2000-0002-0025, 1802-2100-0002-0025, 1802-2200-0002-0025, 1802-2300-0002-0025, 1803-2000-0002-0025, 1803-2100-0002-0025, 1803-2200-0002-0025, 1803-2300-0002-0025, 1804-2000-0002-0025, 1804-2100-0002-0025, 1804-2200-0002-0025, 1804-2300-0002-0025, 1805-2000-0002-0025, 1805-2100-0002-0025, 1805-2200-0002-0025, 1805-2300-0002-0025, 1806-2000-0002-0025, 1806-2100-0002-0025, 1806-2200-0002-0025, 1806-2300-0002-0025, 1807-2000-0002-0025, 1807-2100-0002-0025, 1807-2200-0002-0025, 1807-2300-0002-0025

HMS 0700-2000-0003-0001: AMS Slot filament has run out. Please wait while old filament is purged.

Aliases: 0700-2100-0003-0001, 0700-2200-0003-0001, 0700-2300-0003-0001, 0701-2000-0003-0001, 0701-2100-0003-0001, 0701-2200-0003-0001, 0701-2300-0003-0001, 0702-2000-0003-0001, 0702-2100-0003-0001, 0702-2200-0003-0001, 0702-2300-0003-0001, 0703-2000-0003-0001, 0703-2100-0003-0001, 0703-2200-0003-0001, 0703-2300-0003-0001

X1 series/P1 series

Scan for article

HMS 0700-2000-0003-0002: AMS Slot filament has run out and automatically switched to the slot with the same filament.

Aliases: 0700-2100-0003-0002, 0700-2200-0003-0002, 0700-2300-0003-0002, 0701-2000-0003-0002, 0701-2100-0003-0002, 0701-2200-0003-0002, 0701-2300-0003-0002, 0702-2000-0003-0002, 0702-2100-0003-0002, 0702-2200-0003-0002, 0702-2300-0003-0002, 0703-2000-0003-0002, 0703-2100-0003-0002, 0703-2200-0003-0002, 0703-2300-0003-0002

X1 series/P1 series

Scan for article

HMS 0700-4000-0002-0001: The filament buffer signal lost, the cable or position sensor may be malfunctioning.

Aliases: 0701-4000-0002-0001, 0702-4000-0002-0001, 0703-4000-0002-0001, 1800-4000-0002-0001, 1801-4000-0002-0001, 1802-4000-0002-0001, 1803-4000-0002-0001, 1804-4000-0002-0001, 1805-4000-0002-0001, 1806-4000-0002-0001, 1807-4000-0002-0001

X1 series/P1 series

Scan for article

HMS 0700-4000-0002-0002: The filament buffer position signal error,the position sensor may be malfunctioning.

X1 series/P1 series

Scan for article

HMS 0700-4000-0002-0003: The AMS Hub communication is abnormal,the cable may be not well connected.

X1 series/P1 series

Scan for article

HMS 0700-4000-0002-0004: The filament buffer signal is abnormal,the spring may be stuck or the filament may be tangle.

X1 series/P1 series

Scan for article

HMS 0700-4500-0002-0001: The filament cutter sensor is malfunctioning.The sensor may be disconected or damaged.

X1 series/P1 series

Scan for article

HMS 0700-4500-0002-0002: The filament cutter's cutting distance is too large.The XY motor may lose steps.

X1 series/P1 series

Scan for article

HMS 0700-4500-0002-0003: The filament cutter handle has not been released. The handle or blade may be jammed, or there could be an issue with the filament sensor connection.

Aliases: 1200-4500-0002-0003

X1 series/P1 series

Scan for article

HMS 0700-5000-0002-0001: AMS communication is abnormal; please check the connection cable.

Aliases: 0701-5000-0002-0001, 0702-5000-0002-0001, 0703-5000-0002-0001, 1800-5000-0002-0001, 1801-5000-0002-0001, 1802-5000-0002-0001, 1803-5000-0002-0001, 1804-5000-0002-0001, 1805-5000-0002-0001, 1806-5000-0002-0001, 1807-5000-0002-0001, 1200-5000-0002-0001, 1201-5000-0002-0001, 1202-5000-0002-0001, 1203-5000-0002-0001

X1 series/P1 series/H2 Series/A1/A1 mini

Scan for article

HMS 0700-5100-0003-0001: The AMS is disabled; please load filament from spool holder.

X1 series/P1 series

Scan for article

HMS 0700-6000-0002-0001: The AMS Slot is overloaded. The filament may be tangled or the spool may be stuck.

Aliases: 0700-7000-0002-0001, 0700-7100-0002-0001, 0700-7200-0002-0001, 0700-7300-0002-0001, 0701-7000-0002-0001, 0701-7100-0002-0001, 0701-7200-0002-0001, 0701-7300-0002-0001, 0702-7000-0002-0001, 0702-7100-0002-0001, 0702-7200-0002-0001, 0702-7300-0002-0001, 0703-7000-0002-0001, 0703-7100-0002-0001, 0703-7200-0002-0001, 0703-7300-0002-0001, 0704-7000-0002-0001, 0704-7100-0002-0001, 0704-7200-0002-0001, 0705-7000-0002-0001, 0705-7100-0002-0001, 0705-7200-0002-0001, 0705-7300-0002-0001, 0706-7000-0002-0001, 0706-7100-0002-0001, 0706-7200-0002-0001, 0706-7300-0002-0001, 0707-7000-0002-0001, 0707-7100-0002-0001, 0707-7200-0002-0001, 0707-7300-0002-0001, 1800-7000-0002-0001, 1800-7100-0002-0001, 1800-7200-0002-0001, 1800-7300-0002-0001, 1801-7000-0002-0001, 1801-7100-0002-0001, 1801-7200-0002-0001, 1801-7300-0002-0001, 1802-7000-0002-0001, 1802-7100-0002-0001, 1802-7200-0002-0001, 1802-7300-0002-0001, 1803-7000-0002-0001, 1803-7100-0002-0001, 1803-7200-0002-0001, 1803-7300-0002-0001, 1804-7000-0002-0001, 1804-7100-0002-0001, 1804-7200-0002-0001, 1804-7300-0002-0001, 1805-7000-0002-0001, 1805-7100-0002-0001, 1805-7200-0002-0001, 1805-7300-0002-0001, 1806-7000-0002-0001, 1806-7100-0002-0001, 1806-7200-0002-0001, 1806-7300-0002-0001, 1807-7000-0002-0001, 1807-7100-0002-0001, 1807-7200-0002-0001, 1807-7300-0002-0001

X1 series/P1 series/H2 series/P2S

Scan for article

HMS 0700-7000-0002-0001: Failed to pull out the filament from the extruder. Please check whether the extruder is clogged or whether the filament is broken inside the extruder.

Aliases: 0701-7000-0002-0001, 0702-7000-0002-0001, 0703-7000-0002-0001

X1 series/P1 series

Scan for article

HMS 0700-7000-0002-0002: Failed to feed the filament into the toolhead. Please check whether the filament or the spool is stuck.

Aliases: 0700-7100-0002-0002, 0700-7200-0002-0002, 0700-7300-0002-0002, 0701-7000-0002-0002, 0701-7100-0002-0002, 0701-7200-0002-0002, 0701-7300-0002-0002, 0702-7000-0002-0002, 0702-7100-0002-0002, 0702-7200-0002-0002, 0702-7300-0002-0002, 0703-7000-0002-0002, 0703-7100-0002-0002, 0703-7200-0002-0002, 0703-7300-0002-0002, 0704-7000-0002-0002, 0704-7100-0002-0002, 0704-7200-0002-0002, 0705-7000-0002-0002, 0705-7100-0002-0002, 0705-7200-0002-0002, 0705-7300-0002-0002, 0706-7000-0002-0002, 0706-7100-0002-0002, 0706-7200-0002-0002, 0706-7300-0002-0002, 0707-7000-0002-0002, 0707-7100-0002-0002, 0707-7200-0002-0002, 0707-7300-0002-0002, 1800-7000-0002-0002, 1800-7100-0002-0002, 1800-7200-0002-0002, 1800-7300-0002-0002, 1801-7000-0002-0002, 1801-7100-0002-0002, 1801-7200-0002-0002, 1801-7300-0002-0002, 1802-7000-0002-0002, 1802-7100-0002-0002, 1802-7200-0002-0002, 1802-7300-0002-0002, 1803-7000-0002-0002, 1803-7100-0002-0002, 1803-7200-0002-0002, 1803-7300-0002-0002, 1805-7000-0002-0002, 1805-7100-0002-0002, 1805-7200-0002-0002, 1805-7300-0002-0002, 1806-7000-0002-0002, 1806-7100-0002-0002, 1806-7200-0002-0002, 1806-7300-0002-0002, 1807-7000-0002-0002, 1807-7100-0002-0002, 1807-7200-0002-0002, 1807-7300-0002-0002

X1 series/P1 series/H2 series/P2S

Scan for article

HMS 0700-7000-0002-0003: Failed to extrude the filament. Please check if the extruder or nozzle clogged.

Aliases: 0701-7000-0002-0003, 0702-7000-0002-0003, 0703-7000-0002-0003, 0704-7000-0002-0003, 0705-7000-0002-0003, 0706-7000-0002-0003, 0707-7000-0002-0003, 1800-7000-0002-0003, 1801-7000-0002-0003, 1802-7000-0002-0003, 1803-7000-0002-0003, 1804-7000-0002-0003, 1805-7000-0002-0003, 1806-7000-0002-0003, 1807-7000-0002-0003

X1 series/P1 series/H2 series

Scan for article

HMS 0700-7000-0002-0004: Failed to pull back the filament from the toolhead to AMS. Please check whether the filament or the spool is stuck.

X1 series/P1 series/H2 series

Scan for article

Aliases: 0700-7100-0002-0004, 0700-7200-0002-0004, 0700-7300-0002-0004, 0701-7000-0002-0004, 0701-7100-0002-0004, 0701-7200-0002-0004, 0701-7300-0002-0004, 0702-7000-0002-0004, 0702-7100-0002-0004, 0702-7200-0002-0004, 0702-7300-0002-0004, 0703-7000-0002-0004, 0703-7100-0002-0004, 0703-7200-0002-0004, 0703-7300-0002-0004, 0704-7000-0002-0004, 0704-7100-0002-0004, 0704-7200-0002-0004, 0704-7300-0002-0004, 0705-7000-0002-0004, 0705-7100-0002-0004, 0705-7200-0002-0004, 0705-7300-0002-0004, 0706-7000-0002-0004, 0706-7100-0002-0004, 0706-7200-0002-0004, 0706-7300-0002-0004, 0707-7000-0002-0004, 0707-7100-0002-0004, 0707-7200-0002-0004, 0707-7300-0002-0004, 1800-7000-0002-0004, 1800-7100-0002-0004, 1800-7200-0002-0004, 1800-7300-0002-0004, 1801-7000-0002-0004, 1801-7100-0002-0004, 1801-7200-0002-0004, 1801-7300-0002-0004, 1802-7000-0002-0004, 1802-7100-0002-0004, 1802-7200-0002-0004, 1802-7300-0002-0004, 1803-7000-0002-0004, 1803-7100-0002-0004, 1803-7200-0002-0004, 1803-7300-0002-0004, 1804-7000-0002-0004, 1804-7100-0002-0004, 1804-7200-0002-0004, 1804-7300-0002-0004, 1805-7000-0002-0004, 1805-7100-0002-0004, 1805-7200-0002-0004, 1805-7300-0002-0004, 1806-7000-0002-0004, 1806-7100-0002-0004, 1806-7200-0002-0004, 1806-7300-0002-0004, 1807-7000-0002-0004, 1807-7100-0002-0004, 1807-7200-0002-0004, 1807-7300-0002-0004

HMS 0700-7000-0002-0005: Failed to feed the filament outside the AMS. Please clip the end of the filament flat and check to see if the spool is stuck.

X1 series/P1 series/H2 series

Scan for article

Aliases: 0700-7100-0002-0005, 0700-7200-0002-0005, 0700-7300-0002-0005, 0701-7000-0002-0005, 0701-7100-0002-0005, 0701-7200-0002-0005, 0701-7300-0002-0005, 0702-7000-0002-0005, 0702-7100-0002-0005, 0702-7200-0002-0005, 0702-7300-0002-0005, 0703-7000-0002-0005, 0703-7100-0002-0005, 0703-7200-0002-0005, 0703-7300-0002-0005, 0704-7000-0002-0005, 0704-7100-0002-0005, 0704-7200-0002-0005, 0704-7300-0002-0005, 0705-7000-0002-0005, 0705-7100-0002-0005, 0705-7200-0002-0005, 0705-7300-0002-0005, 0706-7000-0002-0005, 0706-7100-0002-0005, 0706-7200-0002-0005, 0706-7300-0002-0005, 0707-7000-0002-0005, 0707-7100-0002-0005, 0707-7200-0002-0005, 0707-7300-0002-0005, 1800-7000-0002-0005, 1800-7100-0002-0005, 1800-7200-0002-0005, 1800-7300-0002-0005, 1801-7000-0002-0005, 1801-7100-0002-0005, 1801-7200-0002-0005, 1801-7300-0002-0005, 1802-7000-0002-0005, 1802-7100-0002-0005, 1802-7200-0002-0005, 1802-7300-0002-0005, 1803-7000-0002-0005, 1803-7100-0002-0005, 1803-7200-0002-0005, 1803-7300-0002-0005, 1804-7000-0002-0005, 1804-7100-0002-0005, 1804-7200-0002-0005, 1804-7300-0002-0005, 1805-7000-0002-0005, 1805-7100-0002-0005, 1805-7200-0002-0005, 1805-7300-0002-0005, 1806-7000-0002-0005, 1806-7100-0002-0005, 1806-7200-0002-0005, 1806-7300-0002-0005, 1807-7000-0002-0005, 1807-7100-0002-0005, 1807-7200-0002-0005, 1807-7300-0002-0005

HMS 0700-7000-0002-0007: AMS filament ran out. Please put a new filament into AMS and click the "Retry" button.

Aliases: 0701-7000-0002-0007, 0702-7000-0002-0007, 0703-7000-0002-0007

X1 series/P1 series

Scan for article

HMS 0700-7000-0002-0008: Failed to get AMS mapping table; please click "Resume" to retry.

Aliases: 0701-7000-0002-0008, 0702-7000-0002-0008, 0703-7000-0002-0008, 0704-7000-0002-0008, 0705-7000-0002-0008, 0706-7000-0002-0008, 0707-7000-0002-0008, 1800-7000-0002-0008, 1801-7000-0002-0008, 1802-7000-0002-0008, 1803-7000-0002-0008, 1804-7000-0002-0008, 1805-7000-0002-0008, 1806-7000-0002-0008, 1807-7000-0002-0008, 07FE-7000-0002-0008, 07FF-7000-0002-0008, 18FE-7000-0002-0008, 18FF-7000-0002-0008

X1 series/P1 series/H2 series

Scan for article

HMS 0700-8000-0001-0001: AMS Heater Current Sensor Abnormal.

Aliases: 0700-8100-0001-0001, 0701-8000-0001-0001, 0701-8100-0001-0001, 0702-8000-0001-0001, 0702-8100-0001-0001, 0703-8000-0001-0001, 0703-8100-0001-0001, 1800-8000-0001-0001, 1801-8000-0001-0001, 1802-8000-0001-0001, 1803-8000-0001-0001, 1804-8000-0001-0001, 1805-8000-0001-0001, 1806-8000-0001-0001, 1807-8000-0001-0001

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT<

Scan for article

HMS 0700-8000-0001-0002: AMS Heater is offline, possibly due to a loose connector.

Aliases: 0700-8100-0001-0002, 0701-8000-0001-0002, 0701-8100-0001-0002, 0702-8000-0001-0002, 0702-8100-0001-0002, 0703-8000-0001-0002, 0703-8100-0001-0002, 1800-8000-0001-0002, 1801-8000-0001-0002, 1802-8000-0001-0002, 1803-8000-0001-0002, 1804-8000-0001-0002, 1805-8000-0001-0002, 1806-8000-0001-0002, 1807-8000-0001-0002

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT<

Scan for article

HMS 0700-8000-0001-0003: AMS Heater short circuit, possibly caused by wiring short or heater damage.

Aliases: 0700-8100-0001-0003, 0701-8000-0001-0003, 0701-8100-0001-0003, 0702-8000-0001-0003, 0702-8100-0001-0003, 0703-8000-0001-0003, 0703-8100-0001-0003, 1800-8000-0001-0003, 1801-8000-0001-0003, 1802-8000-0001-0003, 1803-8000-0001-0003, 1804-8000-0001-0003, 1805-8000-0001-0003, 1806-8000-0001-0003, 1807-8000-0001-0003

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT

Scan for article

HMS 0700-8000-0001-0004: AMS Heater abnormal heating.

Aliases: 0700-8100-0001-0004, 0701-8000-0001-0004, 0701-8100-0001-0004, 0702-8000-0001-0004, 0702-8100-0001-0004, 0703-8000-0001-0004, 0703-8100-0001-0004, 1800-8000-0001-0004, 1801-8000-0001-0004, 1802-8000-0001-0004, 1803-8000-0001-0004, 1804-8000-0001-0004, 1805-8000-0001-0004, 1806-8000-0001-0004, 1807-8000-0001-0004

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro

Scan for article

HMS 0700-9000-0001-0003: AMS The exhaust Valve is not connected, which may be due to poor connector contact.

Aliases: 0700-9100-0001-0003, 0701-9000-0001-0003, 0701-9100-0001-0003, 0702-9000-0001-0003, 0702-9100-0001-0003, 0703-9000-0001-0003, 0703-9100-0001-0003, 0704-9000-0001-0003, 0704-9100-0001-0003, 0705-9000-0001-0003, 0705-9100-0001-0003, 0706-9000-0001-0003, 0706-9100-0001-0003, 0707-9000-0001-0003, 0707-9100-0001-0003, 1800-9000-0001-0003, 1801-9000-0001-0003, 1802-9000-0001-0003, 1803-9000-0001-0003, 1804-9000-0001-0003, 1805-9000-0001-0003, 1806-9000-0001-0003, 1807-9000-0001-0003

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 0700-9000-0002-0001: AMS The operation of the exhaust Valve is abnormal, which may be due to excessive resistance.

Aliases: 0700-9100-0002-0001, 0701-9000-0002-0001, 0701-9100-0002-0001, 0702-9000-0002-0001, 0702-9100-0002-0001, 0703-9000-0002-0001, 0703-9100-0002-0001, 0704-9000-0002-0001, 0704-9100-0002-0001, 0705-9000-0002-0001, 0705-9100-0002-0001, 0706-9000-0002-0001, 0706-9100-0002-0001, 0707-9000-0002-0001, 0707-9100-0002-0001, 1800-9000-0002-0001, 1801-9000-0002-0001, 1802-9000-0002-0001, 1803-9000-0002-0001, 1804-9000-0002-0001, 1805-9000-0002-0001, 1806-9000-0002-0001, 1807-9000-0002-0001

X1 series/P1 series/P2S/ H2 series/A1/A1 mini/ AMS/AMS HT

Scan for article

HMS 0700-9200-0001-0001: AMS The cooling fan of Heater is blocked, which may be due to the fan being stuck.

Aliases: 0700-9300-0001-0001, 0701-9200-0001-0001, 0701-9300-0001-0001, 0702-9200-0001-0001, 0702-9300-0001-0001, 0703-9200-0001-0001, 0703-9300-0001-0001, 1800-9200-0001-0001, 1801-9200-0001-0001, 1802-9200-0001-0001, 1803-9200-0001-0001, 1804-9200-0001-0001, 1805-9200-0001-0001, 1806-9200-0001-0001, 1807-9200-0001-0001

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini



Scan for article

HMS 0700-9200-0002-0002: AMS Heater cooling fan speed is low, possibly due to excessive resistance.

Aliases: 0700-9300-0002-0002, 0701-9200-0002-0002, 0701-9300-0002-0002, 0702-9200-0002-0002, 0702-9300-0002-0002, 0703-9200-0002-0002, 0703-9300-0002-0002, 1800-9200-0002-0002, 1801-9200-0002-0002, 1802-9200-0002-0002, 1803-9200-0002-0002, 1804-9200-0002-0002, 1805-9200-0002-0002, 1806-9200-0002-0002, 1807-9200-0002-0002

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT



Scan for article

HMS 0700-9200-0002-0003: The AMS Heater cooling fan cannot start because the power adapter is not connected.

Aliases: 0700-9300-0002-0003, 0701-9200-0002-0003, 0701-9300-0002-0003, 0702-9200-0002-0003, 0702-9300-0002-0003, 0703-9200-0002-0003, 0703-9300-0002-0003, 1800-9200-0002-0003, 1801-9200-0002-0003, 1802-9200-0002-0003, 1803-9200-0002-0003, 1804-9200-0002-0003, 1805-9200-0002-0003, 1806-9200-0002-0003, 1807-9200-0002-0003

X1 series/P1 series/P2S/ H2 series/A1/A1 mini



Scan for article

HMS 0700-9400-0001-0001: AMS The temperature sensor of Heater is malfunctioning, which may be due to poor connector contact.

Aliases: 0700-9500-0001-0001, 0701-9400-0001-0001, 0701-9500-0001-0001, 0702-9400-0001-0001, 0702-9500-0001-0001, 0703-9400-0001-0001, 0703-9500-0001-0001, 1800-9400-0001-0001, 1801-9400-0001-0001, 1802-9400-0001-0001, 1803-9400-0001-0001, 1804-9400-0001-0001, 1805-9400-0001-0001, 1806-9400-0001-0001, 1807-9400-0001-0001

X1 series/P1 series/P2S/ H2 series/A1/A1 mini



Scan for article

HMS 0700-9600-0001-0001: AMS drying may be experiencing thermal runaway. Please power off the AMS immediately.

Aliases: 0701-9600-0001-0001, 0702-9600-0001-0001, 0703-9600-0001-0001, 0704-9600-0001-0001, 0705-9600-0001-0001, 0706-9600-0001-0001, 0707-9600-0001-0001, 1800-9600-0001-0001, 1801-9600-0001-0001, 1802-9600-0001-0001, 1803-9600-0001-0001, 1804-9600-0001-0001, 1805-9600-0001-0001, 1806-9600-0001-0001, 1807-9600-0001-0001

X1 series/P1 series/P2S/ H2 series/A1/A1 mini/ AMS 2 Pro/AMS HT

Scan for article

HMS 0700-9600-0001-0003: :AMS Unable to start drying; please pull out the filament from filament hub and try again.

Aliases: 0701-9600-0001-0003, 0702-9600-0001-0003, 0703-9600-0001-0003, 0704-9600-0001-0003, 0705-9600-0001-0003, 0706-9600-0001-0003, 0707-9600-0001-0003, 1800-9600-0001-0003, 1801-9600-0001-0003, 1802-9600-0001-0003, 1803-9600-0001-0003, 1804-9600-0001-0003, 1805-9600-0001-0003, 1806-9600-0001-0003, 1807-9600-0001-0003

H2 series/X1 series/P1 series/P2S

Scan for article

HMS 0700-9600-0002-0002: The ambient temperature of the AMS is too low, which may affect the drying performance.

Aliases: 0701-9600-0002-0002, 0702-9600-0002-0002, 0703-9600-0002-0002, 0704-9600-0002-0002, 0705-9600-0002-0002, 0706-9600-0002-0002, 0707-9600-0002-0002, 1800-9600-0002-0002, 1801-9600-0002-0002, 1802-9600-0002-0002, 1803-9600-0002-0002, 1804-9600-0002-0002, 1805-9600-0002-0002, 1806-9600-0002-0002, 1807-9600-0002-0002

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT

Scan for article

HMS 0700-9700-0003-0001: Chamber temperature of AMS is relatively high; auxiliary feeding or RFID reading is not available currently.

Aliases: 0701-9700-0003-0001, 0702-9700-0003-0001, 0703-9700-0003-0001, 1800-9700-0003-0001, 1801-9700-0003-0001, 1802-9700-0003-0001, 1803-9700-0003-0001, 1804-9700-0003-0001, 1805-9700-0003-0001, 1806-9700-0003-0001, 1807-9700-0003-0001

X1 series/P1 series/P2S/ H2 series/ A1/A1 mini/ AMS 2 Pro/AMS HT

Scan for article

HMS 0700-9800-0002-0001: AMS The power adapter voltage is too low, which may result in insufficient drying temperature. Please replace the power adapter.

Aliases: 0701-9800-0002-0001, 0702-9800-0002-0001, 0703-9800-0002-0001, 1800-9800-0002-0001, 1801-9800-0002-0001, 1802-9800-0002-0001, 1803-9800-0002-0001, 1804-9800-0002-0001, 1805-9800-0002-0001, 1806-9800-0002-0001, 1807-9800-0002-0001

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

HMS 07FF-2000-0002-0001: External filament has run out; please load a new filament.

X1 series/P1 series/P2S

Scan for article

HMS 07FF-2000-0002-0002: External filament is missing; please load a new filament.

X1 series/P1 series/H2 series

Scan for article

HMS 07FF-2000-0002-0004: Please pull out the filament on the spool holder from the extruder.

X1 series/P1 series/H2 series

Scan for article

HMS 0C00-0100-0001-0004: Micro Lidar Lens dirty.

X1 series/P1 series

Scan for article

HMS 0C00-0100-0001-0009: Chamber camera dirty.

X1 series/P1 series

Scan for article

HMS 0C00-0100-0002-0008: Failed to get image from Live View Camera. Spaghetti and waste chute pileup detection is not available at this time.

X1 series/P1 series

Scan for article

HMS 0C00-0300-0003-0006: Purged filaments piled up.

X1 series/P1 series

Scan for article

HMS 0C00-0300-0003-0008: Possible spaghetti defects.

X1 series/P1 series

Scan for article

HMS 1800-7000-0002-0007: AMS-HT filament ran out. Please put a new filament into the same slot in AMS and resume.

Aliases: 1801-7000-0002-0007, 1802-7000-0002-0007, 1800-7003-0002-0007, 1804-7000-0002-0007, 1805-7000-0002-0007, 1806-7000-0002-0007, 1807-7000-0002-0007

X1 series/P1 series/P2S/ H2 series/A1/A1 mini

Scan for article

Index

0300-0100-0001-0003: Pg 1
0300-0100-0001-0006: Pg 1
0300-0100-0001-0007: Pg 1
0300-0100-0001-0008: Pg 1
0300-0100-0001-000A: Pg 2
0300-0100-0003-0008: Pg 2
0300-0200-0001-0001: Pg 2
0300-0200-0001-0002: Pg 2
0300-0200-0001-0003: Pg 3
0300-0200-0001-0006: Pg 3
0300-0200-0001-0007: Pg 3
0300-0300-0001-0001: Pg 3
0300-0300-0002-0002: Pg 4
0300-0400-0002-0001: Pg 4
0300-0600-0001-0001: Pg 4
0300-0600-0001-0002: Pg 4
0300-0600-0001-0003: Pg 5
0300-0700-0001-0001: Pg 4
0300-0700-0001-0002: Pg 4
0300-0700-0001-0003: Pg 5
0300-0800-0001-0001: Pg 4
0300-0800-0001-0002: Pg 4
0300-0800-0001-0003: Pg 5
0300-0A00-0001-0001: Pg 5
0300-0A00-0001-0002: Pg 5
0300-0A00-0001-0003: Pg 5
0300-0A00-0001-0004: Pg 5
0300-0A00-0001-0005: Pg 6
0300-0B00-0001-0001: Pg 5
0300-0B00-0001-0002: Pg 5
0300-0B00-0001-0003: Pg 5
0300-0B00-0001-0004: Pg 5
0300-0B00-0001-0005: Pg 6
0300-0C00-0001-0001: Pg 5
0300-0C00-0001-0002: Pg 5
0300-0C00-0001-0003: Pg 5
0300-0C00-0001-0004: Pg 5
0300-0C00-0001-0005: Pg 6
0300-0D00-0001-0003: Pg 6
0300-0D00-0001-0004: Pg 6
0300-0D00-0001-0005: Pg 6
0300-0D00-0001-0006: Pg 6
0300-0D00-0001-0007: Pg 6
0300-0D00-0001-0008: Pg 6
0300-0D00-0001-0009: Pg 6
0300-0D00-0001-000A: Pg 6
0300-0D00-0001-000B: Pg 6
0300-0D00-0002-0001: Pg 6
0300-0D00-0002-0003: Pg 6
0300-0D00-0002-0004: Pg 6
0300-0D00-0002-0005: Pg 6
0300-0D00-0002-0006: Pg 6
0300-0D00-0002-0007: Pg 6
0300-0D00-0002-0008: Pg 6
0300-0D00-0002-0009: Pg 6
0300-0D00-0002-000A: Pg 6
0300-0F00-0001-0001: Pg 7
0300-1000-0002-0001: Pg 7
0300-1000-0002-0002: Pg 7
0300-1100-0002-0001: Pg 7
0300-1100-0002-0002: Pg 7
0300-1200-0002-0001: Pg 7
0300-1300-0001-0001: Pg 7
0300-1400-0001-0001: Pg 7
0300-1500-0001-0001: Pg 7
0300-1D00-0001-0001: Pg 8
0300-3100-0001-0001: Pg 4
0300-4000-0002-0001: Pg 8
0300-4100-0001-0001: Pg 8
0300-9100-0001-0006: Pg 8
0300-9100-0001-0007: Pg 9
0300-9200-0001-0006: Pg 8
0300-9200-0001-0007: Pg 9
0300-9400-0003-0001: Pg 9
0300-A800-0001-0001: Pg 9
0500-0100-0002-0001: Pg 9
0500-0100-0002-0002: Pg 10
0500-0100-0002-0003: Pg 10
0500-0100-0003-0004: Pg 10
0500-0100-0003-0005: Pg 10
0500-0100-0003-0006: Pg 11
0500-0200-0002-0001: Pg 11
0500-0200-0002-0002: Pg 11
0500-0200-0002-0002: Pg 11
0500-0200-0002-0003: Pg 11
0500-0200-0002-0004: Pg 11
0500-0200-0002-0005: Pg 11
0500-0200-0002-0006: Pg 12
0500-0300-0001-0001: Pg 12
0500-0300-0001-0002: Pg 12
0500-0300-0001-0003: Pg 12
0500-0300-0001-0004: Pg 13
0500-0300-0001-000A: Pg 13
0500-0300-0001-000B: Pg 13
0500-0300-0002-000C: Pg 13
0500-0300-0002-000E: Pg 14
0500-0300-0002-0055: Pg 14
0500-0400-0001-0001: Pg 14
0500-0400-0001-0002: Pg 14
0500-0400-0001-0003: Pg 15
0500-0400-0001-0004: Pg 15
0500-0400-0001-0006: Pg 15
0500-0400-0001-0044: Pg 14
0500-0400-0001-0046: Pg 14
0500-0400-0001-0047: Pg 14
0500-0400-0001-0048: Pg 14
0500-0400-0002-0007: Pg 15
0500-0500-0001-0007: Pg 16
0500-0500-0001-000E: Pg 14
0500-0500-0001-000F: Pg 14
0500-0500-0001-0010: Pg 14
0500-0500-0001-0011: Pg 14
0500-0500-0001-0012: Pg 14
0500-0500-0001-0014: Pg 16
0501-0400-0001-0044: Pg 14
0501-0500-0001-0010: Pg 14
0501-0500-0001-0014: Pg 16
0502-0400-0001-0044: Pg 14
0502-0500-0001-0010: Pg 14
0502-0500-0001-0014: Pg 16
0503-0400-0001-0044: Pg 14
0503-0500-0001-0010: Pg 14
0503-0500-0001-0014: Pg 16
0580-0400-0001-0045: Pg 14
0580-0500-0001-0010: Pg 14
0580-0500-0001-0017: Pg 16
0580-0500-0001-0017: Pg 16
0581-0400-0001-0045: Pg 14
0581-0500-0001-0010: Pg 14
0581-0500-0001-0017: Pg 16
0581-0500-0001-0017: Pg 16
0582-0400-0001-0045: Pg 14
0582-0500-0001-0010: Pg 14
0582-0500-0001-0017: Pg 16
0582-0500-0001-0017: Pg 16
0583-0400-0001-0045: Pg 14
0583-0500-0001-0010: Pg 14
0583-0500-0001-0017: Pg 16
0583-0500-0001-0017: Pg 16
0584-0400-0001-0045: Pg 14
0584-0500-0001-0010: Pg 14
0584-0500-0001-0017: Pg 16
0584-0500-0001-0017: Pg 16
0585-0400-0001-0045: Pg 14
0585-0500-0001-0010: Pg 14
0585-0500-0001-0017: Pg 16
0585-0500-0001-0017: Pg 16
0586-0400-0001-0045: Pg 14
0586-0500-0001-0010: Pg 14
0586-0500-0001-0017: Pg 16
0586-0500-0001-0017: Pg 16
0587-0400-0001-0045: Pg 14
0587-0500-0001-0010: Pg 14
0587-0500-0001-0017: Pg 16
0587-0500-0001-0017: Pg 16
0700-0100-0001-0001: Pg 17
0700-0100-0001-0003: Pg 17
0700-0100-0001-0004: Pg 17
0700-0100-0001-0005: Pg 17
0700-0100-0002-0002: Pg 18
0700-0100-0002-0007: Pg 18
0700-0200-0001-0001: Pg 18
0700-1000-0001-0001: Pg 18
0700-1000-0001-0003: Pg 18
0700-1000-0002-0002: Pg 19
0700-2000-0001-0081: Pg 19
0700-2000-0001-0083: Pg 19
0700-2000-0001-0084: Pg 19
0700-2000-0001-0086: Pg 20
0700-2000-0002-0001: Pg 20
0700-2000-0002-0002: Pg 21
0700-2000-0002-0003: Pg 21
0700-2000-0002-0004: Pg 22
0700-2000-0002-0005: Pg 22
0700-2000-0002-0006: Pg 23
0700-2000-0002-0010: Pg 23
0700-2000-0002-0011: Pg 24
0700-2000-0002-0012: Pg 24
0700-2000-0002-0013: Pg 25
0700-2000-0002-0014: Pg 25
0700-2000-0002-0015: Pg 26
0700-2000-0002-0016: Pg 26
0700-2000-0002-0017: Pg 27
0700-2000-0002-0018: Pg 27
0700-2000-0002-0019: Pg 28
0700-2000-0002-0021: Pg 28
0700-2000-0002-0022: Pg 29
0700-2000-0002-0023: Pg 29
0700-2000-0002-0024: Pg 30
0700-2000-0002-0025: Pg 30
0700-2000-0003-0001: Pg 31
0700-2000-0003-0002: Pg 31
0700-2100-0001-0081: Pg 19
0700-2100-0001-0083: Pg 19
0700-2100-0001-0084: Pg 19
0700-2100-0001-0086: Pg 20
0700-2100-0002-0001: Pg 20
0700-2100-0002-0002: Pg 21
0700-2100-0002-0003: Pg 21
0700-2100-0002-0004: Pg 22
0700-2100-0002-0005: Pg 22
0700-2100-0002-0006: Pg 23
0700-2100-0002-0010: Pg 23
0700-2100-0002-0011: Pg 24
0700-2100-0002-0012: Pg 24
0700-2100-0002-0013: Pg 25
0700-2100-0002-0014: Pg 25
0700-2100-0002-0015: Pg 26
0700-2100-0002-0016: Pg 26
0700-2100-0002-0017: Pg 27
0700-2100-0002-0018: Pg 27
0700-2100-0002-0019: Pg 28
0700-2100-0002-0021: Pg 28
0700-2100-0002-0022: Pg 29
0700-2100-0002-0023: Pg 29
0700-2100-0002-0024: Pg 30
0700-2100-0002-0025: Pg 30
0700-2100-0003-0001: Pg 31
0700-2100-0003-0002: Pg 31
0700-2200-0001-0081: Pg 19
0700-2200-0001-0083: Pg 19
0700-2200-0001-0084: Pg 19
0700-2200-0001-0086: Pg 20
0700-2200-0002-0001: Pg 20
0700-2200-0002-0002: Pg 21
0700-2200-0002-0003: Pg 21
0700-2200-0002-0004: Pg 22
0700-2200-0002-0005: Pg 22
0700-2200-0002-0006: Pg 23
0700-2200-0002-0010: Pg 23
0700-2200-0002-0011: Pg 24
0700-2200-0002-0012: Pg 24
0700-2200-0002-0013: Pg 25
0700-2200-0002-0014: Pg 25
0700-2200-0002-0015: Pg 26
0700-2200-0002-0016: Pg 26
0700-2200-0002-0017: Pg 27
0700-2200-0002-0018: Pg 27
0700-2200-0002-0019: Pg 28
0700-2200-0002-0021: Pg 28
0700-2200-0002-0022: Pg 29
0700-2200-0002-0023: Pg 29
0700-2200-0002-0024: Pg 30
0700-2200-0002-0025: Pg 30
0700-2200-0003-0001: Pg 31
0700-2200-0003-0002: Pg 31
0700-2300-0001-0081: Pg 19
0700-2300-0001-0083: Pg 19
0700-2300-0001-0084: Pg 19
0700-2300-0001-0086: Pg 20
0700-2300-0002-0001: Pg 20
0700-2300-0002-0002: Pg 21
0700-2300-0002-0003: Pg 21
0700-2300-0002-0004: Pg 22
0700-2300-0002-0005: Pg 22
0700-2300-0002-0006: Pg 23
0700-2300-0002-0010: Pg 23
0700-2300-0002-0011: Pg 24
0700-2300-0002-0012: Pg 24
0700-2300-0002-0013: Pg 25
0700-2300-0002-0014: Pg 25
0700-2300-0002-0015: Pg 26
0700-2300-0002-0016: Pg 26
0700-2300-0002-0017: Pg 27
0700-2300-0002-0018: Pg 27
0700-2300-0002-0019: Pg 28
0700-2300-0002-0021: Pg 28
0700-2300-0002-0022: Pg 29
0700-2300-0002-0023: Pg 29
0700-2300-0002-0024: Pg 30
0700-2300-0002-0025: Pg 30
0700-2300-0003-0001: Pg 31
0700-2300-0003-0002: Pg 31
0700-4000-0002-0001: Pg 31
0700-4000-0002-0002: Pg 31
0700-4000-0002-0003: Pg 32
0700-4000-0002-0004: Pg 32
0700-4500-0002-0001: Pg 32
0700-4500-0002-0002: Pg 32
0700-4500-0002-0003: Pg 32
0700-5000-0002-0001: Pg 33
0700-5100-0003-0001: Pg 33
0700-6000-0002-0001: Pg 33
0700-7000-0002-0001: Pg 33

0700-7000-0002-0001: Pg 34
0700-7000-0002-0002: Pg 34
0700-7000-0002-0003: Pg 34
0700-7000-0002-0004: Pg 35
0700-7000-0002-0005: Pg 35
0700-7000-0002-0007: Pg 36
0700-7000-0002-0008: Pg 36
0700-7100-0002-0001: Pg 33
0700-7100-0002-0002: Pg 34
0700-7100-0002-0004: Pg 35
0700-7100-0002-0005: Pg 35
0700-7200-0002-0001: Pg 33
0700-7200-0002-0002: Pg 34
0700-7200-0002-0004: Pg 35
0700-7200-0002-0005: Pg 35
0700-7300-0002-0001: Pg 33
0700-7300-0002-0002: Pg 34
0700-7300-0002-0004: Pg 35
0700-7300-0002-0005: Pg 35
0700-8000-0001-0001: Pg 36
0700-8000-0001-0002: Pg 36
0700-8000-0001-0003: Pg 37
0700-8000-0001-0004: Pg 37
0700-8100-0001-0001: Pg 36
0700-8100-0001-0002: Pg 36
0700-8100-0001-0003: Pg 37
0700-8100-0001-0004: Pg 37
0700-9000-0001-0003: Pg 37
0700-9000-0002-0001: Pg 37
0700-9100-0001-0003: Pg 37
0700-9100-0002-0001: Pg 37
0700-9200-0001-0001: Pg 38
0700-9200-0002-0002: Pg 38
0700-9200-0002-0003: Pg 38
0700-9300-0001-0001: Pg 38
0700-9300-0002-0002: Pg 38
0700-9300-0002-0003: Pg 38
0700-9400-0001-0001: Pg 38
0700-9500-0001-0001: Pg 38
0700-9600-0001-0001: Pg 39
0700-9600-0001-0003: Pg 39
0700-9600-0002-0002: Pg 39
0700-9700-0003-0001: Pg 39
0700-9800-0002-0001: Pg 40
0701-0100-0001-0005: Pg 17
0701-0100-0002-0002: Pg 18
0701-0100-0002-0007: Pg 18
0701-2000-0001-0081: Pg 19
0701-2000-0001-0083: Pg 19
0701-2000-0001-0084: Pg 19
0701-2000-0001-0086: Pg 20
0701-2000-0002-0001: Pg 20
0701-2000-0002-0002: Pg 21
0701-2000-0002-0003: Pg 21
0701-2000-0002-0004: Pg 22
0701-2000-0002-0005: Pg 22
0701-2000-0002-0006: Pg 23
0701-2000-0002-0010: Pg 23
0701-2000-0002-0011: Pg 24
0701-2000-0002-0012: Pg 24
0701-2000-0002-0013: Pg 25
0701-2000-0002-0014: Pg 25
0701-2000-0002-0015: Pg 26
0701-2000-0002-0016: Pg 26
0701-2000-0002-0017: Pg 27
0701-2000-0002-0018: Pg 27
0701-2000-0002-0019: Pg 28
0701-2000-0002-0021: Pg 28
0701-2000-0002-0022: Pg 29
0701-2000-0002-0023: Pg 29
0701-2000-0002-0024: Pg 30
0701-2000-0002-0025: Pg 30
0701-2000-0003-0001: Pg 31
0701-2000-0003-0002: Pg 31
0701-2100-0001-0081: Pg 19
0701-2100-0001-0083: Pg 19
0701-2100-0001-0084: Pg 19
0701-2100-0001-0086: Pg 20
0701-2100-0002-0001: Pg 20
0701-2100-0002-0002: Pg 21
0701-2100-0002-0003: Pg 21
0701-2100-0002-0004: Pg 22
0701-2100-0002-0005: Pg 22
0701-2100-0002-0006: Pg 23
0701-2100-0002-0010: Pg 23
0701-2100-0002-0011: Pg 24
0701-2100-0002-0012: Pg 24
0701-2100-0002-0013: Pg 25
0701-2100-0002-0014: Pg 25
0701-2100-0002-0015: Pg 26
0701-2100-0002-0016: Pg 26
0701-2100-0002-0017: Pg 27
0701-2100-0002-0018: Pg 27
0701-2100-0002-0019: Pg 28
0701-2100-0002-0021: Pg 28
0701-2100-0002-0022: Pg 29
0701-2100-0002-0023: Pg 29
0701-2100-0002-0024: Pg 30
0701-2100-0002-0025: Pg 30
0701-2100-0003-0001: Pg 31
0701-2100-0003-0002: Pg 31
0701-2200-0001-0081: Pg 19
0701-2200-0001-0083: Pg 19
0701-2200-0001-0084: Pg 19
0701-2200-0001-0086: Pg 20
0701-2200-0002-0001: Pg 20
0701-2200-0002-0002: Pg 21
0701-2200-0002-0003: Pg 21
0701-2200-0002-0004: Pg 22
0701-2200-0002-0005: Pg 22
0701-2200-0002-0006: Pg 23
0701-2200-0002-0010: Pg 23
0701-2200-0002-0011: Pg 24
0701-2200-0002-0012: Pg 24
0701-2200-0002-0013: Pg 25
0701-2200-0002-0014: Pg 25
0701-2200-0002-0015: Pg 26
0701-2200-0002-0016: Pg 26
0701-2200-0002-0017: Pg 27
0701-2200-0002-0018: Pg 27
0701-2200-0002-0019: Pg 28
0701-2200-0002-0021: Pg 28
0701-2200-0002-0022: Pg 29
0701-2200-0002-0023: Pg 29
0701-2200-0002-0024: Pg 30
0701-2200-0002-0025: Pg 30
0701-2200-0003-0001: Pg 31
0701-2200-0003-0002: Pg 31
0701-2300-0001-0081: Pg 19
0701-2300-0001-0083: Pg 19
0701-2300-0001-0084: Pg 19
0701-2300-0001-0086: Pg 20
0701-2300-0002-0001: Pg 20
0701-2300-0002-0002: Pg 21
0701-2300-0002-0003: Pg 21
0701-2300-0002-0004: Pg 22
0701-2300-0002-0005: Pg 22
0701-2300-0002-0006: Pg 23
0701-2300-0002-0010: Pg 23
0701-2300-0002-0011: Pg 24
0701-2300-0002-0012: Pg 24
0701-2300-0002-0013: Pg 25
0701-2300-0002-0014: Pg 25
0701-2300-0002-0015: Pg 26
0701-2300-0002-0016: Pg 26
0701-2300-0002-0017: Pg 27
0701-2300-0002-0018: Pg 27
0701-2300-0002-0019: Pg 28
0701-2300-0002-0021: Pg 28
0701-2300-0002-0022: Pg 29
0701-2300-0002-0023: Pg 29
0701-2300-0002-0024: Pg 30
0701-2300-0002-0025: Pg 30
0701-2300-0003-0001: Pg 31
0701-2300-0003-0002: Pg 31
0701-4000-0002-0001: Pg 31
0701-5000-0002-0001: Pg 33
0701-7000-0002-0001: Pg 33
0701-7000-0002-0001: Pg 34
0701-7000-0002-0002: Pg 34
0701-7000-0002-0003: Pg 34
0701-7000-0002-0004: Pg 35
0701-7000-0002-0005: Pg 35
0701-7000-0002-0007: Pg 36
0701-7000-0002-0008: Pg 36
0701-7100-0002-0001: Pg 33
0701-7100-0002-0002: Pg 34
0701-7100-0002-0004: Pg 35
0701-7100-0002-0005: Pg 35
0701-7200-0002-0001: Pg 33
0701-7200-0002-0002: Pg 34
0701-7200-0002-0004: Pg 35
0701-7200-0002-0005: Pg 35
0701-7300-0002-0001: Pg 33
0701-7300-0002-0002: Pg 34
0701-7300-0002-0004: Pg 35
0701-7300-0002-0005: Pg 35
0701-8000-0001-0001: Pg 36
0701-8000-0001-0002: Pg 36
0701-8000-0001-0003: Pg 37
0701-8000-0001-0004: Pg 37
0701-8100-0001-0001: Pg 36
0701-8100-0001-0002: Pg 36
0701-8100-0001-0003: Pg 37
0701-8100-0001-0004: Pg 37
0701-9000-0001-0003: Pg 37
0701-9000-0002-0001: Pg 37
0701-9100-0001-0003: Pg 37
0701-9100-0002-0001: Pg 37
0701-9200-0001-0001: Pg 38
0701-9200-0002-0002: Pg 38
0701-9200-0002-0003: Pg 38
0701-9300-0001-0001: Pg 38
0701-9300-0002-0002: Pg 38
0701-9300-0002-0003: Pg 38
0701-9400-0001-0001: Pg 38
0701-9500-0001-0001: Pg 38
0701-9600-0001-0001: Pg 39
0701-9600-0001-0003: Pg 39
0701-9600-0002-0002: Pg 39
0701-9700-0003-0001: Pg 39
0701-9800-0002-0001: Pg 40
0702-0100-0001-0005: Pg 17
0702-0100-0002-0002: Pg 18
0702-0100-0002-0007: Pg 18
0702-2000-0001-0081: Pg 19
0702-2000-0001-0083: Pg 19
0702-2000-0001-0084: Pg 19
0702-2000-0001-0086: Pg 20
0702-2000-0002-0001: Pg 20
0702-2000-0002-0002: Pg 21
0702-2000-0002-0003: Pg 21
0702-2000-0002-0004: Pg 22
0702-2000-0002-0005: Pg 22
0702-2000-0002-0006: Pg 23
0702-2000-0002-0010: Pg 23
0702-2000-0002-0011: Pg 24
0702-2000-0002-0012: Pg 24
0702-2000-0002-0013: Pg 25
0702-2000-0002-0014: Pg 25
0702-2000-0002-0015: Pg 26
0702-2000-0002-0016: Pg 26
0702-2000-0002-0017: Pg 27
0702-2000-0002-0018: Pg 27
0702-2000-0002-0019: Pg 28
0702-2000-0002-0021: Pg 28
0702-2000-0002-0022: Pg 29
0702-2000-0002-0023: Pg 29
0702-2000-0002-0024: Pg 30
0702-2000-0002-0025: Pg 30
0702-2000-0003-0001: Pg 31
0702-2000-0003-0002: Pg 31
0702-2100-0001-0081: Pg 19
0702-2100-0001-0083: Pg 19
0702-2100-0001-0084: Pg 19
0702-2100-0001-0086: Pg 20
0702-2100-0002-0001: Pg 20
0702-2100-0002-0002: Pg 21
0702-2100-0002-0003: Pg 21
0702-2100-0002-0004: Pg 22
0702-2100-0002-0005: Pg 22
0702-2100-0002-0006: Pg 23
0702-2100-0002-0010: Pg 23
0702-2100-0002-0011: Pg 24
0702-2100-0002-0012: Pg 24
0702-2100-0002-0013: Pg 25
0702-2100-0002-0014: Pg 25
0702-2100-0002-0015: Pg 26
0702-2100-0002-0016: Pg 26
0702-2100-0002-0017: Pg 27
0702-2100-0002-0018: Pg 27
0702-2100-0002-0019: Pg 28
0702-2100-0002-0021: Pg 28
0702-2100-0002-0022: Pg 29
0702-2100-0002-0023: Pg 29
0702-2100-0002-0024: Pg 30
0702-2100-0002-0025: Pg 30
0702-2100-0003-0001: Pg 31
0702-2100-0003-0002: Pg 31
0702-2200-0001-0081: Pg 19
0702-2200-0001-0083: Pg 19
0702-2200-0001-0084: Pg 19
0702-2200-0001-0086: Pg 20
0702-2200-0002-0001: Pg 20
0702-2200-0002-0002: Pg 21
0702-2200-0002-0003: Pg 21
0702-2200-0002-0004: Pg 22
0702-2200-0002-0005: Pg 22
0702-2200-0002-0006: Pg 23
0702-2200-0002-0010: Pg 23
0702-2200-0002-0011: Pg 24
0702-2200-0002-0012: Pg 24
0702-2200-0002-0013: Pg 25
0702-2200-0002-0014: Pg 25
0702-2200-0002-0015: Pg 26
0702-2200-0002-0016: Pg 26
0702-2200-0002-0017: Pg 27
0702-2200-0002-0018: Pg 27
0702-2200-0002-0019: Pg 28
0702-2200-0002-0021: Pg 28
0702-2200-0002-0022: Pg 29
0702-2200-0002-0023: Pg 29
0702-2200-0002-0024: Pg 30
0702-2200-0002-0025: Pg 30
0702-2200-0003-0001: Pg 31
0702-2200-0003-0002: Pg 31
0702-2300-0001-0081: Pg 19
0702-2300-0001-0083: Pg 19
0702-2300-0001-0084: Pg 19
0702-2300-0001-0086: Pg 20
0702-2300-0002-0001: Pg 20
0702-2300-0002-0002: Pg 21

0702-2300-0002-0003: Pg 21
0702-2300-0002-0004: Pg 22
0702-2300-0002-0005: Pg 22
0702-2300-0002-0006: Pg 23
0702-2300-0002-0010: Pg 23
0702-2300-0002-0011: Pg 24
0702-2300-0002-0012: Pg 24
0702-2300-0002-0013: Pg 25
0702-2300-0002-0014: Pg 25
0702-2300-0002-0015: Pg 26
0702-2300-0002-0016: Pg 26
0702-2300-0002-0017: Pg 27
0702-2300-0002-0018: Pg 27
0702-2300-0002-0019: Pg 28
0702-2300-0002-0021: Pg 28
0702-2300-0002-0022: Pg 29
0702-2300-0002-0023: Pg 29
0702-2300-0002-0024: Pg 30
0702-2300-0002-0025: Pg 30
0702-2300-0003-0001: Pg 31
0702-2300-0003-0002: Pg 31
0702-4000-0002-0001: Pg 31
0702-5000-0002-0001: Pg 33
0702-7000-0002-0001: Pg 33
0702-7000-0002-0001: Pg 34
0702-7000-0002-0002: Pg 34
0702-7000-0002-0003: Pg 34
0702-7000-0002-0004: Pg 35
0702-7000-0002-0005: Pg 35
0702-7000-0002-0007: Pg 36
0702-7000-0002-0008: Pg 36
0702-7100-0002-0001: Pg 33
0702-7100-0002-0002: Pg 34
0702-7100-0002-0004: Pg 35
0702-7100-0002-0005: Pg 35
0702-7200-0002-0001: Pg 33
0702-7200-0002-0002: Pg 34
0702-7200-0002-0004: Pg 35
0702-7200-0002-0005: Pg 35
0702-7300-0002-0001: Pg 33
0702-7300-0002-0002: Pg 34
0702-7300-0002-0004: Pg 35
0702-7300-0002-0005: Pg 35
0702-8000-0001-0001: Pg 36
0702-8000-0001-0002: Pg 36
0702-8000-0001-0003: Pg 37
0702-8000-0001-0004: Pg 37
0702-8100-0001-0001: Pg 36
0702-8100-0001-0002: Pg 36
0702-8100-0001-0003: Pg 37
0702-8100-0001-0004: Pg 37
0702-9000-0001-0003: Pg 37
0702-9000-0002-0001: Pg 37
0702-9100-0001-0003: Pg 37
0702-9100-0002-0001: Pg 37
0702-9200-0001-0001: Pg 38
0702-9200-0002-0002: Pg 38
0702-9200-0002-0003: Pg 38
0702-9300-0001-0001: Pg 38
0702-9300-0002-0002: Pg 38
0702-9300-0002-0003: Pg 38
0702-9400-0001-0001: Pg 38
0702-9500-0001-0001: Pg 38
0702-9600-0001-0001: Pg 39
0702-9600-0001-0003: Pg 39
0702-9600-0002-0002: Pg 39
0702-9700-0003-0001: Pg 39
0702-9800-0002-0001: Pg 40
0703-0100-0001-0005: Pg 17
0703-0100-0002-0002: Pg 18
0703-0100-0002-0007: Pg 18
0703-2000-0001-0081: Pg 19
0703-2000-0001-0083: Pg 19
0703-2000-0001-0084: Pg 19
0703-2000-0002-0001: Pg 20
0703-2000-0002-0002: Pg 21
0703-2000-0002-0003: Pg 21
0703-2000-0002-0004: Pg 22
0703-2000-0002-0005: Pg 22
0703-2000-0002-0006: Pg 23
0703-2000-0002-0010: Pg 23
0703-2000-0002-0011: Pg 24
0703-2000-0002-0012: Pg 24
0703-2000-0002-0013: Pg 25
0703-2000-0002-0014: Pg 25
0703-2000-0002-0015: Pg 26
0703-2000-0002-0016: Pg 26
0703-2000-0002-0017: Pg 27
0703-2000-0002-0018: Pg 27
0703-2000-0002-0019: Pg 28
0703-2000-0002-0021: Pg 28
0703-2000-0002-0022: Pg 29
0703-2000-0002-0023: Pg 29
0703-2000-0002-0024: Pg 30
0703-2000-0002-0025: Pg 30
0703-2000-0003-0001: Pg 31
0703-2000-0003-0002: Pg 31
0703-2100-0001-0081: Pg 19
0703-2100-0001-0083: Pg 19
0703-2100-0001-0084: Pg 19
0703-2100-0002-0001: Pg 20
0703-2100-0002-0002: Pg 21
0703-2100-0002-0003: Pg 21
0703-2100-0002-0004: Pg 22
0703-2100-0002-0005: Pg 22
0703-2100-0002-0006: Pg 23
0703-2100-0002-0010: Pg 23
0703-2100-0002-0011: Pg 24
0703-2100-0002-0012: Pg 24
0703-2100-0002-0013: Pg 25
0703-2100-0002-0014: Pg 25
0703-2100-0002-0015: Pg 26
0703-2100-0002-0016: Pg 26
0703-2100-0002-0017: Pg 27
0703-2100-0002-0018: Pg 27
0703-2100-0002-0019: Pg 28
0703-2100-0002-0021: Pg 28
0703-2100-0002-0022: Pg 29
0703-2100-0002-0023: Pg 29
0703-2100-0002-0024: Pg 30
0703-2100-0002-0025: Pg 30
0703-2100-0003-0001: Pg 31
0703-2100-0003-0002: Pg 31
0703-2200-0001-0081: Pg 19
0703-2200-0001-0083: Pg 19
0703-2200-0001-0084: Pg 19
0703-2200-0002-0001: Pg 20
0703-2200-0002-0002: Pg 21
0703-2200-0002-0003: Pg 21
0703-2200-0002-0004: Pg 22
0703-2200-0002-0005: Pg 22
0703-2200-0002-0006: Pg 23
0703-2200-0002-0010: Pg 23
0703-2200-0002-0011: Pg 24
0703-2200-0002-0012: Pg 24
0703-2200-0002-0013: Pg 25
0703-2200-0002-0014: Pg 25
0703-2200-0002-0015: Pg 26
0703-2200-0002-0016: Pg 26
0703-2200-0002-0017: Pg 27
0703-2200-0002-0018: Pg 27
0703-2200-0002-0019: Pg 28
0703-2200-0002-0021: Pg 28
0703-2200-0002-0022: Pg 29
0703-2200-0002-0023: Pg 29
0703-2200-0002-0024: Pg 30
0703-2200-0002-0025: Pg 30
0703-2200-0003-0001: Pg 31
0703-2200-0003-0002: Pg 31
0703-2300-0001-0081: Pg 19
0703-2300-0001-0083: Pg 19
0703-2300-0001-0084: Pg 19
0703-2300-0002-0001: Pg 20
0703-2300-0002-0002: Pg 21
0703-2300-0002-0003: Pg 21
0703-2300-0002-0004: Pg 22
0703-2300-0002-0005: Pg 22
0703-2300-0002-0006: Pg 23
0703-2300-0002-0010: Pg 23
0703-2300-0002-0011: Pg 24
0703-2300-0002-0012: Pg 24
0703-2300-0002-0013: Pg 25
0703-2300-0002-0014: Pg 25
0703-2300-0002-0015: Pg 26
0703-2300-0002-0016: Pg 26
0703-2300-0002-0017: Pg 27
0703-2300-0002-0018: Pg 27
0703-2300-0002-0019: Pg 28
0703-2300-0002-0021: Pg 28
0703-2300-0002-0022: Pg 29
0703-2300-0002-0023: Pg 29
0703-2300-0002-0024: Pg 30
0703-2300-0002-0025: Pg 30
0703-2300-0003-0001: Pg 31
0703-2300-0003-0002: Pg 31
0703-4000-0002-0001: Pg 31
0703-5000-0002-0001: Pg 33
0703-7000-0002-0001: Pg 33
0703-7000-0002-0001: Pg 34
0703-7000-0002-0002: Pg 34
0703-7000-0002-0003: Pg 34
0703-7000-0002-0004: Pg 35
0703-7000-0002-0005: Pg 35
0703-7000-0002-0007: Pg 36
0703-7000-0002-0008: Pg 36
0703-7100-0002-0001: Pg 33
0703-7100-0002-0002: Pg 34
0703-7100-0002-0004: Pg 35
0703-7100-0002-0005: Pg 35
0703-7200-0002-0001: Pg 33
0703-7200-0002-0002: Pg 34
0703-7200-0002-0004: Pg 35
0703-7200-0002-0005: Pg 35
0703-7300-0002-0001: Pg 33
0703-7300-0002-0002: Pg 34
0703-7300-0002-0004: Pg 35
0703-7300-0002-0005: Pg 35
0703-8000-0001-0001: Pg 36
0703-8000-0001-0002: Pg 36
0703-8000-0001-0003: Pg 37
0703-8000-0001-0004: Pg 37
0703-8100-0001-0001: Pg 36
0703-8100-0001-0002: Pg 36
0703-8100-0001-0003: Pg 37
0703-8100-0001-0004: Pg 37
0703-9000-0001-0003: Pg 37
0703-9000-0002-0001: Pg 37
0703-9100-0001-0003: Pg 37
0703-9100-0002-0001: Pg 37
0703-9200-0001-0001: Pg 38
0703-9200-0002-0002: Pg 38
0703-9200-0002-0003: Pg 38
0703-9300-0001-0001: Pg 38
0703-9300-0002-0002: Pg 38
0703-9300-0002-0003: Pg 38
0703-9400-0001-0001: Pg 38
0703-9500-0001-0001: Pg 38
0703-9600-0001-0001: Pg 39
0703-9600-0001-0003: Pg 39
0703-9600-0002-0002: Pg 39
0703-9700-0003-0001: Pg 39
0703-9800-0002-0001: Pg 40
0704-0100-0001-0005: Pg 17
0704-2000-0002-0001: Pg 20
0704-2000-0002-0002: Pg 21
0704-2000-0002-0003: Pg 21
0704-2000-0002-0004: Pg 22
0704-2000-0002-0005: Pg 22
0704-2000-0002-0006: Pg 23
0704-2000-0002-0011: Pg 24
0704-2000-0002-0012: Pg 24
0704-2000-0002-0013: Pg 25
0704-2000-0002-0014: Pg 25
0704-2000-0002-0015: Pg 26
0704-2000-0002-0016: Pg 26
0704-2000-0002-0017: Pg 27
0704-2000-0002-0018: Pg 27
0704-2000-0002-0019: Pg 28
0704-2000-0002-0021: Pg 28
0704-2000-0002-0022: Pg 29
0704-2000-0002-0024: Pg 30
0704-2000-0002-0025: Pg 30
0704-2100-0002-0001: Pg 20
0704-2100-0002-0002: Pg 21
0704-2100-0002-0003: Pg 21
0704-2100-0002-0004: Pg 22
0704-2100-0002-0005: Pg 22
0704-2100-0002-0006: Pg 23
0704-2100-0002-0011: Pg 24
0704-2100-0002-0012: Pg 24
0704-2100-0002-0013: Pg 25
0704-2100-0002-0014: Pg 25
0704-2100-0002-0015: Pg 26
0704-2100-0002-0016: Pg 26
0704-2100-0002-0017: Pg 27
0704-2100-0002-0018: Pg 27
0704-2100-0002-0019: Pg 28
0704-2100-0002-0021: Pg 28
0704-2100-0002-0022: Pg 29
0704-2100-0002-0024: Pg 30
0704-2100-0002-0025: Pg 30
0704-2200-0002-0001: Pg 20
0704-2200-0002-0002: Pg 21
0704-2200-0002-0003: Pg 21
0704-2200-0002-0004: Pg 22
0704-2200-0002-0005: Pg 22
0704-2200-0002-0006: Pg 23
0704-2200-0002-0011: Pg 24
0704-2200-0002-0012: Pg 24
0704-2200-0002-0013: Pg 25
0704-2200-0002-0014: Pg 25
0704-2200-0002-0015: Pg 26
0704-2200-0002-0016: Pg 26
0704-2200-0002-0017: Pg 27
0704-2200-0002-0018: Pg 27
0704-2200-0002-0019: Pg 28
0704-2200-0002-0021: Pg 28
0704-2200-0002-0022: Pg 29
0704-2200-0002-0024: Pg 30
0704-2200-0002-0025: Pg 30
0704-2300-0002-0001: Pg 20
0704-2300-0002-0002: Pg 21
0704-2300-0002-0003: Pg 21
0704-2300-0002-0004: Pg 22
0704-2300-0002-0005: Pg 22
0704-2300-0002-0006: Pg 23
0704-2300-0002-0011: Pg 24
0704-2300-0002-0012: Pg 24
0704-2300-0002-0013: Pg 25
0704-2300-0002-0014: Pg 25
0704-2300-0002-0015: Pg 26
0704-2300-0002-0016: Pg 26

0704-2300-0002-0017: Pg 27
0704-2300-0002-0018: Pg 27
0704-2300-0002-0019: Pg 28
0704-2300-0002-0021: Pg 28
0704-2300-0002-0022: Pg 29
0704-2300-0002-0024: Pg 30
0704-2300-0002-0025: Pg 30
0704-7000-0002-0001: Pg 33
0704-7000-0002-0002: Pg 34
0704-7000-0002-0003: Pg 34
0704-7000-0002-0004: Pg 35
0704-7000-0002-0005: Pg 35
0704-7000-0002-0008: Pg 36
0704-7100-0002-0001: Pg 33
0704-7100-0002-0002: Pg 34
0704-7100-0002-0004: Pg 35
0704-7100-0002-0005: Pg 35
0704-7200-0002-0001: Pg 33
0704-7200-0002-0002: Pg 34
0704-7200-0002-0004: Pg 35
0704-7200-0002-0005: Pg 35
0704-7300-0002-0004: Pg 35
0704-7300-0002-0005: Pg 35
0704-9000-0001-0003: Pg 37
0704-9000-0002-0001: Pg 37
0704-9100-0001-0003: Pg 37
0704-9100-0002-0001: Pg 37
0704-9600-0001-0001: Pg 39
0704-9600-0001-0003: Pg 39
0704-9600-0002-0002: Pg 39
0705-0100-0001-0005: Pg 17
0705-2000-0002-0001: Pg 20
0705-2000-0002-0002: Pg 21
0705-2000-0002-0003: Pg 21
0705-2000-0002-0004: Pg 22
0705-2000-0002-0005: Pg 22
0705-2000-0002-0006: Pg 23
0705-2000-0002-0011: Pg 24
0705-2000-0002-0012: Pg 24
0705-2000-0002-0013: Pg 25
0705-2000-0002-0014: Pg 25
0705-2000-0002-0015: Pg 26
0705-2000-0002-0016: Pg 26
0705-2000-0002-0017: Pg 27
0705-2000-0002-0018: Pg 27
0705-2000-0002-0019: Pg 28
0705-2000-0002-0021: Pg 28
0705-2000-0002-0022: Pg 29
0705-2000-0002-0024: Pg 30
0705-2000-0002-0025: Pg 30
0705-2100-0002-0001: Pg 20
0705-2100-0002-0002: Pg 21
0705-2100-0002-0003: Pg 21
0705-2100-0002-0004: Pg 22
0705-2100-0002-0005: Pg 22
0705-2100-0002-0006: Pg 23
0705-2100-0002-0011: Pg 24
0705-2100-0002-0012: Pg 24
0705-2100-0002-0013: Pg 25
0705-2100-0002-0014: Pg 25
0705-2100-0002-0015: Pg 26
0705-2100-0002-0016: Pg 26
0705-2100-0002-0017: Pg 27
0705-2100-0002-0018: Pg 27
0705-2100-0002-0019: Pg 28
0705-2100-0002-0021: Pg 28
0705-2100-0002-0022: Pg 29
0705-2100-0002-0024: Pg 30
0705-2100-0002-0025: Pg 30
0705-2200-0002-0001: Pg 20
0705-2200-0002-0002: Pg 21
0705-2200-0002-0003: Pg 21
0705-2200-0002-0004: Pg 22
0705-2200-0002-0005: Pg 22
0705-2200-0002-0006: Pg 23
0705-2200-0002-0011: Pg 24
0705-2200-0002-0012: Pg 24
0705-2200-0002-0013: Pg 25
0705-2200-0002-0014: Pg 25
0705-2200-0002-0015: Pg 26
0705-2200-0002-0016: Pg 26
0705-2200-0002-0017: Pg 27
0705-2200-0002-0018: Pg 27
0705-2200-0002-0019: Pg 28
0705-2200-0002-0021: Pg 28
0705-2200-0002-0022: Pg 29
0705-2200-0002-0024: Pg 30
0705-2200-0002-0025: Pg 30
0705-2300-0002-0001: Pg 20
0705-2300-0002-0002: Pg 21
0705-2300-0002-0003: Pg 21
0705-2300-0002-0004: Pg 22
0705-2300-0002-0005: Pg 22
0705-2300-0002-0006: Pg 23
0705-2300-0002-0011: Pg 24
0705-2300-0002-0012: Pg 24
0705-2300-0002-0013: Pg 25
0705-2300-0002-0014: Pg 25
0705-2300-0002-0015: Pg 26
0705-2300-0002-0016: Pg 26
0705-2300-0002-0017: Pg 27
0705-2300-0002-0018: Pg 27
0705-2300-0002-0019: Pg 28
0705-2300-0002-0021: Pg 28
0705-2300-0002-0022: Pg 29
0705-2300-0002-0024: Pg 30
0705-2300-0002-0025: Pg 30
0705-7000-0002-0001: Pg 33
0705-7000-0002-0002: Pg 34
0705-7000-0002-0003: Pg 34
0705-7000-0002-0004: Pg 35
0705-7000-0002-0005: Pg 35
0705-7000-0002-0008: Pg 36
0705-7100-0002-0001: Pg 33
0705-7100-0002-0002: Pg 34
0705-7100-0002-0004: Pg 35
0705-7100-0002-0005: Pg 35
0705-7200-0002-0001: Pg 33
0705-7200-0002-0002: Pg 34
0705-7200-0002-0004: Pg 35
0705-7200-0002-0005: Pg 35
0705-7300-0002-0001: Pg 33
0705-7300-0002-0002: Pg 34
0705-7300-0002-0004: Pg 35
0705-7300-0002-0005: Pg 35
0705-9000-0001-0003: Pg 37
0705-9000-0002-0001: Pg 37
0705-9100-0001-0003: Pg 37
0705-9100-0002-0001: Pg 37
0705-9600-0001-0001: Pg 39
0705-9600-0001-0003: Pg 39
0705-9600-0002-0002: Pg 39
0706-0100-0001-0005: Pg 17
0706-2000-0002-0001: Pg 20
0706-2000-0002-0002: Pg 21
0706-2000-0002-0003: Pg 21
0706-2000-0002-0004: Pg 22
0706-2000-0002-0005: Pg 22
0706-2000-0002-0006: Pg 23
0706-2000-0002-0011: Pg 24
0706-2000-0002-0012: Pg 24
0706-2000-0002-0013: Pg 25
0706-2000-0002-0014: Pg 25
0706-2000-0002-0015: Pg 26
0706-2000-0002-0016: Pg 26
0706-2000-0002-0017: Pg 27
0706-2000-0002-0018: Pg 27
0706-2000-0002-0019: Pg 28
0706-2000-0002-0021: Pg 28
0706-2000-0002-0022: Pg 29
0706-2000-0002-0024: Pg 30
0706-2000-0002-0025: Pg 30
0706-2100-0002-0001: Pg 20
0706-2100-0002-0002: Pg 21
0706-2100-0002-0003: Pg 21
0706-2100-0002-0004: Pg 22
0706-2100-0002-0005: Pg 22
0706-2100-0002-0006: Pg 23
0706-2100-0002-0011: Pg 24
0706-2100-0002-0012: Pg 24
0706-2100-0002-0013: Pg 25
0706-2100-0002-0014: Pg 25
0706-2100-0002-0015: Pg 26
0706-2100-0002-0016: Pg 26
0706-2100-0002-0017: Pg 27
0706-2100-0002-0018: Pg 27
0706-2100-0002-0019: Pg 28
0706-2100-0002-0021: Pg 28
0706-2100-0002-0022: Pg 29
0706-2100-0002-0024: Pg 30
0706-2100-0002-0025: Pg 30
0706-2200-0002-0001: Pg 20
0706-2200-0002-0002: Pg 21
0706-2200-0002-0003: Pg 21
0706-2200-0002-0004: Pg 22
0706-2200-0002-0005: Pg 22
0706-2200-0002-0006: Pg 23
0706-2200-0002-0011: Pg 24
0706-2200-0002-0012: Pg 24
0706-2200-0002-0013: Pg 25
0706-2200-0002-0014: Pg 25
0706-2200-0002-0015: Pg 26
0706-2200-0002-0016: Pg 26
0706-2200-0002-0017: Pg 27
0706-2200-0002-0018: Pg 27
0706-2200-0002-0019: Pg 28
0706-2200-0002-0021: Pg 28
0706-2200-0002-0022: Pg 29
0706-2200-0002-0024: Pg 30
0706-2200-0002-0025: Pg 30
0706-2300-0002-0001: Pg 20
0706-2300-0002-0002: Pg 21
0706-2300-0002-0003: Pg 21
0706-2300-0002-0004: Pg 22
0706-2300-0002-0005: Pg 22
0706-2300-0002-0006: Pg 23
0706-2300-0002-0011: Pg 24
0706-2300-0002-0012: Pg 24
0706-2300-0002-0013: Pg 25
0706-2300-0002-0014: Pg 25
0706-2300-0002-0015: Pg 26
0706-2300-0002-0016: Pg 26
0706-2300-0002-0017: Pg 27
0706-2300-0002-0018: Pg 27
0706-2300-0002-0019: Pg 28
0706-2300-0002-0021: Pg 28
0706-2300-0002-0022: Pg 29
0706-2300-0002-0024: Pg 30
0706-2300-0002-0025: Pg 30
0706-7000-0002-0001: Pg 33
0706-7000-0002-0002: Pg 34
0706-7000-0002-0003: Pg 34
0706-7000-0002-0004: Pg 35
0706-7000-0002-0005: Pg 35
0706-7000-0002-0008: Pg 36
0706-7100-0002-0001: Pg 33
0706-7100-0002-0002: Pg 34
0706-7100-0002-0004: Pg 35
0706-7100-0002-0005: Pg 35
0706-7200-0002-0001: Pg 33
0706-7200-0002-0002: Pg 34
0706-7200-0002-0004: Pg 35
0706-7200-0002-0005: Pg 35
0706-7300-0002-0001: Pg 33
0706-7300-0002-0002: Pg 34
0706-7300-0002-0004: Pg 35
0706-7300-0002-0005: Pg 35
0706-9000-0001-0003: Pg 37
0706-9000-0002-0001: Pg 37
0706-9100-0001-0003: Pg 37
0706-9100-0002-0001: Pg 37
0706-9600-0001-0001: Pg 39
0706-9600-0001-0003: Pg 39
0706-9600-0002-0002: Pg 39
0707-0100-0001-0005: Pg 17
0707-2000-0002-0001: Pg 20
0707-2000-0002-0002: Pg 21
0707-2000-0002-0003: Pg 21
0707-2000-0002-0004: Pg 22
0707-2000-0002-0005: Pg 22
0707-2000-0002-0006: Pg 23
0707-2000-0002-0011: Pg 24
0707-2000-0002-0012: Pg 24
0707-2000-0002-0013: Pg 25
0707-2000-0002-0014: Pg 25
0707-2000-0002-0015: Pg 26
0707-2000-0002-0016: Pg 26
0707-2000-0002-0017: Pg 27
0707-2000-0002-0018: Pg 27
0707-2000-0002-0019: Pg 28
0707-2000-0002-0021: Pg 28
0707-2000-0002-0022: Pg 29
0707-2000-0002-0024: Pg 30
0707-2000-0002-0025: Pg 30
0707-2100-0002-0001: Pg 20
0707-2100-0002-0002: Pg 21
0707-2100-0002-0003: Pg 21
0707-2100-0002-0004: Pg 22
0707-2100-0002-0005: Pg 22
0707-2100-0002-0006: Pg 23
0707-2100-0002-0011: Pg 24
0707-2100-0002-0012: Pg 24
0707-2100-0002-0013: Pg 25
0707-2100-0002-0014: Pg 25
0707-2100-0002-0015: Pg 26
0707-2100-0002-0016: Pg 26
0707-2100-0002-0017: Pg 27
0707-2100-0002-0018: Pg 27
0707-2100-0002-0019: Pg 28
0707-2100-0002-0021: Pg 28
0707-2100-0002-0022: Pg 29
0707-2100-0002-0024: Pg 30
0707-2100-0002-0025: Pg 30
0707-2200-0002-0001: Pg 20
0707-2200-0002-0002: Pg 21
0707-2200-0002-0003: Pg 21
0707-2200-0002-0004: Pg 22
0707-2200-0002-0005: Pg 22
0707-2200-0002-0006: Pg 23
0707-2200-0002-0011: Pg 24
0707-2200-0002-0012: Pg 24
0707-2200-0002-0013: Pg 25
0707-2200-0002-0014: Pg 25
0707-2200-0002-0015: Pg 26
0707-2200-0002-0016: Pg 26
0707-2200-0002-0017: Pg 27
0707-2200-0002-0018: Pg 27
0707-2200-0002-0019: Pg 28
0707-2200-0002-0021: Pg 28
0707-2200-0002-0022: Pg 29
0707-2200-0002-0024: Pg 30
0707-2200-0002-0025: Pg 30

0707-2300-0002-0001: Pg 20
0707-2300-0002-0002: Pg 21
0707-2300-0002-0003: Pg 21
0707-2300-0002-0004: Pg 22
0707-2300-0002-0005: Pg 22
0707-2300-0002-0006: Pg 23
0707-2300-0002-0011: Pg 24
0707-2300-0002-0012: Pg 24
0707-2300-0002-0013: Pg 25
0707-2300-0002-0014: Pg 25
0707-2300-0002-0015: Pg 26
0707-2300-0002-0016: Pg 26
0707-2300-0002-0017: Pg 27
0707-2300-0002-0018: Pg 27
0707-2300-0002-0019: Pg 28
0707-2300-0002-0021: Pg 28
0707-2300-0002-0022: Pg 29
0707-2300-0002-0024: Pg 30
0707-2300-0002-0025: Pg 30
0707-7000-0002-0001: Pg 33
0707-7000-0002-0002: Pg 34
0707-7000-0002-0003: Pg 34
0707-7000-0002-0004: Pg 35
0707-7000-0002-0005: Pg 35
0707-7000-0002-0008: Pg 36
0707-7100-0002-0001: Pg 33
0707-7100-0002-0002: Pg 34
0707-7100-0002-0004: Pg 35
0707-7100-0002-0005: Pg 35
0707-7200-0002-0001: Pg 33
0707-7200-0002-0002: Pg 34
0707-7200-0002-0004: Pg 35
0707-7200-0002-0005: Pg 35
0707-7300-0002-0001: Pg 33
0707-7300-0002-0002: Pg 34
0707-7300-0002-0004: Pg 35
0707-7300-0002-0005: Pg 35
0707-9000-0001-0003: Pg 37
0707-9000-0002-0001: Pg 37
0707-9100-0001-0003: Pg 37
0707-9100-0002-0001: Pg 37
0707-9600-0001-0001: Pg 39
0707-9600-0001-0003: Pg 39
0707-9600-0002-0002: Pg 39
07FE-7000-0002-0008: Pg 36
07FF-2000-0002-0001: Pg 40
07FF-2000-0002-0002: Pg 40
07FF-2000-0002-0004: Pg 40
07FF-7000-0002-0008: Pg 36
0C00-0100-0001-0004: Pg 41
0C00-0100-0001-0009: Pg 41
0C00-0100-0002-0008: Pg 41
0C00-0300-0003-0006: Pg 41
0C00-0300-0003-0008: Pg 41
1200-4500-0002-0003: Pg 32
1200-5000-0002-0001: Pg 33
1201-5000-0002-0001: Pg 33
1202-5000-0002-0001: Pg 33
1203-5000-0002-0001: Pg 33
1800-0100-0001-0005: Pg 17
1800-0100-0002-0007: Pg 18
1800-2000-0001-0081: Pg 19
1800-2000-0001-0083: Pg 19
1800-2000-0001-0084: Pg 19
1800-2000-0002-0001: Pg 20
1800-2000-0002-0002: Pg 21
1800-2000-0002-0003: Pg 21
1800-2000-0002-0004: Pg 22
1800-2000-0002-0005: Pg 22
1800-2000-0002-0006: Pg 23
1800-2000-0002-0010: Pg 23
1800-2000-0002-0011: Pg 24
1800-2000-0002-0012: Pg 24
1800-2000-0002-0013: Pg 25
1800-2000-0002-0014: Pg 25
1800-2000-0002-0015: Pg 26
1800-2000-0002-0016: Pg 26
1800-2000-0002-0017: Pg 27
1800-2000-0002-0018: Pg 27
1800-2000-0002-0019: Pg 28
1800-2000-0002-0021: Pg 28
1800-2000-0002-0022: Pg 29
1800-2000-0002-0023: Pg 29
1800-2000-0002-0024: Pg 30
1800-2000-0002-0025: Pg 30
1800-2100-0002-0001: Pg 20
1800-2100-0002-0002: Pg 21
1800-2100-0002-0003: Pg 21
1800-2100-0002-0004: Pg 22
1800-2100-0002-0005: Pg 22
1800-2100-0002-0006: Pg 23
1800-2100-0002-0011: Pg 24
1800-2100-0002-0012: Pg 24
1800-2100-0002-0013: Pg 25
1800-2100-0002-0014: Pg 25
1800-2100-0002-0015: Pg 26
1800-2100-0002-0016: Pg 26
1800-2100-0002-0017: Pg 27
1800-2100-0002-0018: Pg 27
1800-2100-0002-0019: Pg 28
1800-2100-0002-0021: Pg 28
1800-2100-0002-0022: Pg 29
1800-2100-0002-0024: Pg 30
1800-2100-0002-0025: Pg 30
1800-2200-0002-0001: Pg 20
1800-2200-0002-0002: Pg 21
1800-2200-0002-0003: Pg 21
1800-2200-0002-0004: Pg 22
1800-2200-0002-0005: Pg 22
1800-2200-0002-0006: Pg 23
1800-2200-0002-0011: Pg 24
1800-2200-0002-0012: Pg 24
1800-2200-0002-0013: Pg 25
1800-2200-0002-0014: Pg 25
1800-2200-0002-0015: Pg 26
1800-2200-0002-0016: Pg 26
1800-2200-0002-0017: Pg 27
1800-2200-0002-0018: Pg 27
1800-2200-0002-0019: Pg 28
1800-2200-0002-0021: Pg 28
1800-2200-0002-0022: Pg 29
1800-2200-0002-0024: Pg 30
1800-2200-0002-0025: Pg 30
1800-2300-0002-0001: Pg 20
1800-2300-0002-0002: Pg 21
1800-2300-0002-0003: Pg 21
1800-2300-0002-0004: Pg 22
1800-2300-0002-0005: Pg 22
1800-2300-0002-0006: Pg 23
1800-2300-0002-0011: Pg 24
1800-2300-0002-0012: Pg 24
1800-2300-0002-0013: Pg 25
1800-2300-0002-0014: Pg 25
1800-2300-0002-0015: Pg 26
1800-2300-0002-0016: Pg 26
1800-2300-0002-0017: Pg 27
1800-2300-0002-0018: Pg 27
1800-2300-0002-0019: Pg 28
1800-2300-0002-0021: Pg 28
1800-2300-0002-0022: Pg 29
1800-2300-0002-0024: Pg 30
1800-2300-0002-0025: Pg 30
1800-4000-0002-0001: Pg 31
1800-5000-0002-0001: Pg 33
1800-7000-0002-0001: Pg 33
1800-7000-0002-0002: Pg 34
1800-7000-0002-0003: Pg 34
1800-7000-0002-0004: Pg 35
1800-7000-0002-0005: Pg 35
1800-7000-0002-0007: Pg 42
1800-7000-0002-0008: Pg 36
1800-7003-0002-0007: Pg 42
1800-7100-0002-0001: Pg 33
1800-7100-0002-0002: Pg 34
1800-7100-0002-0004: Pg 35
1800-7100-0002-0005: Pg 35
1800-7200-0002-0001: Pg 33
1800-7200-0002-0002: Pg 34
1800-7200-0002-0004: Pg 35
1800-7200-0002-0005: Pg 35
1800-7300-0002-0001: Pg 33
1800-7300-0002-0002: Pg 34
1800-7300-0002-0004: Pg 35
1800-7300-0002-0005: Pg 35
1800-8000-0001-0001: Pg 36
1800-8000-0001-0002: Pg 36
1800-8000-0001-0003: Pg 37
1800-8000-0001-0004: Pg 37
1800-9000-0001-0003: Pg 37
1800-9000-0002-0001: Pg 37
1800-9200-0001-0001: Pg 38
1800-9200-0002-0002: Pg 38
1800-9200-0002-0003: Pg 38
1800-9400-0001-0001: Pg 38
1800-9600-0001-0001: Pg 39
1800-9600-0001-0003: Pg 39
1800-9600-0002-0002: Pg 39
1800-9700-0003-0001: Pg 39
1800-9800-0002-0001: Pg 40
1801-0100-0001-0005: Pg 17
1801-0100-0002-0007: Pg 18
1801-2000-0001-0081: Pg 19
1801-2000-0001-0083: Pg 19
1801-2000-0001-0084: Pg 19
1801-2000-0002-0001: Pg 20
1801-2000-0002-0002: Pg 21
1801-2000-0002-0003: Pg 21
1801-2000-0002-0004: Pg 22
1801-2000-0002-0005: Pg 22
1801-2000-0002-0006: Pg 23
1801-2000-0002-0010: Pg 23
1801-2000-0002-0011: Pg 24
1801-2000-0002-0012: Pg 24
1801-2000-0002-0013: Pg 25
1801-2000-0002-0014: Pg 25
1801-2000-0002-0015: Pg 26
1801-2000-0002-0016: Pg 26
1801-2000-0002-0017: Pg 27
1801-2000-0002-0018: Pg 27
1801-2000-0002-0019: Pg 28
1801-2000-0002-0021: Pg 28
1801-2000-0002-0022: Pg 29
1801-2000-0002-0023: Pg 29
1801-2000-0002-0024: Pg 30
1801-2000-0002-0025: Pg 30
1801-2100-0002-0001: Pg 20
1801-2100-0002-0002: Pg 21
1801-2100-0002-0003: Pg 21
1801-2100-0002-0004: Pg 22
1801-2100-0002-0005: Pg 22
1801-2100-0002-0006: Pg 23
1801-2100-0002-0011: Pg 24
1801-2100-0002-0012: Pg 24
1801-2100-0002-0013: Pg 25
1801-2100-0002-0014: Pg 25
1801-2100-0002-0015: Pg 26
1801-2100-0002-0016: Pg 26
1801-2100-0002-0017: Pg 27
1801-2100-0002-0018: Pg 27
1801-2100-0002-0019: Pg 28
1801-2100-0002-0021: Pg 28
1801-2100-0002-0022: Pg 29
1801-2100-0002-0024: Pg 30
1801-2100-0002-0025: Pg 30
1801-2200-0002-0001: Pg 20
1801-2200-0002-0002: Pg 21
1801-2200-0002-0003: Pg 21
1801-2200-0002-0004: Pg 22
1801-2200-0002-0005: Pg 22
1801-2200-0002-0006: Pg 23
1801-2200-0002-0011: Pg 24
1801-2200-0002-0012: Pg 24
1801-2200-0002-0013: Pg 25
1801-2200-0002-0014: Pg 25
1801-2200-0002-0015: Pg 26
1801-2200-0002-0016: Pg 26
1801-2200-0002-0017: Pg 27
1801-2200-0002-0018: Pg 27
1801-2200-0002-0019: Pg 28
1801-2200-0002-0021: Pg 28
1801-2200-0002-0022: Pg 29
1801-2200-0002-0024: Pg 30
1801-2200-0002-0025: Pg 30
1801-2300-0002-0001: Pg 20
1801-2300-0002-0002: Pg 21
1801-2300-0002-0003: Pg 21
1801-2300-0002-0004: Pg 22
1801-2300-0002-0005: Pg 22
1801-2300-0002-0006: Pg 23
1801-2300-0002-0011: Pg 24
1801-2300-0002-0012: Pg 24
1801-2300-0002-0013: Pg 25
1801-2300-0002-0014: Pg 25
1801-2300-0002-0015: Pg 26
1801-2300-0002-0016: Pg 26
1801-2300-0002-0017: Pg 27
1801-2300-0002-0018: Pg 27
1801-2300-0002-0019: Pg 28
1801-2300-0002-0021: Pg 28
1801-2300-0002-0022: Pg 29
1801-2300-0002-0024: Pg 30
1801-2300-0002-0025: Pg 30
1801-4000-0002-0001: Pg 31
1801-5000-0002-0001: Pg 33
1801-7000-0002-0001: Pg 33
1801-7000-0002-0002: Pg 34
1801-7000-0002-0003: Pg 34
1801-7000-0002-0004: Pg 35
1801-7000-0002-0005: Pg 35
1801-7000-0002-0007: Pg 42
1801-7000-0002-0008: Pg 36
1801-7100-0002-0001: Pg 33
1801-7100-0002-0002: Pg 34
1801-7100-0002-0004: Pg 35
1801-7100-0002-0005: Pg 35
1801-7200-0002-0001: Pg 33
1801-7200-0002-0002: Pg 34
1801-7200-0002-0004: Pg 35
1801-7200-0002-0005: Pg 35
1801-7300-0002-0001: Pg 33
1801-7300-0002-0002: Pg 34
1801-7300-0002-0004: Pg 35
1801-7300-0002-0005: Pg 35
1801-8000-0001-0001: Pg 36
1801-8000-0001-0002: Pg 36
1801-8000-0001-0003: Pg 37
1801-8000-0001-0004: Pg 37
1801-9000-0001-0003: Pg 37
1801-9000-0002-0001: Pg 37
1801-9200-0001-0001: Pg 38
1801-9200-0002-0002: Pg 38
1801-9200-0002-0003: Pg 38

1801-9400-0001-0001: Pg 38
1801-9600-0001-0001: Pg 39
1801-9600-0001-0003: Pg 39
1801-9600-0002-0002: Pg 39
1801-9700-0003-0001: Pg 39
1801-9800-0002-0001: Pg 40
1802-0100-0001-0005: Pg 17
1802-0100-0002-0007: Pg 18
1802-2000-0001-0081: Pg 19
1802-2000-0001-0083: Pg 19
1802-2000-0001-0084: Pg 19
1802-2000-0002-0001: Pg 20
1802-2000-0002-0002: Pg 21
1802-2000-0002-0003: Pg 21
1802-2000-0002-0004: Pg 22
1802-2000-0002-0005: Pg 22
1802-2000-0002-0006: Pg 23
1802-2000-0002-0010: Pg 23
1802-2000-0002-0011: Pg 24
1802-2000-0002-0012: Pg 24
1802-2000-0002-0013: Pg 25
1802-2000-0002-0014: Pg 25
1802-2000-0002-0015: Pg 26
1802-2000-0002-0016: Pg 26
1802-2000-0002-0017: Pg 27
1802-2000-0002-0018: Pg 27
1802-2000-0002-0019: Pg 28
1802-2000-0002-0021: Pg 28
1802-2000-0002-0022: Pg 29
1802-2000-0002-0023: Pg 29
1802-2000-0002-0024: Pg 30
1802-2000-0002-0025: Pg 30
1802-2100-0002-0001: Pg 20
1802-2100-0002-0002: Pg 21
1802-2100-0002-0003: Pg 21
1802-2100-0002-0004: Pg 22
1802-2100-0002-0005: Pg 22
1802-2100-0002-0006: Pg 23
1802-2100-0002-0011: Pg 24
1802-2100-0002-0012: Pg 24
1802-2100-0002-0013: Pg 25
1802-2100-0002-0014: Pg 25
1802-2100-0002-0015: Pg 26
1802-2100-0002-0016: Pg 26
1802-2100-0002-0017: Pg 27
1802-2100-0002-0018: Pg 27
1802-2100-0002-0019: Pg 28
1802-2100-0002-0021: Pg 28
1802-2100-0002-0022: Pg 29
1802-2100-0002-0024: Pg 30
1802-2100-0002-0025: Pg 30
1802-2200-0002-0001: Pg 20
1802-2200-0002-0002: Pg 21
1802-2200-0002-0003: Pg 21
1802-2200-0002-0004: Pg 22
1802-2200-0002-0005: Pg 22
1802-2200-0002-0006: Pg 23
1802-2200-0002-0011: Pg 24
1802-2200-0002-0012: Pg 24
1802-2200-0002-0013: Pg 25
1802-2200-0002-0014: Pg 25
1802-2200-0002-0015: Pg 26
1802-2200-0002-0016: Pg 26
1802-2200-0002-0017: Pg 27
1802-2200-0002-0018: Pg 27
1802-2200-0002-0019: Pg 28
1802-2200-0002-0021: Pg 28
1802-2200-0002-0022: Pg 29
1802-2200-0002-0024: Pg 30
1802-2200-0002-0025: Pg 30
1802-2300-0002-0001: Pg 20
1802-2300-0002-0002: Pg 21
1802-2300-0002-0003: Pg 21
1802-2300-0002-0004: Pg 22
1802-2300-0002-0005: Pg 22
1802-2300-0002-0006: Pg 23
1802-2300-0002-0011: Pg 24
1802-2300-0002-0012: Pg 24
1802-2300-0002-0013: Pg 25
1802-2300-0002-0014: Pg 25
1802-2300-0002-0015: Pg 26
1802-2300-0002-0016: Pg 26
1802-2300-0002-0017: Pg 27
1802-2300-0002-0018: Pg 27
1802-2300-0002-0019: Pg 28
1802-2300-0002-0021: Pg 28
1802-2300-0002-0022: Pg 29
1802-2300-0002-0024: Pg 30
1802-2300-0002-0025: Pg 30
1802-4000-0002-0001: Pg 31
1802-5000-0002-0001: Pg 33
1802-7000-0002-0001: Pg 33
1802-7000-0002-0002: Pg 34
1802-7000-0002-0003: Pg 34
1802-7000-0002-0004: Pg 35
1802-7000-0002-0005: Pg 35
1802-7000-0002-0007: Pg 42
1802-7000-0002-0008: Pg 36
1802-7100-0002-0001: Pg 33
1802-7100-0002-0002: Pg 34
1802-7100-0002-0004: Pg 35
1802-7100-0002-0005: Pg 35
1802-7200-0002-0001: Pg 33
1802-7200-0002-0002: Pg 34
1802-7200-0002-0004: Pg 35
1802-7200-0002-0005: Pg 35
1802-7300-0002-0001: Pg 33
1802-7300-0002-0002: Pg 34
1802-7300-0002-0004: Pg 35
1802-7300-0002-0005: Pg 35
1802-8000-0001-0001: Pg 36
1802-8000-0001-0002: Pg 36
1802-8000-0001-0003: Pg 37
1802-8000-0001-0004: Pg 37
1802-9000-0001-0003: Pg 37
1802-9000-0002-0001: Pg 37
1802-9200-0001-0001: Pg 38
1802-9200-0002-0002: Pg 38
1802-9200-0002-0003: Pg 38
1802-9400-0001-0001: Pg 38
1802-9600-0001-0001: Pg 39
1802-9600-0001-0003: Pg 39
1802-9600-0002-0002: Pg 39
1802-9700-0003-0001: Pg 39
1802-9800-0002-0001: Pg 40
1803-0100-0001-0005: Pg 17
1803-0100-0002-0007: Pg 18
1803-2000-0001-0081: Pg 19
1803-2000-0001-0083: Pg 19
1803-2000-0001-0084: Pg 19
1803-2000-0002-0001: Pg 20
1803-2000-0002-0002: Pg 21
1803-2000-0002-0003: Pg 21
1803-2000-0002-0004: Pg 22
1803-2000-0002-0005: Pg 22
1803-2000-0002-0006: Pg 23
1803-2000-0002-0010: Pg 23
1803-2000-0002-0011: Pg 24
1803-2000-0002-0012: Pg 24
1803-2000-0002-0013: Pg 25
1803-2000-0002-0014: Pg 25
1803-2000-0002-0015: Pg 26
1803-2000-0002-0016: Pg 26
1803-2000-0002-0017: Pg 27
1803-2000-0002-0018: Pg 27
1803-2000-0002-0019: Pg 28
1803-2000-0002-0021: Pg 28
1803-2000-0002-0022: Pg 29
1803-2000-0002-0023: Pg 29
1803-2000-0002-0024: Pg 30
1803-2000-0002-0025: Pg 30
1803-2100-0002-0001: Pg 20
1803-2100-0002-0002: Pg 21
1803-2100-0002-0003: Pg 21
1803-2100-0002-0004: Pg 22
1803-2100-0002-0005: Pg 22
1803-2100-0002-0006: Pg 23
1803-2100-0002-0011: Pg 24
1803-2100-0002-0012: Pg 24
1803-2100-0002-0013: Pg 25
1803-2100-0002-0014: Pg 25
1803-2100-0002-0015: Pg 26
1803-2100-0002-0016: Pg 26
1803-2100-0002-0017: Pg 27
1803-2100-0002-0018: Pg 27
1803-2100-0002-0019: Pg 28
1803-2100-0002-0021: Pg 28
1803-2100-0002-0022: Pg 29
1803-2100-0002-0024: Pg 30
1803-2100-0002-0025: Pg 30
1803-2200-0002-0001: Pg 20
1803-2200-0002-0002: Pg 21
1803-2200-0002-0003: Pg 21
1803-2200-0002-0004: Pg 22
1803-2200-0002-0005: Pg 22
1803-2200-0002-0006: Pg 23
1803-2200-0002-0011: Pg 24
1803-2200-0002-0012: Pg 24
1803-2200-0002-0013: Pg 25
1803-2200-0002-0014: Pg 25
1803-2200-0002-0015: Pg 26
1803-2200-0002-0016: Pg 26
1803-2200-0002-0017: Pg 27
1803-2200-0002-0018: Pg 27
1803-2200-0002-0019: Pg 28
1803-2200-0002-0021: Pg 28
1803-2200-0002-0022: Pg 29
1803-2200-0002-0024: Pg 30
1803-2200-0002-0025: Pg 30
1803-2300-0002-0001: Pg 20
1803-2300-0002-0002: Pg 21
1803-2300-0002-0003: Pg 21
1803-2300-0002-0004: Pg 22
1803-2300-0002-0005: Pg 22
1803-2300-0002-0006: Pg 23
1803-2300-0002-0011: Pg 24
1803-2300-0002-0012: Pg 24
1803-2300-0002-0013: Pg 25
1803-2300-0002-0014: Pg 25
1803-2300-0002-0015: Pg 26
1803-2300-0002-0016: Pg 26
1803-2300-0002-0017: Pg 27
1803-2300-0002-0018: Pg 27
1803-2300-0002-0019: Pg 28
1803-2300-0002-0021: Pg 28
1803-2300-0002-0022: Pg 29
1803-2300-0002-0024: Pg 30
1803-2300-0002-0025: Pg 30
1803-4000-0002-0001: Pg 31
1803-5000-0002-0001: Pg 33
1803-7000-0002-0001: Pg 33
1803-7000-0002-0002: Pg 34
1803-7000-0002-0003: Pg 34
1803-7000-0002-0004: Pg 35
1803-7000-0002-0005: Pg 35
1803-7000-0002-0008: Pg 36
1803-7100-0002-0001: Pg 33
1803-7100-0002-0002: Pg 34
1803-7100-0002-0004: Pg 35
1803-7100-0002-0005: Pg 35
1803-7200-0002-0001: Pg 33
1803-7200-0002-0002: Pg 34
1803-7200-0002-0004: Pg 35
1803-7200-0002-0005: Pg 35
1803-7300-0002-0001: Pg 33
1803-7300-0002-0002: Pg 34
1803-7300-0002-0004: Pg 35
1803-7300-0002-0005: Pg 35
1803-8000-0001-0001: Pg 36
1803-8000-0001-0002: Pg 36
1803-8000-0001-0003: Pg 37
1803-8000-0001-0004: Pg 37
1803-9000-0001-0003: Pg 37
1803-9000-0002-0001: Pg 37
1803-9200-0001-0001: Pg 38
1803-9200-0002-0002: Pg 38
1803-9200-0002-0003: Pg 38
1803-9400-0001-0001: Pg 38
1803-9600-0001-0001: Pg 39
1803-9600-0001-0003: Pg 39
1803-9600-0002-0002: Pg 39
1803-9700-0003-0001: Pg 39
1803-9800-0002-0001: Pg 40
1804-0100-0001-0005: Pg 17
1804-0100-0002-0007: Pg 18
1804-2000-0001-0081: Pg 19
1804-2000-0001-0083: Pg 19
1804-2000-0001-0084: Pg 19
1804-2000-0002-0001: Pg 20
1804-2000-0002-0002: Pg 21
1804-2000-0002-0003: Pg 21
1804-2000-0002-0004: Pg 22
1804-2000-0002-0005: Pg 22
1804-2000-0002-0006: Pg 23
1804-2000-0002-0010: Pg 23
1804-2000-0002-0011: Pg 24
1804-2000-0002-0012: Pg 24
1804-2000-0002-0013: Pg 25
1804-2000-0002-0014: Pg 25
1804-2000-0002-0015: Pg 26
1804-2000-0002-0016: Pg 26
1804-2000-0002-0017: Pg 27
1804-2000-0002-0018: Pg 27
1804-2000-0002-0019: Pg 28
1804-2000-0002-0021: Pg 28
1804-2000-0002-0022: Pg 29
1804-2000-0002-0023: Pg 29
1804-2000-0002-0024: Pg 30
1804-2000-0002-0025: Pg 30
1804-2100-0002-0001: Pg 20
1804-2100-0002-0002: Pg 21
1804-2100-0002-0003: Pg 21
1804-2100-0002-0004: Pg 22
1804-2100-0002-0005: Pg 22
1804-2100-0002-0006: Pg 23
1804-2100-0002-0011: Pg 24
1804-2100-0002-0012: Pg 24
1804-2100-0002-0013: Pg 25
1804-2100-0002-0014: Pg 25
1804-2100-0002-0015: Pg 26
1804-2100-0002-0016: Pg 26
1804-2100-0002-0017: Pg 27
1804-2100-0002-0018: Pg 27
1804-2100-0002-0019: Pg 28
1804-2100-0002-0021: Pg 28
1804-2100-0002-0022: Pg 29
1804-2100-0002-0024: Pg 30
1804-2100-0002-0025: Pg 30
1804-2200-0002-0001: Pg 20
1804-2200-0002-0002: Pg 21
1804-2200-0002-0003: Pg 21
1804-2200-0002-0004: Pg 22

1804-2200-0002-0005: Pg 22
1804-2200-0002-0006: Pg 23
1804-2200-0002-0011: Pg 24
1804-2200-0002-0012: Pg 24
1804-2200-0002-0013: Pg 25
1804-2200-0002-0014: Pg 25
1804-2200-0002-0015: Pg 26
1804-2200-0002-0016: Pg 26
1804-2200-0002-0017: Pg 27
1804-2200-0002-0018: Pg 27
1804-2200-0002-0019: Pg 28
1804-2200-0002-0021: Pg 28
1804-2200-0002-0022: Pg 29
1804-2200-0002-0024: Pg 30
1804-2200-0002-0025: Pg 30
1804-2300-0002-0001: Pg 20
1804-2300-0002-0002: Pg 21
1804-2300-0002-0003: Pg 21
1804-2300-0002-0004: Pg 22
1804-2300-0002-0005: Pg 22
1804-2300-0002-0006: Pg 23
1804-2300-0002-0011: Pg 24
1804-2300-0002-0012: Pg 24
1804-2300-0002-0013: Pg 25
1804-2300-0002-0014: Pg 25
1804-2300-0002-0015: Pg 26
1804-2300-0002-0016: Pg 26
1804-2300-0002-0017: Pg 27
1804-2300-0002-0018: Pg 27
1804-2300-0002-0019: Pg 28
1804-2300-0002-0021: Pg 28
1804-2300-0002-0022: Pg 29
1804-2300-0002-0024: Pg 30
1804-2300-0002-0025: Pg 30
1804-4000-0002-0001: Pg 31
1804-5000-0002-0001: Pg 33
1804-7000-0002-0001: Pg 33
1804-7000-0002-0003: Pg 34
1804-7000-0002-0004: Pg 35
1804-7000-0002-0005: Pg 35
1804-7000-0002-0007: Pg 42
1804-7000-0002-0008: Pg 36
1804-7100-0002-0001: Pg 33
1804-7100-0002-0004: Pg 35
1804-7100-0002-0005: Pg 35
1804-7200-0002-0001: Pg 33
1804-7200-0002-0004: Pg 35
1804-7200-0002-0005: Pg 35
1804-7300-0002-0001: Pg 33
1804-7300-0002-0004: Pg 35
1804-7300-0002-0005: Pg 35
1804-8000-0001-0001: Pg 36
1804-8000-0001-0002: Pg 36
1804-8000-0001-0003: Pg 37
1804-8000-0001-0004: Pg 37
1804-9000-0001-0003: Pg 37
1804-9000-0002-0001: Pg 37
1804-9200-0001-0001: Pg 38
1804-9200-0002-0002: Pg 38
1804-9200-0002-0003: Pg 38
1804-9400-0001-0001: Pg 38
1804-9600-0001-0001: Pg 39
1804-9600-0001-0003: Pg 39
1804-9600-0002-0002: Pg 39
1804-9700-0003-0001: Pg 39
1804-9800-0002-0001: Pg 40
1805-0100-0001-0005: Pg 17
1805-0100-0002-0007: Pg 18
1805-2000-0001-0081: Pg 19
1805-2000-0001-0083: Pg 19
1805-2000-0001-0084: Pg 19
1805-2000-0002-0001: Pg 20
1805-2000-0002-0002: Pg 21
1805-2000-0002-0003: Pg 21
1805-2000-0002-0004: Pg 22
1805-2000-0002-0005: Pg 22
1805-2000-0002-0006: Pg 23
1805-2000-0002-0010: Pg 23
1805-2000-0002-0011: Pg 24
1805-2000-0002-0012: Pg 24
1805-2000-0002-0013: Pg 25
1805-2000-0002-0014: Pg 25
1805-2000-0002-0015: Pg 26
1805-2000-0002-0016: Pg 26
1805-2000-0002-0017: Pg 27
1805-2000-0002-0018: Pg 27
1805-2000-0002-0019: Pg 28
1805-2000-0002-0021: Pg 28
1805-2000-0002-0022: Pg 29
1805-2000-0002-0023: Pg 29
1805-2000-0002-0024: Pg 30
1805-2000-0002-0025: Pg 30
1805-2100-0002-0001: Pg 20
1805-2100-0002-0002: Pg 21
1805-2100-0002-0003: Pg 21
1805-2100-0002-0004: Pg 22
1805-2100-0002-0005: Pg 22
1805-2100-0002-0006: Pg 23
1805-2100-0002-0011: Pg 24
1805-2100-0002-0012: Pg 24
1805-2100-0002-0013: Pg 25
1805-2100-0002-0014: Pg 25
1805-2100-0002-0015: Pg 26
1805-2100-0002-0016: Pg 26
1805-2100-0002-0017: Pg 27
1805-2100-0002-0018: Pg 27
1805-2100-0002-0019: Pg 28
1805-2100-0002-0021: Pg 28
1805-2100-0002-0022: Pg 29
1805-2100-0002-0024: Pg 30
1805-2100-0002-0025: Pg 30
1805-2200-0002-0001: Pg 20
1805-2200-0002-0002: Pg 21
1805-2200-0002-0003: Pg 21
1805-2200-0002-0004: Pg 22
1805-2200-0002-0005: Pg 22
1805-2200-0002-0006: Pg 23
1805-2200-0002-0011: Pg 24
1805-2200-0002-0012: Pg 24
1805-2200-0002-0013: Pg 25
1805-2200-0002-0014: Pg 25
1805-2200-0002-0015: Pg 26
1805-2200-0002-0016: Pg 26
1805-2200-0002-0017: Pg 27
1805-2200-0002-0018: Pg 27
1805-2200-0002-0019: Pg 28
1805-2200-0002-0021: Pg 28
1805-2200-0002-0022: Pg 29
1805-2200-0002-0024: Pg 30
1805-2200-0002-0025: Pg 30
1805-2300-0002-0001: Pg 20
1805-2300-0002-0002: Pg 21
1805-2300-0002-0003: Pg 21
1805-2300-0002-0004: Pg 22
1805-2300-0002-0005: Pg 22
1805-2300-0002-0006: Pg 23
1805-2300-0002-0011: Pg 24
1805-2300-0002-0012: Pg 24
1805-2300-0002-0013: Pg 25
1805-2300-0002-0014: Pg 25
1805-2300-0002-0015: Pg 26
1805-2300-0002-0016: Pg 26
1805-2300-0002-0017: Pg 27
1805-2300-0002-0018: Pg 27
1805-2300-0002-0019: Pg 28
1805-2300-0002-0021: Pg 28
1805-2300-0002-0022: Pg 29
1805-2300-0002-0024: Pg 30
1805-2300-0002-0025: Pg 30
1805-4000-0002-0001: Pg 31
1805-5000-0002-0001: Pg 33
1805-7000-0002-0001: Pg 33
1805-7000-0002-0002: Pg 34
1805-7000-0002-0003: Pg 34
1805-7000-0002-0004: Pg 35
1805-7000-0002-0005: Pg 35
1805-7000-0002-0007: Pg 42
1805-7000-0002-0008: Pg 36
1805-7100-0002-0001: Pg 33
1805-7100-0002-0002: Pg 34
1805-7100-0002-0004: Pg 35
1805-7100-0002-0005: Pg 35
1805-7200-0002-0001: Pg 33
1805-7200-0002-0002: Pg 34
1805-7200-0002-0004: Pg 35
1805-7200-0002-0005: Pg 35
1805-7300-0002-0001: Pg 33
1805-7300-0002-0002: Pg 34
1805-7300-0002-0004: Pg 35
1805-7300-0002-0005: Pg 35
1805-8000-0001-0001: Pg 36
1805-8000-0001-0002: Pg 36
1805-8000-0001-0003: Pg 37
1805-8000-0001-0004: Pg 37
1805-9000-0001-0003: Pg 37
1805-9000-0002-0001: Pg 37
1805-9200-0001-0001: Pg 38
1805-9200-0002-0002: Pg 38
1805-9200-0002-0003: Pg 38
1805-9400-0001-0001: Pg 38
1805-9600-0001-0001: Pg 39
1805-9600-0001-0003: Pg 39
1805-9600-0002-0002: Pg 39
1805-9700-0003-0001: Pg 39
1805-9800-0002-0001: Pg 40
1806-0100-0001-0005: Pg 17
1806-0100-0002-0007: Pg 18
1806-2000-0001-0081: Pg 19
1806-2000-0001-0083: Pg 19
1806-2000-0001-0084: Pg 19
1806-2000-0002-0001: Pg 20
1806-2000-0002-0002: Pg 21
1806-2000-0002-0004: Pg 22
1806-2000-0002-0005: Pg 22
1806-2000-0002-0006: Pg 23
1806-2000-0002-0010: Pg 23
1806-2000-0002-0011: Pg 24
1806-2000-0002-0012: Pg 24
1806-2000-0002-0013: Pg 25
1806-2000-0002-0014: Pg 25
1806-2000-0002-0015: Pg 26
1806-2000-0002-0016: Pg 26
1806-2000-0002-0017: Pg 27
1806-2000-0002-0018: Pg 27
1806-2000-0002-0019: Pg 28
1806-2000-0002-0021: Pg 28
1806-2000-0002-0022: Pg 29
1806-2000-0002-0023: Pg 29
1806-2000-0002-0024: Pg 30
1806-2000-0002-0025: Pg 30
1806-2100-0002-0001: Pg 20
1806-2100-0002-0002: Pg 21
1806-2100-0002-0004: Pg 22
1806-2100-0002-0005: Pg 22
1806-2100-0002-0006: Pg 23
1806-2100-0002-0011: Pg 24
1806-2100-0002-0012: Pg 24
1806-2100-0002-0013: Pg 25
1806-2100-0002-0014: Pg 25
1806-2100-0002-0015: Pg 26
1806-2100-0002-0016: Pg 26
1806-2100-0002-0017: Pg 27
1806-2100-0002-0018: Pg 27
1806-2100-0002-0019: Pg 28
1806-2100-0002-0021: Pg 28
1806-2100-0002-0022: Pg 29
1806-2100-0002-0024: Pg 30
1806-2100-0002-0025: Pg 30
1806-2200-0002-0001: Pg 20
1806-2200-0002-0002: Pg 21
1806-2200-0002-0004: Pg 22
1806-2200-0002-0005: Pg 22
1806-2200-0002-0006: Pg 23
1806-2200-0002-0011: Pg 24
1806-2200-0002-0012: Pg 24
1806-2200-0002-0013: Pg 25
1806-2200-0002-0014: Pg 25
1806-2200-0002-0015: Pg 26
1806-2200-0002-0016: Pg 26
1806-2200-0002-0017: Pg 27
1806-2200-0002-0018: Pg 27
1806-2200-0002-0019: Pg 28
1806-2200-0002-0021: Pg 28
1806-2200-0002-0022: Pg 29
1806-2200-0002-0024: Pg 30
1806-2200-0002-0025: Pg 30
1806-2300-0002-0001: Pg 20
1806-2300-0002-0002: Pg 21
1806-2300-0002-0004: Pg 22
1806-2300-0002-0005: Pg 22
1806-2300-0002-0006: Pg 23
1806-2300-0002-0011: Pg 24
1806-2300-0002-0012: Pg 24
1806-2300-0002-0013: Pg 25
1806-2300-0002-0014: Pg 25
1806-2300-0002-0015: Pg 26
1806-2300-0002-0016: Pg 26
1806-2300-0002-0017: Pg 27
1806-2300-0002-0018: Pg 27
1806-2300-0002-0019: Pg 28
1806-2300-0002-0021: Pg 28
1806-2300-0002-0022: Pg 29
1806-2300-0002-0024: Pg 30
1806-2300-0002-0025: Pg 30
1806-4000-0002-0001: Pg 31
1806-5000-0002-0001: Pg 33
1806-7000-0002-0001: Pg 33
1806-7000-0002-0002: Pg 34
1806-7000-0002-0003: Pg 34
1806-7000-0002-0004: Pg 35
1806-7000-0002-0005: Pg 35
1806-7000-0002-0007: Pg 42
1806-7000-0002-0008: Pg 36
1806-7100-0002-0001: Pg 33
1806-7100-0002-0002: Pg 34
1806-7100-0002-0004: Pg 35
1806-7100-0002-0005: Pg 35
1806-7200-0002-0001: Pg 33
1806-7200-0002-0002: Pg 34
1806-7200-0002-0004: Pg 35
1806-7200-0002-0005: Pg 35
1806-7300-0002-0001: Pg 33
1806-7300-0002-0002: Pg 34
1806-7300-0002-0004: Pg 35
1806-7300-0002-0005: Pg 35
1806-8000-0001-0001: Pg 36
1806-8000-0001-0002: Pg 36
1806-8000-0001-0003: Pg 37
1806-8000-0001-0004: Pg 37
1806-9000-0001-0003: Pg 37
1806-9000-0002-0001: Pg 37
1806-9200-0001-0001: Pg 38

1806-9200-0002-0002: Pg 38
1806-9200-0002-0003: Pg 38
1806-9400-0001-0001: Pg 38
1806-9600-0001-0001: Pg 39
1806-9600-0001-0003: Pg 39
1806-9600-0002-0002: Pg 39
1806-9700-0003-0001: Pg 39
1806-9800-0002-0001: Pg 40
1807-0100-0001-0005: Pg 17
1807-0100-0002-0007: Pg 18
1807-2000-0001-0081: Pg 19
1807-2000-0001-0083: Pg 19
1807-2000-0001-0084: Pg 19
1807-2000-0002-0001: Pg 20
1807-2000-0002-0002: Pg 21
1807-2000-0002-0004: Pg 22
1807-2000-0002-0005: Pg 22
1807-2000-0002-0006: Pg 23
1807-2000-0002-0010: Pg 23
1807-2000-0002-0011: Pg 24
1807-2000-0002-0012: Pg 24
1807-2000-0002-0013: Pg 25
1807-2000-0002-0014: Pg 25
1807-2000-0002-0015: Pg 26
1807-2000-0002-0016: Pg 26
1807-2000-0002-0017: Pg 27
1807-2000-0002-0018: Pg 27
1807-2000-0002-0019: Pg 28
1807-2000-0002-0021: Pg 28
1807-2000-0002-0022: Pg 29
1807-2000-0002-0023: Pg 29
1807-2000-0002-0024: Pg 30
1807-2000-0002-0025: Pg 30
1807-2100-0002-0001: Pg 20
1807-2100-0002-0002: Pg 21
1807-2100-0002-0004: Pg 22
1807-2100-0002-0005: Pg 22
1807-2100-0002-0006: Pg 23
1807-2100-0002-0011: Pg 24
1807-2100-0002-0012: Pg 24
1807-2100-0002-0013: Pg 25
1807-2100-0002-0014: Pg 25
1807-2100-0002-0015: Pg 26
1807-2100-0002-0016: Pg 26
1807-2100-0002-0017: Pg 27
1807-2100-0002-0018: Pg 27
1807-2100-0002-0019: Pg 28
1807-2100-0002-0021: Pg 28
1807-2100-0002-0022: Pg 29
1807-2100-0002-0024: Pg 30
1807-2100-0002-0025: Pg 30
1807-2200-0002-0001: Pg 20
1807-2200-0002-0002: Pg 21
1807-2200-0002-0004: Pg 22
1807-2200-0002-0005: Pg 22
1807-2200-0002-0006: Pg 23
1807-2200-0002-0011: Pg 24
1807-2200-0002-0012: Pg 24
1807-2200-0002-0013: Pg 25
1807-2200-0002-0014: Pg 25
1807-2200-0002-0015: Pg 26
1807-2200-0002-0016: Pg 26
1807-2200-0002-0017: Pg 27
1807-2200-0002-0018: Pg 27
1807-2200-0002-0019: Pg 28
1807-2200-0002-0021: Pg 28
1807-2200-0002-0022: Pg 29
1807-2200-0002-0024: Pg 30
1807-2200-0002-0025: Pg 30
1807-2300-0002-0001: Pg 20
1807-2300-0002-0002: Pg 21
1807-2300-0002-0004: Pg 22
1807-2300-0002-0005: Pg 22
1807-2300-0002-0006: Pg 23
1807-2300-0002-0011: Pg 24
1807-2300-0002-0012: Pg 24
1807-2300-0002-0013: Pg 25
1807-2300-0002-0014: Pg 25
1807-2300-0002-0015: Pg 26
1807-2300-0002-0016: Pg 26
1807-2300-0002-0017: Pg 27
1807-2300-0002-0018: Pg 27
1807-2300-0002-0019: Pg 28
1807-2300-0002-0021: Pg 28
1807-2300-0002-0022: Pg 29
1807-2300-0002-0024: Pg 30
1807-2300-0002-0025: Pg 30
1807-4000-0002-0001: Pg 31
1807-5000-0002-0001: Pg 33
1807-7000-0002-0001: Pg 33
1807-7000-0002-0002: Pg 34
1807-7000-0002-0003: Pg 34
1807-7000-0002-0004: Pg 35
1807-7000-0002-0005: Pg 35
1807-7000-0002-0007: Pg 42
1807-7000-0002-0008: Pg 36
1807-7100-0002-0001: Pg 33
1807-7100-0002-0002: Pg 34
1807-7100-0002-0004: Pg 35
1807-7100-0002-0005: Pg 35
1807-7200-0002-0001: Pg 33
1807-7200-0002-0002: Pg 34
1807-7200-0002-0004: Pg 35
1807-7200-0002-0005: Pg 35
1807-7300-0002-0001: Pg 33
1807-7300-0002-0002: Pg 34
1807-7300-0002-0004: Pg 35
1807-7300-0002-0005: Pg 35
1807-8000-0001-0001: Pg 36
1807-8000-0001-0002: Pg 36
1807-8000-0001-0003: Pg 37
1807-8000-0001-0004: Pg 37
1807-9000-0001-0003: Pg 37
1807-9000-0002-0001: Pg 37
1807-9200-0001-0001: Pg 38
1807-9200-0002-0002: Pg 38
1807-9200-0002-0003: Pg 38
1807-9400-0001-0001: Pg 38
1807-9600-0001-0001: Pg 39
1807-9600-0001-0003: Pg 39
1807-9600-0002-0002: Pg 39
1807-9700-0003-0001: Pg 39
1807-9800-0002-0001: Pg 40
18FE-7000-0002-0008: Pg 36
18FF-7000-0002-0008: Pg 36