```
p2d wr fsm
+ pct size w
+ n buff
+ in_pct data w
+ clk
+ reset n
+ pct size
+ in pct wrreq
+ in pct data
+ in pct wrfull
+ pct hdr 0
and 10 more...
```