

chkEN G # chkEN DIR SXRSXT # chkRESET_N

and 67 more... + pnISX view() + ~pnlSX view() # ParameterChangeHandler()

OnDIV2PrescalerChange() # ParameterChangeHandler() # OnbtnCalculateClick() # OnbtnTuneClick() # OnEnableRefSpurCancelation() # OnbtnChangeRefClkClick()

lms7002 pnlSX view # cmbRZ CTRL

cmbCMPLO CTRL

ImsControl

OnbtnReadComparators() # OnShowVCOclicked()

wndld2Enum + Ims7002 pnISX view() + Ims7002_pnlSX_view()

+ Initialize() + UpdateGUI() # ParameterChangeHandler() # ParameterChangeHandler() # OnbtnReadComparators() # OnbtnChangeRefClkClick()

OnbtnCalculateClick() # OnbtnTuneClick() # OnShowVCOclicked() # OnEnableRefSpurCancelation()