




*Not for navigational purposes.

*Airport's chart may change without prior notice.

Address:

Carretera antigua a Minatitlán,
Km. 21.5, Zip code 96340
Cosoleacaque, Veracruz.

Telephone: +52 (722) 273 0981

Operational information:

General Aviation

Operational hours:

1300-0100 UTC

Overtime: Available upon request
and under authorities' approval.
This must be requested 4 hrs. prior
the airport's closure.

Customs and Immigration:

1300-0100 UTC

Fuel available: Avgas 100/130, Jet
A.

Fuel delays may be expected since
Government fuel provider (ASA)
has top priority with commercial
operations.

Fuel payment method:

Debit card, Credit card and fuel
release through fuel providers.

GSE: N/A

FIRE CAT: VI

Catering: N/A

Manny staff: Joel Hipólito Corsino.

Car rental: Yes

Executive transportation: N/A

Ground ambulance: N/A

Type of surface: Asphalt

Elevation (ft): 36

PCN: 065FAXT

Arrivals:

1. Upon arrival, aircraft must follow ATC's instructions to enter to General Aviation where international authorities are located.
2. Crew and passengers' passports will be requested by one of our staff representatives to present them to Immigration authorities. Once released, they will be handed back.
3. When passengers get off the aircraft, Customs, federal agents, and health-sanitation authorities will board to perform an inspection.
4. Passengers must walk into the General Aviation building to follow the CIQ processes. Please consider all luggage must be unloaded and cannot be inspected without owner's presence (Authorities usually take trained dogs to detect food or any other substances).
5. This process takes around 20-30 minutes, depending on the number of operations happening simultaneously at the airport.

Departures:

1. Crew and passengers' passports will be requested by one of our staff representatives to present them to Immigration and Customs authorities.
2. Luggage will be taken to the X ray machine for a security inspection.
3. Once finalized, they will be allowed to board aircraft.
4. This process takes around 20-30 minutes.
5. After the above process is done, aircraft will follow ATC's instructions to take off.

