




MMPA/PAZ
TAJÍN NATIONAL AIRPORT



*Not for navigational purposes.

*Airport's chart may change without prior notice.

Address:

Carretera México -Tuxpan km. 8.
Zip code 92900, Tihuatlán
Veracruz.

Telephone: +52 (722) 273 0981

Operational information:

General Aviation.

Operational hours:

1300-0000 UTC

Overtime: Available upon request
and under authorities' approval.
This must be requested 4 hrs. prior
the airport's closure.

Customs and Immigration:

1300-0000 UTC

Fuel available: Avgas 100/130, Jet
A.

Fuel delays may be expected since
Government fuel provider (ASA)
has top priority with commercial
operations.

Fuel payment method:

Debit card, Credit card and fuel
release through fuel providers.

American Express is not accepted.

GSE: Yes

FIRE CAT: IV

Catering: N/A

Manny staff: José Abel Romero
Cortez / Arturo Hernández
Hernández.

Car rental: N/A

Executive transportation: N/A

Ground ambulance: N/A

Type of surface: Asphalt

Elevation (ft): 497

PCN: 023FAXT

Arrivals:

1. Upon arrival, aircraft must follow ATC's instructions to enter to General Aviation apron.
2. When passengers get off, federal agents will get on board to perform an inspection of the luggage (There might be the possibility of having this done by the National Guard) They usually take trained dogs to detect food and/or any other substances.
3. This process takes around 10-20 minutes.
4. Once this is over, passengers will be able to exit through General Aviation.

Departures:

1. Boarding will be done through the General Aviation terminal.
2. Luggage will be taken to the X ray machine for a security inspection.
3. Luggage might also be checked by the National Guard or soldiers, before boarding on the apron.
4. This process will take around 10-20 minutes.
5. After the above process is done, aircraft will follow ATC's instructions to take off.

