Variavel XMEAS-17 FAULT:3

Stripper Temperature (unit = Deg C)

Process measurements (3 minute sampling interval)

- - - +std
—— avg_data0
- - - -std
—— avg