SOP — Abnormal Process Condition Response

Document ID: APEL-SOP-OPS-204 | Owner: Operations | Revision: 7.1

This page defines the task-specific controls for recognition.

Recognition

- Unexpected pressure
- Loss of flow
- Rapid temperature change
- Utility instability
- Unusual vibration

Stabilization

This page defines the task-specific controls for stabilization.

Stabilization

- Verify indication where practical.
- Reduce process stress using approved procedures.
- Notify shift supervisor.
- Protect people and equipment.

Escalation

This page defines the task-specific controls for escalation.

Escalation

- Safety-system activation
- Rapidly worsening trend
- Equipment trip
- Potential release
- Loss of containment

Event logging

This page defines the task-specific controls for event logging.

Event logging

- Time
- Tag
- Observed value
- Action
- Person notified
- Current state

Follow-up

This page defines the task-specific controls for follow-up.

Follow-up

- Instrumentation verification
- Maintenance work order
- Engineering study
- SOP update
- Operator training