# ApexPetro Refining Complex

Coastal Refinery - Unit 2

## INSPECTION RECORD

Document ID: INS-P102-2026-0307

Equipment ID: P-102 (Feed Transfer Pump)

Location: Pump Bay 2 / Unit 2

Inspection Date: 07 March 2026

Department: Inspection & Integrity

### Measurement Readings

| Parameter | Value | Unit | Operating Limit | Status |
|---|---|---|---|---|
| DE Vibration | 5.6 | mm/s | <= 4.5 mm/s | HIGH |
| (repeat check) | 5.5 | mm/s | <= 4.5 mm/s | HIGH |

### Inspection Observations

DE-side vibration measured above the 4.5 mm/s action threshold during routine condition monitoring. A repeat measurement was taken to confirm the reading; the repeat check remained above the applicable limit, confirming a genuine high-vibration condition rather than a spurious reading. A maintenance inspection has been requested to determine the root cause.

### Recommended Action

Raise maintenance work order for coupling/alignment inspection per P-102 operating guidance (DE vibration above limit).

Inspected By: _____

Approved By: _____

Date: 07-Mar-2026

Department: Inspection & Integrity