Standard Operating Procedure: Hot Work Near Live Hydrocarbon Facilities

Document ID:	SOP-SAF-210	**Effective Date:**	2026-08-01
Revision:	3.5	**Classification:**	CONFIDENTIAL - STRICT PROPRIETARY
Department:	HSE Department	**Site Location:**	Jamnagar Refinery Complex (JRC)

1. Purpose

Safety controls for welding, cutting, grinding within 15 meters of operational hydrocarbon units.

2. Step-by-Step Procedure

1. Cover all sewer catch basins and drains within 15m radius with fire-retardant blankets.
2. Conduct continuous LEL gas monitoring; work permitted only at 0.0% LEL.
3. Deploy two pressurized fire extinguishers (10 kg DCP) and charged water hose reel.
4. Maintain dedicated fire watch for minimum 60 minutes after hot work completion.