


ART FILM - ASSEMBLY_TOP



ART FILM - ASSEMBLY_TOP





STACKUP TABLE									
Unit = Mils									
#	NAME	TYPE	MATERIAL	THICKNESS	TOLERANCE				
		SURFACE	AIR	0	+0/-0				
	SOLDERMASK_TOP	MASK	SOLDERMASK_FLEXIBLE_UV_CURE	0.47	+ 0 / - 0				
1	TOP	CONDUCTOR	10Z_COPPER	1.4	+0.1/-0.1				
		DIELECTRIC	FR - 4	3.7	+0/-0				
2	L2_GND	PLANE	10Z_COPPER	1.4	+0.1/-0.1				
		DIELECTRIC	FR - 4	18	+ 0 / - 0				
3	L3_PWR	PLANE	10Z_COPPER	1.4	+0.1/-0.1				
		DIELECTRIC	FR - 4	3.7	+ 0 / - 0				
4	BOTTOM	CONDUCTOR	10Z_COPPER	1.4	+0.1/-0.1				
	SOLDERMASK_BOTTOM	MASK	SOLDERMASK_FLEXIBLE_UV_CURE	0.47	+ 0 / - 0				
		SURFACE	AIR	0	+0/-0				
	<u> </u>	31.94							

DRILL CHART: TOP to BOTTOM								
ALL UNITS ARE IN MILS								
FIGURE	FINISHED_SIZE	PLATED	QTY					
•	13.0	PLATED	157					
4	43.0	PLATED	2					
*	55.12	PLATED	2					
•	55.12	PLATED	2					
0	125.0	NON-PLATED	4					

UNLESS OTHERWISE SPECIFIED	SIGNATURES	DATE	COMPANY NAME AND ADDRESS				
DIMENSIONS ARE IN INCHES							
TOLERANCES ON:							
2 PL DECIMALS +							
3 PL DECIMALS +			-				
ANGLES +							
FRACTIONS +			SIZE F	FSCM NO		DWG NO	
			-				
			SCALE	-			SHEET