



LINE SIZE	A	B	C	D	E
3/4"	100	100	CUT FROM H200X100X5.5X8	—	—
1"	100	100		—	—
1 1/2"	100	100		—	—
2"	100	100		—	—
2 1/2"	100	100		—	—
3"	100	100		—	—
4"	100	100		—	—
5"	100	100		—	—
6"	100	100		—	—
8"	100	100		—	—
10"	200	200	CUT FROM H200X200X8X12	70	—
12"	200	200		70	—
14"	200	200		70	—
16"	300	250	FAB. FROM 12 ^t PLATE	100	12
18"	300	250		100	12
20"	300	250		100	12
24"	350	250		100	12

1. DESIGNATION NUMBER DENOTE AS FOLLOWS:

80-2B(P)-A(A)-130-500

DENOTE TYPE NO.					└─┬─┐	MODIFY LOPS=500 (IN mm) IF ANY
DENOTE LINE SIZE					└─┬─┘	MODIFY HOPS=130 (IN mm) IF ANY
DENOTE REIN. PAD IS REQ'D					└─┬──┘	SEE SH'T D-80A TABLE "B"
					└──┬──┘	SEE SH'T D-80A TABLE "A"

2. LENGTH OF PIPE SHOE (SAY LOPS) TO SUIT BEAM WIDTH IN FIELD.

3. HOPS=HEIGHT OF PIPE SHOE, LOPS=LENGTH OF PIPE SHOE.