

HEAT INDEX REFERENCE CHART

The Heat Index combines air temperature and relative humidity to reflect what the temperature actually feels like to the human body. Use this chart to assess risk level in interior work zones based on measured temperature and humidity readings.

Note: Radiant heat from surfaces (concrete, metal decking, glass) can add an additional 10-15°F to the effective Heat Index. Under T8 CCR §3396, temperature/heat index must be measured and recorded whenever indoor conditions require additional control measures.

Heat Index (°F)	Risk Level	Required Response	CDRP Frequency	Buddy System
Below 82°F	CAUTION	Monitor, Hydrate, CDRP on Request (§3396)	On Request	Encouraged
82 - 87°F	MODERATE	§3396 active; water, cool-down area, CDRP on request; control measures if restrictive PPE/radiant heat	Encouraged Every 2 Hours	Encouraged
87 - 103°F	HIGH	§3396 control measures & recordkeeping required; increase CDRPs	Every 2 Hours	MANDATORY
103 - 115°F	VERY HIGH	High-Heat Procedures active; shorten shifts; engineering controls required	Every 1 Hour	MANDATORY
115 - 129°F	EXTREME	Reduce strenuous tasks, shorten shifts, maximum controls	Every 30 – 45 Minutes	MANDATORY
130°F+	SUSPEND WORK	Suspend work, GC/Superintendent Directive, continuous cooling	Continuous Cooling	MANDATORY

Note: The chart above addresses interior ambient temperatures. For outdoor delivery/staging areas, apply same thresholds to outdoor heat index readings obtained from weather services or onsite measurement. High-Heat Procedures (T8 CCR §3395) activate at 95°F outdoor temperature. Shade is required at 80°F+.