
M8 5-position

Connector name	X-407
Drawing date	12-29-14
Drawn by	Victor Brechbill





Pin	Name	Function	Wire color*
1	+5V	5V power to strain gauge sensor 2	Brown
2	STRN_2_X	0-5V analog signal from strain gauge sensor 2 x-axis routed to AIN-8	White
3	GND	Ground for strain gauge sensor 2	Blue
4	STRN_2_Y	0-5V analog signal from strain gauge sensor 2 y-axis routed to AIN-9	Black
5	STRN_2_XY	0-5V analog signal from strain gauge sensor 2 diagonal routed to AIN-10	Grey