



Service Order: 25-0026974

Order Status: Complete

Customer	Problem
FORT WAYNE URBAN LEAGUE 2135 HANNA ST. FORT WAYNE, IN 46803	MULTIPLE SPLIT UNITS NOT COOLING - SEE NORA NEIGER 260-257-9411
Who called: JOHN ROGERS	200 201 0 111

Work Performed

6/9/2025 LJB Arrived onsite, started going through units, found 4 condenser units with open compressors, and one with a locked up compressor drawing 137amps. Repaired one condenser with a 44+5mfd capacitor. Repaired another that had a leaky schraeder core without a cap, added 2lbs of r-22 refrigerant, replaced schraeder core and cap. Had to bend the fan guard out on another to the fan wouldnt bind up. Found the left most fan/evaporator coil in the upper mechanical room had a blown 3amp fuse on the control board from when they had a fire near its corresponding condenser and it shorted the wires, replaced fuse and found the condensate pan float switch bad, replaced it and unit ran fine. Sent email with data plate pictures and model/serial info to Ben Hoover to quote replacement on the 5 condensers that are bad.

Material / Parts						
Part	Description	Serial No.	Unit Price	Quantity		
N/A	44 +5mfd capacitor			1		
R22 REF	R22 REFRIGERANT			2		
N/A	Schraeder core			1		
N/A	Service port cap			1		
N/A	3amp car fuse			1		
N/A	Cc-1 condensat pan switch			1		

Tech Name	Reg. time	Overtime	Dbl. time
LEON BEDWELL JR.	7:15	0:00	0:00

Part Number	Part Description	Quantity	UOM
	40+5 cap	1	E
	55+5 capacitor	1	E
	270-324 capacitor	1	E
	Condensate pan float switch	1	E