

Revision History

Rev	Note
01	Initial Release
02	Swapped positions of Z-30 and Z-31, error from initial release.
03	Swapped positions of Z-55 and Z-56, cable spec Rev03 change to match supplier drawing. Component Z-114 changed to Z-115 to match cable spec, error from initial release. Code Z-114 reintroduced as an extension cable for Z-115 component, safety switch. Schematic Label changed for Z-114.