

	XP13 WF-7		
1000	Конт.	Цепь	
ADC6	1	ADC6	
ADC5	2	ADC5	
ADC4	3	ADC4	
ADC3	4	ADC3	
ADC2	5	ADC2	
ADC1	6	ADC1	
ADC0	7	ADC0	

	XP14 WF-3		
CIC IN	Конт.	Цепь	
SIG_IN	1	GND	
GND	2		
	3	ADC/CMP	