



ALL FOLDS ARE FIXED WITH HOT GLUE

PW-00-0 AND PW-01-0 SHALL BE GLUED IN PLACE DURING THE PROCESS

FUSELAGE		CUT & FOLD
SCALE 2:3	PROJECT	PART NUMBER
PAGE 2/2	RC Trainer V1	PF-01-0-0