## MSFS: G1000 NXi Update 0.2.0 - Airways, North-Up Map, Brightness - Microsoft Flight Simulator

https://www.youtube.com/watch?v=2sgzSPhkCSU

The settings prompts are the same in the Microsoft simulator in the above video.

G1000 manual

https://static.garmin.com/pumac/190-00629-04 a.pdf

Personally, I feel Map orientation North Up is the best setting for you can double check your magnetic compass for checking the accuracy of both instruments.