

27-APR-2017

**DIL-WPDL****1-10****AOI****AOI****GENERAL****Operational Hours****ATS Hours / AD ADMIN Hours:** 2130-0900. Other times O/R.

PPR for EMERG night OPS.

**Airport Information****RFF:** CAT 5**Fuel:** PPR**PCN:** RWY 08/26: 42/F/B/X/U.**Operation****Geodetic Reference Datum**

Non-WGS-84 compliant airport.

**Traffic Notes:**

RWY and APCH lights are turned off when TWR CLSD, thereafter activation by pilot.

**RWY Restriction**

ACFT with MTOW above 7t / 15430lbs after LDG taxi to RWY end and backtrack compulsory to prevent damage to RWY surface.

**Warnings****NDB/KO:**

Severe needle fluctuations may occur within minor arc bearing 120° to 230° below FL150, along bearings over islands to the north especially bearing 297° between 25NM and 35NM. Excessive needle fluctuations may be experienced along bearing 084° from overhead KO NDB to BACAU WPT and along bearing 257° from overhead to WPT OTORA. Holding pattern not to be used.

**VOR/DME/DIL:**

Limited coverage over terrain in southern sector.

**ARRIVAL****Arrival Procedure****VFR Traffic Pattern**

RWY 26 right-hand circuit.

**DEPARTURE****Take-off Minima**

RWY		08/26	
All ACFT	ft - m/km	0 - 400V	HJ only

13-DEC-2007


DIL-WPDL

## East Timor Dili Presidente Nicolau Lobato

NIL  
AFC

2-10

## Presidente Nicolau Lobato Dili East Timor

NIL  
AFC

Comoro APP/TWR

122.900 2130-0945

Comoro GND

133.900 2130-0945

Landing RWY system:

08

60 | 1790 x 30 | 3.0° | 17 / 1hPa | TDZ ---% | +0.1%

60 L | 30 x 1790 | 3.0° | -0.1% | TDZ ---% | 25 / 1hPa

26

Changes: New


13-DEC-2007  
DIL-WPDL

East Timor Dili Presidente Nicolau Lobato

3-20

AGC  
NIL  
AGC

Presidente Nicolau Lobato Dili East Timor  
AGC  
NIL  
AGC



Changes: New


18-NOV-2010

DIL-WPDL

7-10

VOR DME Letdown

IAC



Changes: MIN


18-NOV-2010

DIL-WPDL

7-20

VOR Letdown

IAC



Changes: MIN


18-NOV-2010

DIL-WPDL

7-30

IAC

NDB Letdown



Changes: MIN