

04-JUN-2015

**MKK-PHMK**

1-10

AOI

AOI

**GENERAL****ATS Hours**

H24, attended 1600-0545.

AD closed to air carrier OPS with more than 10 PAX seat between 0530-1600 except PPR,  
call (808) 567-9660/9663.

**Airport Information**

**RFF:** FAA Index A / CAT 5

**Fuel:** Not published

**PCN:** RWY 05/23: 12/F/B/Y/T, RWY 17/35: 11/F/B/Y/T

**Customs:** Not published

**Operation**

24HR PPR for Division 1.1/1.2/1.3 explosives and 4HR PPR for other hazardous material, contact (808) 567-6140/6008.

**Traffic Notes**

RWY and APCH light are turned off when TWR CLSD, thereafter activation by CTAF.

**Warnings**

**MKK VOR/DME** unusable: R275-R285 beyond 25NM below 3500ft.

Standing water/ponding on RWY 17/35 near TWY E during inclement weather

Mountain APPROX 1280ft MSL located 2.8NM from THR RWY 05 on extended CL.

Birds in vicinity of AD.

**ARRIVAL****Speed**

MAX IAS 250KT below 10000ft.

**Communication**

**COM Failure:** See CRAR United States

**Warnings**

RWY 05 PAPI not authorized 1.8NM beyond landing THR due to rapidly rising terrain

04-JUN-2015

**MKK-PHMK****1-20****AOI****DEPARTURE****Take-off Minima**

RWY		05	
1+2 ENG	ft - ft/SM	0 - 1.0V	SID BLUSH, SID HAPAI, SID KAUNAKAKAI:
3+4 ENG		0 - 0.25V	MNM climb gradient 8.9% up to 800
All ACFT		c300 - 1.0V	MNM climb gradient 5.4% up to 1500
		c1500 - 2.5V	climb in visual conditions (SID KAUNAKAKAI only)
RWY		17	
1+2 ENG	ft - ft/SM	0 - 1.0V	-
3+4 ENG		0 - 0.5V	-
All ACFT		Not authorized	SID BLUSH, SID HAPAI
RWY		23	
1+2 ENG	ft - ft/SM	0 - 1.0V	SID KAUNAKAKAI:
3+4 ENG		0 - 0.5V	MNM climb gradient 7.2% up to 1500
All ACFT		c1500 - 2.5V	climb in visual conditions
		Not authorized	SID BLUSH, SID HAPAI
RWY		35	
1+2 ENG	ft - ft/SM	0 - 1.0V	SID KAUNAKAKAI:
3+4 ENG		0 - 0.5V	MNM climb gradient 8.8% up to 800
All ACFT		c300 - 1.0V	wo MNM climb restrictions
		Not authorized	SID BLUSH, SID HAPAI

**Speed**

MAX IAS 250KT below 10000ft.

**Communication****COM Failure:** See CRAR United States.

16-MAR-2017

MKK-PHMK


## United States Kaunakakai Molokai

AGC  
AFC

## Molokai Kaunakakai United States

AGC  
AFC

2-10



16-MAR-2017

MKK-PHMK

United States Kaunakakai Molokai


3-20

AGC

AGC

Molokai Kaunakakai United States

AGC



Changes: Parking Stands 2, 3, 4, ABN, BLDG

04-JUN-2015

MKK-PHMK

United States Kaunakakai Molokai


SID

SID

Molokai Kaunakakai United States

HAPAI 3  
BLUSH 2

4-10



04-JUN-2015

MKK-PHKM

United States Kaunakakai Molokai

4-20


HAPAI 3

SID

SID

Molokai Kaunakakai United States

HAPAI 3



Changes: new

04-JUN-2015

MKK-PHMK

## United States Kaunakakai Molokai

NIL

4-30

OBST DEP KAUNAKAKAI 1 (HMK 1)


SID

SID

## Molokai Kaunakakai United States

NIL

OBST DEP KAUNAKAKAI 1 (HMK 1)



04-JUN-2015

**MKK-PHMK****5-10****BLUSH 2**

SIDPT

**BLUSH 2**

RWY 05 (049°)

DESIGNATOR	ROUTING	ALTITUDES
	<b>Runway 05</b>	
<b>BLUSH 2</b> 125.700	LT HDG 360° - intercept R075 <b>CKH</b> to BLUSH	BLUSH at <b>5000</b>

04-JUN-2015

**MKK-PHMK****5-20****HAPAI 3****HAPAI 3**

RWY 05 (049°)

DESIGNATOR	ROUTING	ALTITUDES
	Runway 05	
<b>HAPAI 3</b> 125.700	<b>LT HDG 340° - intercept R030 MKK to HAPAI</b>	
	<b>TRANSITION</b>	
<b>BAMBO</b>	HAPAI - follow D10 <b>MKK</b> arc counter clockwise to DAKKL - <b>RT</b> intercept R300 <b>MKK</b> to BAMBO	BAMBO MNM <b>8000</b>
<b>LOKIE</b>	HAPAI - follow D10 <b>MKK</b> arc counter clockwise via DAKKL to LOKIE	
<b>MOLOKAI (MKK)</b>	HAPAI - <b>LT HDG 180° - intercept R030 MKK to MKK</b>	


05-JAN-2017

MKK-PHMK

7-10

IAC

RNAV (GPS) B



**Effective 24-MAY-2018**

17-MAY-2018

## **United States Kaunakakai Molokai**

MKK-PHMK

7-30

VOR A

