

17-MAR-2016

N/A-MPSM**1-10****AOI****AOI****GENERAL****Operational Hours****ATS Hours:** 1100-0300**Airport Information****RFF:** CAT 7**PCN:** RWY 17/35: 44/F/C/W/T**Warnings**

Birds in vicinity of AD.

ARRIVAL**Speed**

MAX IAS 250KT below 10000ft within TMA.

Communication**COM Failure**

| ILS or VOR/DME 35: Initiate procedure in accordance with ATC instructions and published charts.

Arrival Procedure**VFR Traffic Pattern:** RWY 35 right-hand circuit.**DEPARTURE****Take-off Minima**

RWY		17/35	
A, B, C	ft - m/km	0 - 400V	HJ only
		0 - 800V	HN
D		Not applicable	-


Speed

MAX IAS 250KT below 10000ft within TMA.

2-10

ez Intl
AGC
AFC

AFC Cap.Scarlett R. Martinez Intl **Rio Hato** Panama
[AGC]



Effective 02-MAR-2017
23-FEB-2017

N/A-MPSM

3-20

Panama Rio Hato Cap.Scarlett R. Martinez Intl

AGC


AGC

AGC

AGC

Cap.Scarlett R. Martinez Intl Rio Hato Panama

ATIS	127.600	1100-0300
Scarlett TWR	118.200	1100-0300
GND	121.700	1100-0300
Panama RDO	123.600	Sector East 126.900 Sector West



Effective 02-MAR-2017
23-FEB-2017


Panama Rio Hato Cap.Scarlett R. Martinez Intl

IAC

N/A-MPSM

7-10

ILS 35




Changes: Navaid renamed, QFU, HLDG, Editorial

N/A-MPSM

7-30

RNAV (GNSS) 35



Effective 02-MAR-2017
23-FEB-2017


Panama Rio Hato Cap.Scarlett R. Martinez Intl

IAC

N/A-MPSM

7-50

VOR DME 35



Changes: Navaid renamed, SUAs, HLDG, QFU

Effective 02-MAR-2017
23-FEB-2017


Panama Rio Hato Cap.Scarlett R. Martinez Intl

IAC

N/A-MPSM

7-60

VOR 35



Changes: Navaid renamed, QFU, HLDG, Editorial