

09-NOV-2017

ANR-EBAW**1-10****AOI****AOI****GENERAL****Operational Hours**

ATS Hours / AD ADMIN Hours: 0530-2200‡. Other times O/R, at least the preceding day before 1100‡.

Airport Information

RFF: CAT 7

Fuel: MON-FRI 0430-2030‡, SAT and SUN 0530-2130‡
Other times PN. No fuel AVBL when AD is CLSD.

Customs: 0530-2200‡

PCN: RWY 11/29: 30/FAW/U

Operation

Preferential RWY: TKOF/LDG: RWY 11.

Transponder Mode S

Select assigned transponder Mode A and activate Mode S, set to AUTO if technically AVBL;

- from push-back or taxi, whichever comes earlier.
- after LDG, continuously until fully parked on stand.

Select ACFT identification feature if AVBL, before activating transponder.

Low Visibility Procedures

LVP in force when RVR below 550m.

When LVP in force, only one ACFT at a time is allowed on the maneuvering area, taxi authorized only on TWY A, B, F, and guided by follow-me.

TWY Restriction:

TWY K width 15m / 49ft

TWY B, E, G, J width 12m / 39ft.

Taxi/Parking

ACFT movement to/from north side during night and when RVR below 1500m shall be marshalled to/from RWY via TWY E or G.

ARRIVAL**Communication****COM Failure**

If ACFT does not succeed in LDG within 30min it must leave Antwerpen CTR on MT 309° at MAX 2000ft and land at the first suitable AD in VMC.

Arrival Procedure**Noise Abatement Procedure**

Visual APCH: Do not intercept APCH slope of PAPI (3.5°) below 1700ft if MET CONDs permit a visual straight-in or a direct APCH on RWY 11.

Reverse: Do not use more than idle reverse if possible.

09-NOV-2017

ANR-EBAW**1-20****AOI****AOI****DEPARTURE****Take-off Minima**

RWY		29	
A, B, C	ft - m/km	0 - 150R	-
D		Not applicable	-

RWY		11	
A, B, C	ft - m/km	0 - 400R/400V	-
D		Not applicable	-

Departure Procedure**Start-up**

REQ CLR 10min before ready.

Any call in advance of the 10min may result in disruption of DEP sequence and cause delay.

Departure Notes| **PUTTY 5E/1G/5C/1B:** After PUTTY to HSD (DEST EHAM) or to STD (all other DEST).

Routing via SPI - AMASI shall select a climb profile in order to be able to cross SPI at FL240 or above. Flights unable to meet this climb requirement may expect rerouting via SPI - LIRSU - AMASI.

Noise Abatement Procedure: Use ICAO Standard NADP1.**De-Icing**

AVBL

02-NOV-2017

Belgium Antwerpen Deurne


AFC

Deurne **Antwerpen** Belgium

AF


2-10

ANR-EBAW



D-ATIS	124.200
Brussels ARR	118.250
TWR	135.200 0530-2200
	119.700 0530-2200
GND	121.900 0530-2200

Landing RWY system:



02-NOV-2017

ANR-EBAW

Belgium Antwerpen Deurne


3-20

AGC

AGC

Deurne Antwerpen Belgium

AGC



Changes: Nil

02-NOV-2017

ANR-EBAW


Belgium Antwerpen Deurne

SIDs RWY 11

Deurne **Antwerpen** Belgium

SIDs RWY 11

4-10



02-NOV-2017

ANR-EBAW

Belgium **Antwerpen** Deurne


Deurne **Antwerpen** Belgium

4-20

SIDs RWY 29

10

SIDs RWY 29



ANR-EBAW

5-10

SIDs RWY 11

GILOM 2E / GILOM 2F / GILOM 2G / NICKY 3E / PUTTY 1G / PUTTY 5E / SONDI 4E
RWY 11 (110°)

DESIGNATOR	ROUTING	ALTITUDES
	Runway 11	
GILOM 2E (ATC) 135.200	at 1500 RT intercept R004 BUB to BUB - R135 BUB to GILOM	
GILOM 2F (ATC) 135.200	at 1500 direct BUN - R187 BUN to GILOM	
GILOM 2G (ATC) 135.200	at 1500 RT intercept R099 NIK to NIK - R140 NIK to BUB - R135 BUB to GILOM	
NICKY 3E NIK 3E 135.200	at 1500 RT intercept R099 NIK to NIK	
PUTTY 1G (ATC) 135.200	at 1500 RT intercept R099 NIK to NIK - R026 NIK to PUTTY	
PUTTY 5E 135.200	at 1500 LT intercept R004 BUB - LT intercept R308 BUN to PUTTY	
SONDI 4E 135.200	at 1500 LT intercept R090 ANT to SONDI	

ANR-EBAW

5-20

SIDs RWY 29

GILOM 2C / GILOM 3B / GILOM 3D / NICKY 4C / PUTTY 1B / PUTTY 5C / SONDI 4C
RWY 29 (290°)

DESIGNATOR	ROUTING	ALTITUDES
	Runway 29	
GILOM 2C (ATC) 135.200	at 600 LT intercept R339 BUB to BUB - R135 BUB to GILOM	
GILOM 3B (ATC) 135.200	at 600 LT intercept R079 NIK to NIK - R140 NIK to BUB - R135 BUB to GILOM	
GILOM 3D (ATC) 135.200	at 600 LT intercept R276 BUN to BUN - R187 BUN to GILOM	
NICKY 4C NIK 4C 135.200	at 600 LT intercept R079 NIK to NIK	
PUTTY 1B (ATC) 135.200	at 600 LT intercept R079 NIK to NIK - R026 NIK to PUTTY	
PUTTY 5C 135.200	at 600 LT intercept R079 NIK inbound - crossing R343 BUB RT intercept R345 BUB to PUTTY	
SONDI 4C 135.200	at 600 LT intercept R079 NIK inbound - crossing R338 BUB LT intercept QDM 074 ONW to ONW - QDR 254 ONW - intercept R086 NIK to SONDI	

02-NOV-2017

ANR-EBAW


Belgium Antwerpen Deurne

STAR
STAR

Deurne Antwerpen Belgium

STAR
STARs

6-10



02-NOV-2017


Belgium Antwerpen Deurne

IAC

ANR-EBAW

7-10

ILS or LOC 29



Changes: MSA, SUAs, OBST

23-FEB-2017


Belgium Antwerpen Deurne

IAC

ANR-EBAW

7-30

RNAV (GNSS) 11




Changes: TDZE, Note, OBST, SUAs, Profile

02-NOV-2017

ANR-EBAW

7-50

VOR 11




Changes: MSA, SUAs, OBST

02-NOV-2017

ANR-EBAW

7-60

VOR 29



Changes: MSA, SUAs, OBST

02-NOV-2017

ANR-EBAW

Belgium Antwerpen Deurne

MRC
NIL

Deurne Antwerpen Belgium

MRC
NIL

8-10

