

22-SEP-2016

**LVP-OIBV****1-10****AOI****AOI****GENERAL****Operational Hours****ATS Hours:** HJ**AD ADMIN Hours:** 0230-1430‡**Airport Information****RFF:** CAT 6**PCN:** RWY 11/29: 48/F/A/X/T**Customs:** Not AVBL**Operation****Traffic Note**

PPR from Iranian Air Transportation Company - NAFT.

**Warnings****LVA VOR/DME** unusable counter clockwise within D20:

R360-R340 below 5000ft.

R080-R360 below 5000ft.

Strolling animals on movement area.

Birds in vicinity of AD.

**DEPARTURE****Take-off Minima**

RWY		11/29	
All ACFT	ft - m/km	0 - 400V	HJ only
		0 - 800V	HN

**Departure Procedure****Start-up:** Clearance should be REQ 5-10min prior to start-up**De-Icing**

Not AVBL

07-JUL-2016

LVP-OIBV

Iran Lavan Lavan Island

AGC


AFC

Lavan Island Lavan Iran

AGC

AFC

2-10



## Info

Landing RWY system:

11	420	THR 44 (2hPa) / TDZ 44 (---%)	0.0%
L-S			

60 L	45 x 2693	420
PAPI angle not AVBL	0.0%	L-S
TDZ --- (---%) / THR 45 (2hPa)		

Changes: new

07-JUL-2016

LVP-OIBV


Iran Lavan Lavan Island

AGC

Lavan Island Lavan Iran

AGC

3-20



Changes: new

07-JUL-2016

LVP-OIBV

Iran Lavan Lavan Island

SIDs LAM 2A/2B

SIDs KIS 1G/1H

Lavan Island Lavan Iran


SIDs LAM 2A/2B

SIDs KIS 1G/1H

4-10

SID

SID



07-JUL-2016

LVP-OIBV

Iran Lavan Lavan Island

Lavan Island Lavan Iran


4-20

SIDs LAM 2A/2B

SID

SID

SIDs LAM 2A/2B



Changes: new

07-JUL-2016

**LVP-OIBV****5-10****SIDs KIS 1G/1H****KISH 1H / KISH 1G**

RWYs 11 (109°) / 29 (289°)

DESIGNATOR	ROUTING	ALTITUDES
	<b>Runway 11</b>	
<b>KISH 1H KIS 1H 122.100</b>	<b>RT - intercept R116 LVA to KIS</b>	
	<b>Runway 29</b>	
<b>KISH 1G KIS 1G 122.100</b>	<b>RT - intercept R116 LVA to KIS</b>	

07-JUL-2016

**LVP-OIBV****5-20****SIDs LAM 2A/2B****LAMERD 2B / LAMERD 2A**

RWYs 11 (109°) / 29 (289°)

	GS	120	150	180	210	240	270
4.3%	ft/MIN	600	700	800	1000	1100	1200

DESIGNATOR	ROUTING	ALTITUDES
	<b>Runway 11</b>	
<b>LAMERD 2B LAM 2B 4.3% 122.100</b>	intercept R106 <b>LVA</b> - at <b>2000 RT</b> direct <b>LVA</b> - intercept R343 <b>LVA to LAM</b>	<b>LVA MNM 4000</b>
<b>LAMERD 2A LAM 2A 4.3% 122.100</b>	<b>Runway 29</b>	
	intercept R266 <b>LVA</b> - at <b>2000 LT</b> direct <b>LVA</b> - intercept R343 <b>LVA to LAM</b>	<b>LVA MNM 4000</b>

07-JUL-2016

LVP-OIBV

Iran Lavan Lavan Island

NIL

6-10


STARs KIS 1V / LAM 1P

STAR

Lavan Island Lavan Iran


NIL

STARs KIS 1V / LAM 1P




Changes: new

07-JUL-2016

**LVP-OIBV****7-10****VOR DME 29****IAC**

Changes: new

07-JUL-2016

**LVP-OIBV****7-20****NDB 29**

Changes: new