

PCL-SPCL**1-10****AOI****GENERAL****Operational Hours****ATS Hours:** 1200-0600**AD ADMIN Hours:** H24**Airport Information****RFF:** CAT 7**Fuel:** 1200-2300, other times O/R.**PCN:** RWY 02/20: 46/F/C/X/T**Warnings**

Do not overfly city east of AD below 2000ft.

Do not mistake highway 1.5NM southeast with final APCH RWY 02 lights.

Birds in vicinity of AD.


DEPARTURE**Take-off Minima**

RWY		02/20	
3+4 ENG	ft - m/km	0 - 800V	-
1+2 ENG		0 - 1600V	-


05-JAN-2017

PCL-SPCL

Peru Pucallpa Cap FAP David Armando Abensur R. Intl.

AFCCap FAP David Armando Abensur R. Intl. **Pucallpa Peru****AFC****AFC****AFC**

Changes: Nil



29-JAN-2015

PCL-SPCL


Peru Pucallpa

COCOS 1

Pucallpa Peru

COCOS 1

4-10



29-JAN-2015


PCL-SPCL**5-10****COCOS 1****COCOS 1**

RWY 20 (204°)

DESIGNATOR	ROUTING	ALTITUDES
	Runway 20	
COCOS 1 128.500	at 1000 RT intercept R241 PUL to COCOS	COCOS MNM FL80

Effective 20-AUG-2015
13-AUG-2015


PCL-SPCL



Effective 20-AUG-2015
13-AUG-2015

PCL-SPCL

Peru Pucallpa
MIKAR 1A STAR
STAR MIKAR 1A
Pucallpa Peru




05-JAN-2017

PCL-SPCL

7-10

VOR W 02

IAC




05-JAN-2017

PCL-SPCL

7-20

IAC

VOR V 02



Changes: APL


05-JAN-2017

PCL-SPCL

7-30

IAC

VOR A 20



Changes: APL