

15-MAR-2018

AQI-OEPA**1-10****AOI****AOI****GENERAL****Operational Hours**| **ATS Hours:** Not AVBL| **AD OPS Hours:** 0400-2000| **AD ADMIN Hours:** SUN-THU 0500-1300**Airport Information****RFF:** CAT 7**Fuel:** HO**PCN:** RWY 16/34: 59/F/A/W/T**Customs:** Not AVBL**Operation****Traffic Note**

| Uncontrolled AD. PPR PN 3HR to AD for non-SKED flights.

Traffic Information Broadcast by ACFT (TIBA) must be followed.

Warnings

APCH RWY 34: Be aware 1566 MSL antenna located at 788m / 2585ft SW of THR RWY 34.

ARRIVAL**Communication**

Contact Fire and Rescue Service (FRS) on 133.500 15min before LDG. Refer to CRAR.

DEPARTURE**Take-off Minima**

RWY		16/34	
1 & 2 ENG	ft - m/km	0 - 1.6V	Lower MIN by state permission
3 & 4 ENG		0 - 800V	

Additionally see CRAR.

02-JAN-2018 UTM
28-DEC-2017

AQI-OEPA

3-09


Tempo AGC


AGC

AGC

Tempo AGC

Hafr Al Batin Domestic Al Qaisumah Saudi Arabia





Effective 12-NOV-2015

05-NOV-2015


Saudi Arabia Al Qaisumah Hafr Al Batin Domestic

AQI-OEPA

7-10

ILS DME 34

IAC



Changes: APL

Effective 12-NOV-2015


05-NOV-2015

Saudi Arabia Al Qaisumah Hafr Al Batin Domestic

AQI-OEPA

7-20

VOR DME 16




Changes: APL

AQI-OEPA

7-30


VOR 16



AQI-OEPA

7-40

VOR DME 34



1) PROC NA when AQI QNH N/A

2) E of RWY 16/34 only

AQI-OEPA

7-50

VOR 34

