

GENERAL**Operational Hours****ATS Hours / AD ADMIN Hours:** H24**Airport Information****RFF:** CAT 9**Fuel:** JP-8**PCM:** RWY 18/36: 57 F/D/W/T**Customs:** Not published**Operation****TWY Restriction**

TWY 1,4 width 19m / 62ft

TWY 5 width 21m / 69ft

Taxi/Parking

Marshaller mandatory.

Noise Abatement Procedure

There is Manyas Lake at 5NM SE of AD, flying below 2500ft is forbidden.

Warnings

Birds in vicinity of AD.

ARRIVAL**Speed**

MAX IAS 250KT within TMA at or below FL100 (refer to RFCs)


DEPARTURE**Take-off Minima**

RWY		18/36	
All ACFT	ft - m/km	0 - 400V	-

Speed

MAX IAS 250KT within TMA at or below FL100 (refer to RFCs)

ATC Clot, Clearance**Start-up:** For start-up PROCs see CRAR.



Effective 19-JUL-2018

12-JUL-2018


BDM-LTBG

3-20

Turkey Balıkesir Bandırma

AGC AGC
AGC AGC
AGC


Bandırma Balıkesir Turkey



BDM-LTBG

7-10

ILS or LOC Z 36




1) Up to 5500ft

BDM-LTBG

7-20

ILS or LOC Y 36



12-JUL-2018

BDM-LTBG


Turkey Balikesir Bandirma

MRC

Bandirma Balikesir Turkey

MRC

8-10



Changes: OBST