

31-MAY-2018

**BUN-SKBU****1-10****AOI****AOI****GENERAL****Operational Hours****ATS Hours / AD Hours:** 1100-2300**Airport Information****RFF:** CAT 4**PCN:** RWY 09/27: 72/F/B/X/T**Customs:** Not AVBL**Warnings**

Exercise caution on APN due to the proximity of the terminal and TWR.

Exercise caution on RWY due to the presence of people.

Reduced visibility from TWR towards THR 27 and part of the RWY.

Birds in vicinity of AD.

**ARRIVAL****Speed**

MAX IAS 250KT below FL100 within airspace classes D and G.

**DEPARTURE****Take-off Minima**

RWY		09/27	
3+4 ENG	ft - m/km	0 - 800V	-
2 ENG		0 - 1.6V	-

**Speed**

MAX IAS 250KT below FL100 within airspace classes D and G.

31-MAY-2018

Colombia Buenaventura Gerardo Tovar Lopez

AGC

AFC


Gerardo Tovar Lopez Buenaventura Colombia

AGC

AFC

BUN-SKBU

2-10



Changes: new

Cali CTL	126.700
Cali APP	119.100
Gerardo Tovar Lopez TWR	118.700 1100-2300

Landing RWY system:	
09	03.0° 60 L 1200 x 30
27	-0.2% TDZ --- (%) / THR 48 (2hPa)

31-MAY-2018

BUN-SKBU

Colombia **Buenaventura** Gerardo Tovar Lopez

3-20

AGC

Gerardo Tovar Lopez **Buenaventura Colombia**


AGC

AGC

W076°59.5'

Gerardo Tovar Lopez TWR 118.700 1100-2300

W076°59.1'



Changes: new