

WMI-EPMO

1-10

AOI

AOI

GENERAL**Operational Hours****ATS Hours**

TWR: MON-FRI, SUN 0500-2300‡, SAT 0500-2359‡

AFIS AVBL outside TWR HRs

Current working HRs see NOTAM

AD ADMIN Hours: H24**Airport Information****RFF:** CAT 7**Fuel:** H24**PCN:** RWY 08/26: first 540m / 1772ft both sides 53/R/B/W/T
rest 1420m / 4659ft 53/F/B/X/T**Customs:** H24**Operation****Traffic Notes**

Code D and E ACFT PPR PN 24HR

Low Visibility Procedure

LVP in force when RVR below 550m or CEIL is at or below 200ft.

ARR RWY 08 use only TWYs B, C, A1, A2.

Follow-me mandatory.

TWY Restrictions

TWY J, U, V1, V2 width 21m / 69ft.

TWY A1, A2 (from APN 1 stand 10-1) width 18m / 59ft.

TWY D width 16m / 52ft.

TWY A2 (from APN 1 stand 1 to TWY D), A3, E, W width 15m / 49ft.

TWY S width 14m / 46ft.

TWYs D and S AVBL up to code letter B ACFT, and AVBL for taxiing SR-SS only.

TWY A3, E AVBL up to code letter C ACFT with a wheel base up to 18m / 59ft.

Code letter C ACFT taxi via TWY A2, C to APN 1, stand 13 with follow-me assistance.

Minimum Runway Occupancy Time (MROT): Ensure standard MROT procedures.**ARRIVAL****Communication**

On initial contact with TWR report: PSN, ALT and IAS.

COM Failure**RNAV-1 (P-RNAV) approved ACFT**

If STAR was assigned and acknowledged by crew and vectoring was initiated.

Continue on assigned HDG and last cleared and acknowledged ALT for 2min. Then proceed direct FAP/FAF and execute APCH (ILS or VOR) and land. Descending shall be executed in accordance with vertical restrictions specified on chart.

WMI-EPMO

1-20

AOI

ARRIVAL**RNAV-1 (P-RNAV) not approved ACFT**

Maintain last assigned and acknowledged ALT/flight level. Proceed IRDOM/INREN and commence descent in the HLDG pattern over IRDOM/INREN then FAF (RWY 08), DOMUV then FAF (RWY 26), execute APCH and land. If LDG is not possible, execute MISAP and proceed to FAF of most convenient RWY, execute APCH and land.

DEPARTURE**Take-off Minima**

RWY		08/26	
All ACFT	ft - m/km	0 - 125R	-

ATIS

AFIS: 120.325 / Outside TWR working hours.

START-UP PROCEDURES

TWR 123.925 MON-FRI, SUN 0500-2300‡, SAT 0500-2359‡.

REQ CLR 10min prior to being ready for push-back or start-up to TWR and report:

- Call sign
- Stand
- Destination AD
- Planned cruising LVL (if other than in FPL)
- Any changes to FPL
- | - Inability to fly SIDs if applicable.

CLRs are not issued earlier than 30min before EOBT/CTOT.

TAXI PROCEDURES**TWY Dimension**

TWY A2 (from TWY C to APN 1 stand 10), B, C width 23m.

TWY J, U, V1, V2 width 21m.

TWY A1, A2 (from APN 1 stand 10-1) width 18m.

TWY D width 16m.

TWY A2 (from APN 1 stand 1 to TWY D), A3, E, S, W width 15m.

TWY S width 14m.

TWYs D and S AVBL up to code letter B ACFT, and AVBL for taxiing SR-SS only.

TWY A3, E AVBL up to code letter C ACFT with a wheel base up to 18m.

Effective 13-SEP-2018

06-SEP-2018

WMI-EPMO


Poland Warsaw Modlin

AGC
AFC

Modlin Warsaw Poland

AGC
AFC

2-10



Changes: FREQ

Effective 13-SEP-2018

06-SEP-2018

WMI-EPMO

Poland Warsaw Modlin

3-20

AGC


AGC


Modlin Warsaw Poland


AGC

E020°40'

Modlin Info	120.325	Mon-Fri 2300-0500‡ Sat 2359-0500‡ Sun 2300-0500‡
Modlin TWR	123.925	Mon-Fri 0500-2300‡ Sat 0500-2359‡ Sun 0500-2300‡
Modlin DLV	119.680	Mon-Sun 0500-2100‡







Effective 07-JAN-2016

31-DEC-2015

WMI-EPMO

4-30

Poland Warsaw Modlin


RNAV SIDs RWY 26

SID

SID

Modlin Warsaw Poland

RNAV SIDs RWY 26



Changes: Track, SUAs

WMI-EPMO

5-10

RNAV SIDs RWY 08 B DEPs

BAMSO 1B / EVINA 1B / LOLSI 1B / OLILA 1B / SOXER 1B / XIMBA 1B

RWY 08 (076°)

DESIGNATOR	ROUTING	ALTITUDES
	Runway 08	
BAMSO 1B 125.050 ①②	M0866 [K200-] - M0822 [K200-] - M0864 [K250-] - MOL [K250-] - M0946 - M0947 - BITVA - WA571 - BAMSO	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 BITVA MNM FL90 Initial climb 4000
EVINA 1B 125.050 ①②	M0866 [K200-] - M0822 [K200-] - M0864 [K250-] - MOL [K250-] - M0946 - M0947 - M0362 - WA708 - MAKUS - EVDEX - NIPUS - EVINA	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 NIPUS MNM F180 Initial climb 4000
LOLSI 1B 125.050 ①②	M0866 [K200-] - M0822 [K200-] - M0864 [K250-] - MOL [K250-] - M0946 - M0947 - M0362 - WA708 - MAKUS - WA754 - LOLSI	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 WA754 MNM FL100 Initial climb 4000
OLILA 1B 125.050 ①②	M0866 [K200-] - M0822 - RODEV - OLILA	OLILA MNM FL100 Initial climb 4000
SOXER 1B 125.050 ①②	M0866 [K200-] - M0822 [K200-] - M0864 [K250-] - MOL [K250-] - M0946 - M0947 - M0362 - WA708 - MAKUS - WA756 - SOXER	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 WA756 MNM FL100 Initial climb 4000
XIMBA 1B 125.050 ①②	M0866 [K200-] - M0822 [K200-] - M0864 [K250-] - MOL [K250-] - M0946 - M0947 - M0362 - WA708 - MAKUS - EVDEX - EREDA - XENOM - TISTA - XIMBA	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 TISTA MNM FL170 Initial climb 4000

① ACFT unable to comply with SID profile restrictions must request non-standard departure.

② If unable to comply with RNAV 1 or P-RNAV, advise ATC before start-up for radar vectoring.

WMI-EPMO

5-20

RNAV SIDs RWY 08 C/F DEPs

BAMSO 2C / BAMSO 2F / EVINA 2C

RWY 08 (076°)

	GS	120	150	180	210	240	270
8.2%	ft/MIN	1000	1300	1500	1800	2000	2300

DESIGNATOR	ROUTING	ALTITUDES
	Runway 08	
BAMSO 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) to M0822 - M0816 - M0817 - M0859 - DILMU - WA698 - BAMSO FMS M0821 [K220- ;L] - M0822 [R] - M0816 [R] - M0817 [R] - M0859 - DILMU [L]- WA698 [L]- BAMSO	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 Initial climb 4000
BAMSO 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) - intercept R015 MOL to DOMOB - M0816 - M0817 - M0859 - DILMU - WA698 - BAMSO FMS [K200- ;A1000 ;L] - DOMOB [R] - M0816 [R] - M0817 [R] - M0859 - DILMU [L] - WA698 [L] - BAMSO	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 Initial climb 4000
EVINA 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) to M0822 - M0816 - M0817 - M0859 - M0818 - M0861 - NITKI - XIBOL - NIPUS - EVINA FMS M0821 [K220- ;L] - M0822 [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0818 - M0861 [L] - NITKI [L] - XIBOL - NIPUS [L] - EVINA	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 NIPUS MNM FL180 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 NIPUS MNM FL180 Initial climb 4000

① Climb gradient of 8.2 % for ATC purposes.

② ACFT unable to comply with SID profile restrictions must request non-standard departure.

③ If unable to comply with RNAV 1 or P-RNAV, advise ATC before start-up for radar vectoring.

WMI-EPMO

5-30

RNAV SIDs RWY 08 C/F DEPs

EVINA 2F / LOLSI 2C / LOLSI 2F

RWY 08 (076°)

	GS	120	150	180	210	240	270
8.2%	ft/MIN	1000	1300	1500	1800	2000	2300

DESIGNATOR	ROUTING	ALTITUDES
	Runway 08	
EVINA 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) - intercept R015 MOL to DOMOB - M0816 - M0817 - M0859 - M0861 - NITKI - XIBOL - NIPUS - EVINA FMS [K200- ;A1000 ;L] - DOMOB [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0861 [L] - NITKI [L] - XIBOL - NIPUS [L] - EVINA	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 NIPUS MNM FL180 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 NIPUS MNM FL180 Initial climb 4000
LOLSI 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) to M0822 - M0816 - M0817 - M0859 - M0818 - M0861 - GILAL - WA664 - LOLSI FMS M0821 [K220- ;L] - M0822 [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0818 - M0861 - GILAL [R] - WA664 - LOLSI	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 Initial climb 4000
LOLSI 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) intercept R015 MOL to DOMOB - M0816 - M0817 - M0859 - M0861 - GILAL - WA664 - LOLSI FMS [K200- ;A1000 ;L] - DOMOB [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0861 - GILAL [R] - WA664 - LOLSI	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 Initial climb 4000

① Climb gradient of 8.2 % for ATC purposes.

② ACFT unable to comply with SID profile restrictions must request non-standard departure.

③ If unable to comply with RNAV 1 or P-RNAV, advise ATC before start-up for radar vectoring.

WMI-EPMO

5-40

RNAV SIDs RWY 08 C/F DEPs

OLILA 2C / OLILA 2F / SOXER 2C

RWY 08 (076°)

	GS	120	150	180	210	240	270
8.2%	ft/MIN	1000	1300	1500	1800	2000	2300

DESIGNATOR	ROUTING	ALTITUDES
	Runway 08	
OLILA 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) - M0822 - DOMOB - WA663 - OLILA FMS M0821 [K220- ;L] - M0822 [L] - DOMOB [L] - WA663 - OLILA	WA663 MNM FL80 OLILA MNM FL100 WA663 MNM FL80 OLILA MNM FL100 Initial climb 4000
OLILA 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) intercept R015 MOL to DOMOB LT (MAX 230KT) - WA663 - OLILA FMS [K200- ;A1000 ;L] - DOMOB [K230- ;L] - WA663 - OLILA	OLILA MNM FL100 OLILA MNM FL100 Initial climb 4000
SOXER 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) to M0822 - M0816 - M0817 - M0859 - M0818 - M0861 - GILAL - WA666 - SOXER FMS M0821 [K220- ;L] - M0822 [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0818 - M0861 - GILAL [R] - WA666 - SOXER	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 Initial climb 4000

① Climb gradient of 8.2 % for ATC purposes.

② ACFT unable to comply with SID profile restrictions must request non-standard departure.

③ If unable to comply with RNAV 1 or P-RNAV, advise ATC before start-up for radar vectoring.

WMI-EPMO

5-50

RNAV SIDs RWY 08 C/F DEPs

SOXER 2F / XIMBA 2C / XIMBA 2F

RWY 08 (076°)

	GS	120	150	180	210	240	270
8.2%	ft/MIN	1000	1300	1500	1800	2000	2300

DESIGNATOR	ROUTING	ALTITUDES
	Runway 08	
SOXER 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) intercept R015 MOL to DOMOB - M0816 - M0817 - M0859 - M0861 - GILAL - WA666 - SOXER FMS [K200- ;A1000 ;L] - DOMOB [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0861 - GILAL [R] - WA666 - SOXER	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 Initial climb 4000
XIMBA 2C 8.2% to M0821 125.050 ①②③	R076 MOL - at M0821 LT (MAX 220KT, 25° bank) to M0822 - M0816 - M0817 - M0859 - M0818 - WA656 - XIMBA FMS M0821 [K220- ;L] - M0822 [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0818 [L] - WA656 [L] - XIMBA	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 Initial climb 4000
XIMBA 2F 8.2% to DOMOB 125.050 ①②③	at 1000 LT (MAX 200KT, 20° bank) intercept R015 MOL to DOMOB - M0816 - M0817 - M0859 - M0861 - WA656 - XIMBA FMS [K200- ;A1000 ;L] - DOMOB [R] - M0816 [R] - M0817 [R] - M0859 [R] - M0861 [L] - WA656 [R] - XIMBA	M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 M0816 MNM 6000 M0817 MNM FL80 M0859 MNM FL130 M0861 MNM FL160 Initial climb 4000

① Climb gradient of 8.2 % for ATC purposes.

② ACFT unable to comply with SID profile restrictions must request non-standard departure.

③ If unable to comply with RNAV 1 or P-RNAV, advise ATC before start-up for radar vectoring.

WMI-EPMO

5-60

RNAV SIDs RWY 26

BAMSO 2J / EVINA 2J / LOLSI 2J / OLILA 2J

RWY 26 (256°)

	GS	120	150	180	210	240	270
6.1%	ft/MIN	800	1000	1200	1300	1500	1700
7.5%	ft/MIN	1000	1200	1400	1600	1900	2100

DESIGNATOR	ROUTING	ALTITUDES
	Runway 26	
BAMSO 2J 7.5% to MOL 125.050 ①②③	at D3 MOL RT (MAX 220KT, 20° bank) to MOL - R109 MOL to M0946 - M0947 - BITVA - WA571 - BAMSO FMS MOL [L] - M0946 [L] - M0947 [R] - BITVA [L] - WA571 [L] - BAMSO	MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 BITVA MNM FL90 MOL MNM 4000 M0946 MNM 6000 M0947 MNM 7000 BITVA MNM FL90 Initial climb 4000
EVINA 2J 7.5% to 3000 6.1% to M0944 125.050 ①②③	at D3 MOL LT (MAX 220KT, 20° bank) intercept R250 MOL to M0951 - M0943 - M0944 - EVDEX - NIPUS - EVINA FMS M0951 - M0943 [L] - M0944 [L] - EVDEX [R] - NIPUS - EVINA	M0944 MNM FL90 NIPUS MNM FL180 M0944 MNM FL90 NIPUS MNM FL180 Initial climb 4000
LOLSI 2J 7.5% to 3000 6.1% to M0944 125.050 ①②③	at D3 MOL LT (MAX 220KT, 20° bank) intercept R250 MOL to M0951 - M0943 - M0944 - LOLSI FMS M0951 - M0943 [L] - M0944 [R] - LOLSI	M0944 MNM FL90 M0944 MNM FL90 Initial climb 4000
OLILA 2J 7.5% to RODEV 125.050 ①②③	at D3 MOL RT (MAX 220KT, 20° bank) intercept R345 WAR to RODEV - OLILA FMS RODEV [L] - OLILA	OLILA MNM FL100 OLILA MNM FL100 Initial climb 4000

① Climb gradient of 7.5% for ATC purposes.

② If unable to comply with RNAV 1 or P-RNAV, advise ATC before start up for radar vectoring.

③ ACFT unable to comply with SID profile restrictions must request non-standard departure.

WMI-EPMO**5-70****RNAV SIDs RWY 26****SOXER 2J / XIMBA 2J**

RWY 26 (256°)

	GS	120	150	180	210	240	270
6.1%	ft/MIN	800	1000	1200	1300	1500	1700
7.5%	ft/MIN	1000	1200	1400	1600	1900	2100

DESIGNATOR	ROUTING	ALTITUDES
	Runway 26	
SOXER 2J 7.5% to 3000 6.1% to M0944 125.050 ①②③	at D3 MOL LT (MAX 220KT, 20° bank) intercept R250 MOL to M0951 - M0943 - M0944 -SOXER FMS M0951 - M0943 [L] - M0944 [R] - SOXER	M0944 MNM FL90 M0944 MNM FL90 initial climb 4000
XIMBA 2J 7.5% to 3000 6.1% to M0944 125.050 ①②③	at D3 MOL LT (MAX 220KT, 20° bank) intercept R250 MOL to M0951 - M0943 - M0944 - EVDEX - ABSEL - EREDA - XENOM - TISTA - XIMBA FMS M0951 - M0943 [L] - M0944 [L] - EVDEX [L] - ABSEL [R] - EREDA - XENOM [L] - TISTA [R] - XIMBA	M0944 MNM FL90 TISTA MNM FL170 M0944 MNM FL90 TISTA MNM FL170 initial climb 4000

- ① Climb gradient of 7.5% for ATC purposes.
 ② If unable to comply with RNAV 1 or P-RNAV, advise ATC before start up for radar vectoring.
 ③ ACFT unable to comply with SID profile restrictions must request non-standard departure.

Effective 07-JAN-2016

31-DEC-2015

WMI-EPMO

Poland Warsaw Modlin

[RNAV STARs RWY 08 S ARR]

6-10

RNAV STARs RWY 08 R ARR


STAR

STAR

Modlin Warsaw Poland

[RNAV STARs RWY 08 S ARR]

RNAV STARs RWY 08 R ARR



Effective 07-JAN-2016

31-DEC-2015

WMI-EPMO

Poland Warsaw Modlin

Modlin Warsaw Polan


6-20

RNAV STARs RWY 08 S ARRs

STAR

STAR

RNAV STARs RWY 08 S ARR



Effective 07-JAN-2016

31-DEC-2015

WMI-EPMO

6-30

RNAV STARs RWY 08 T ARRs


STAR

STAR

Modlin Warsaw Polan

RNAV STARS RWY 08 W AR

RNAV STARs RWY 08 T ARRs



Effective 07-JAN-2016

31-DEC-2015

WMI-EPMO

Poland Warsaw Modlin


STAR

STAR

Modlin Warsaw Poland

6-40

RNAV STARs RWY 08 W ARR



Changes: HLDG, SUAs

Effective 21-JUN-2018

14-JUN-2018

WMI-EPMO

Poland Warsaw Modlin

[RNAV STARs RWY 26 Y ARRs]

6-50

RNAV STARs RWY 26 X ARRs


STAR

STAR

Modlin Warsaw Poland

[RNAV STARs RWY 26 Y ARRs]

RNAV STARs RWY 26 X ARRs



Effective 21-JUN-2018

14-JUN-2018

WMI-EPMO

Poland Warsaw Modlin


STAR

STAR

Modlin Warsaw Poland

6-60

RNAV STARs RWY 26 Y ARRs




10-AUG-2017

WMI-EPMO

7-10

ILS or LOC 08



Effective 21-JUN-2018

14-JUN-2018


WMI-EPMO

Poland Warsaw Modlin

7-30

IAC

RNAV (GNSS) 08




Changes: Nil

WMI-EPMO

7-40


RNAV (GNSS) 26



Changes: Completely revised

7-50

VOR 08




05-OCT-2017

WMI-EPMO

7-60

VOR 26




Changes: Nil

7-70

Visual 26

VAC



Changes: FREQ, AD ELEV