

GENERAL

Operational Hours

ATS Hours: H24

AD Operator: MON-FRI 0000-0900. SAT, SUN, HOL O/R.

Airport Information

RFF: CAT 9

PCN: RWY 04/22: 70/F/B/W/T

Operation

TWY Restrictions

Taxilane NE of MIL ramp restricted when MIL ACFT parked along RWY.

Rapid exit TWY H AVBL HJ only due to no TWY LGT's.

Taxi/Parking

4 ENG ACFT are advised to use inner ENGs while taxiing to avoid jet blast.

Visual docking guidance system AVBL.

Standard Taxi Routes

ARR RWY 04:

- Rapid exit TWY E then TWY D to ramp, or via TWY C to TWY B, then via TWY D to ramp or
- TWY C - TWY B - TWY D to ramp of Terminal 1, or
- Rapid exit TWY E - TWY B - TWY F or F2 to ramp of Terminal 2, or
- TWY C - TWY B - TWY F or F2 to the ramp of Terminal 2.

ARR RWY 22:

- Rapid exit TWY H - TWY B - TWY F or D to ramp of Terminal 1, or
- TWY K - TWY B -TWY F to the ramp of Terminal 1.
- Rapid exit TWY H - TWY B - TWY F or F2 to ramp of Terminal 2, or
- TWY J or K - TWY B - TWY F or F2 to ramp of Terminal 2.

DEP RWY 04:

- TWY D, F or F2 - TWY B -TWY J for short field TKOF or continue TWY K for normal TKOF.

DEP RWY 22:

- TWY D, F or F2 - TWY B -TWY D for short field TKOF, or continue via TWY C for full length TKOF.

Noise Abatement Procedure

ARR: Enter traffic circuit on the downwind leg at an angle of 45° and maintain AD circuit height. Descent may be commenced on mid base leg.

DEP: Climb straight out to 2000ft before commencing a turn.

Engine Run-up Area

Engine-run-ups shall be performed next to TWY C or TWY J.

Warnings

Birds in vicinity of AD.

ARRIVAL

Communication

COM Failure: See CRAR.

CEB-RPVM

1-20

AOI

AOI

ARRIVAL

Arrival Procedure

VFR Traffic Pattern: RWY 04 right-hand circuit.

Non-standard GP Intercept Position on

RWY 04

GP intercepts RWY 04 at 310m / 1016ft after landing threshold.

Remaining DIST beyond GP is 3000m / 9844ft.

RWY 22

GP intercepts RWY 22 at 308m / 1011ft after landing threshold.

Remaining DIST beyond GP is 3002m / 9849ft.

DEPARTURE

Take-off Minima

RWY		04/22	
All ACFT	ft - m/km	0 - 400V	HJ only
		0 - 800V	HN

Communication

COM Failure: See CRAR.

Effective 21-JUN-2018

14-JUN-2018

Philippines Lapu Lapu Mactan-Cebu Intl

AGC
AFC

Mactan-Cebu Intl **Lapu Lapu** Philippines

CEB-RPVM

2-10

Legend:

- ATIS**: 126.600, 132.200 E, 127.500 W
- Mactan CTL**: 124.700, 121.200
- Mactan APP**: 118.100, 121.800, 125.100
- Mactan TWR**: 124.700, 121.200
- Mactan GND**: 118.100, 121.800
- Mactan DLV**: 124.700, 121.200

Landing RWY system:

04L: PAPI angle not AVBL, 3310 x 45, THR 21 (1hPa) / TDZ 26 (---%), +0.1%
 HL-S, 420, 60 HL, 30 HL

22R: PAPI angle not AVBL, 45 x 3310, TDZ 34 (---%) / THR 31 (1hPa), HL-P1
 -0.1%, 60 HL, 30 HL

Changes: Nil

Effective 21-JUN-2018

14-JUN-2018

CEB-RPVM

Philippines Lapu Lapu Mactan-Cebu Intl


3-20

AGC

AGC

Mactan-Cebu Intl Lapu Lapu Philippines

AGC



Changes: WIP, BLDG, Parking Stands

Effective 12-Oct-2017
05-OCT-2017

CEB-RPVM


4-10

RNAV SIDs RWY 04
[RNAV SIDs RWY 22]

SID
SID

RNAV SIDs RWY 04
[RNAV SIDs RWY 22]

Mactan-Cebu Int'l Lapu Lapu Philippines




Effective 12-Oct-2017

CEB-RPVM

Philippines Lapu Lapu Mactan-Cebu Intl

SID
SID

RNAV SIDs RWY 22
Mactan-Cebu Intl Lapu Lapu Philippines



02-FEB-2017

CEB-RPVM

Philippines Lapu Lapu Mactan-Cebu Intl

SID


SID

Mactan-Cebu Intl Lapu Lapu Philippines

SID

SID

4-30



02-FEB-2017

Philippines **Lapu Lapu** Mactan-Cebu Intl


CEB-RPVM

4-40

SIDs South

Mactan-Cebu Intl **Lapu Lapu** Philippines

SIDs South



CEB-RPVM

5-10

RNAV SIDs RWY 04

SIDPT

ALDIN 4P / CAREB 4P / DIMLO 4P / EMDEE 4P / KANON 4P / MOLOC 4P / PARAO 4P
RWY 04 (046°)

	GS	120	150	180	210	240	270
3.4%	ft/MIN	500	600	700	800	900	1000
3.7%	ft/MIN	500	600	700	800	900	1100
3.8%	ft/MIN	500	600	700	900	1000	1100
3.9%	ft/MIN	500	600	800	900	1000	1100

DESIGNATOR	ROUTING	ALTITUDES
	Runway 04	
ALDIN 4P 124.700	[M046 ;A2000+ ;R] - NIXON - ROLIN - EMDEE - ALDIN	
CAREB 4P 3.9% 124.700 ①	[M046 ;A2000+ ;R] - IRENE - CAREB	
DIMLO 4P 3.4% 124.700 ②	[M046 ;A2000+ ;R] - NIXON - THESA - DIMLO	
EMDEE 4P 124.700	[M046 ;A2000+ ;R] - NIXON - ROLIN - EMDEE	
KANON 4P 3.4% 124.700 ③	[M046 ;A2500+ ;L] - TAHAR - KANON	
MOLOC 4P 3.8% 124.700 ④	[M046 ;A2500+ ;L] - SEBIO - AKILO - MOLOC	
PARAO 4P 3.7% 124.700 ⑤	[M046 ;A2500+ ;L] - TAHAR - PARAO	

① ATC climb gradient to reach CAREB MNM 13000

② ATC climb gradient to reach DIMLO MNM 13000

③ ATC climb gradient to reach KANON MNM 13000

④ ATC climb gradient to reach MOLOC MNM 13000

⑤ ATC climb gradient to reach PARAO MNM 13000

CEB-RPVM

5-20

RNAV SIDs RWY 04

PONSO 4P

RWY 04 (046°)

	GS	120	150	180	210	240	270
4.3%	ft/MIN	600	700	800	1000	1100	1200

DESIGNATOR	ROUTING	ALTITUDES
	Runway 04	
PONSO 4P 4.3% 124.700 ①	[M046 ;A2000+ ;R] - PONSO	

① ATC climb gradient to reach PONSO MNM 13000

CEB-RPVM

5-30

RNAV SIDs RWY 22

ALDIN 4R / CAREB 4R / DIMLO 4R / EMDEE 4R / KANON 4R / MOLOC 4R

RWY 22 (226°)

	GS	120	150	180	210	240	270
3.4%	ft/MIN	500	600	700	800	900	1000
3.7%	ft/MIN	500	600	700	800	900	1100
3.8%	ft/MIN	500	600	700	900	1000	1100
4.0%	ft/MIN	500	700	800	900	1000	1100

DESIGNATOR	ROUTING	ALTITUDES
	Runway 22	
ALDIN 4R 124.700 ①	<u>MADOL</u> - BELEN - EMDEE - ALDIN	
CAREB 4R 3.4% 124.700 ①②	<u>MADOL</u> - MARVI - LEELA - CAREB	
DIMLO 4R 4.0% 124.700 ①③	<u>MADOL</u> - TUBIG - DIMLO	
EMDEE 4R 3.7% 124.700 ①④	<u>MADOL</u> - BELEN - EMDEE	
KANON 4R 3.7% to 3000 3.7% 124.700 ①⑤	<u>MELVZ [R]</u> - PINKY - KANON	
MOLOC 4R 3.8% to 3000 3.4% 124.700 ①⑥	<u>MELVZ [R]</u> - BURDA - MOLOC	

① Presence of low closed-in OBST near the DER of RWY 22 and within the RWY strip.

② ATC climb gradient to reach CAREB MNM 13000

③ ATC climb gradient to reach DIMLO MNM 13000

④ ATC climb gradient to reach EMDEE MNM 13000

⑤ Climb gradient 3.7% to 3000. ATC climb gradient 3.7% to reach KANON MNM 13000.

⑥ Climb gradient 3.8% to 3000. ATC climb gradient 3.4% to reach MOLOC MNM 13000.

CEB-RPVM

5-40

RNAV SIDs RWY 22

SIDPT

PARAO 4R / PONSO 4R

RWY 22 (226°)

	GS	120	150	180	210	240	270
3.7%	ft/MIN	500	600	700	800	900	1100

DESIGNATOR	ROUTING	ALTITUDES
	Runway 22	
PARAO 4R 3.7% to 3000 124.700 ①	MELVZ [R] - PINKY - PARAO	
PONSO 4R 124.700 ①	[M226 ;A2000+ ;K250- ;L] - DAROD [K250-] - ALMAR - PONSO	

① Presence of low closed-in OBST near the DER of RWY 22 and within the RWY strip.

02-FEB-2017

CEB-RPVM**5-50****SIDs North**

SIDPT

BATAY 2A / KANON 2A / MOLOC 2A / PARAO 2A / PONSO 2A / TADAG 2A

RWY 04 (046°)

DESIGNATOR	ROUTING	ALTITUDES
Runway 04		
BATAY 2A BTY 2A 124.700	at MNM 3000 LT intercept R351 MCT to TUBUR - BATAY	D10 MCT MNM 5000 TUBUR MNM 6000
KANON 2A KON 2A 124.700	at MNM 3000 LT intercept R296 MCT to SANGI - CARLO - KANON	D10 MCT MNM 5000 SANGI MNM 7000 CARLO MNM 9000
MOLOC 2A MLC 2A 124.700	at MNM 3000 LT intercept R326 MCT to MANOK - MOLOC	D10 MCT MNM 5000 MANOK MNM 6000 MOLOC MNM FL150
PARAO 2A PRO 2A 124.700	at MNM 3000 LT intercept R317 MCT to ASTUR - PARA0	D10 MCT MNM 5000 ASTUR MNM 8000
PONSO 2A PON 2A 124.700	at MNM 2000 RT intercept R048 MCT to PACIN - KAWIT - PONSO	PACIN MNM 6000
TADAG 2A TAG 2A 124.700	at MNM 3000 LT intercept R267 MCT to RASEC - TADAG	RASEC MNM 9000 TADAG MNM 11000

02-FEB-2017

CEB-RPVM**5-60****SIDs North****BATAY 2B / KANON 2B / MOLOC 2B / PARAO 2B / PONSO 2B / TADAG 2B**

RWY 22 (226°)

DESIGNATOR	ROUTING	ALTITUDES
Runway 22		
BATAY 2B BTY 2B 124.700	at MNM 3000 RT intercept R351 MCT to TUBUR - BATAY	D10 MCT MNM 5000 TUBUR MNM 6000
KANON 2B KON 2B 124.700	at MNM 3000 RT intercept R296 MCT to SANGI - CARLO - KANON	D10 MCT MNM 5000 SANGI MNM 7000 CARLO MNM 9000
MOLOC 2B MLC 2B 124.700	at MNM 3000 RT intercept R326 MCT to MANOK - MOLOC	D10 MCT MNM 5000 MANOK MNM 6000 MOLOC MNM FL150
PARAO 2B PRO 2B 124.700	at MNM 3000 RT intercept R317 MCT to ASTUR - PARA0	D10 MCT MNM 5000 ASTUR MNM 8000
PONSO 2B PON 2B 124.700	at MNM 2000 LT intercept R048 MCT to PACIN - KAWIT - PONSO	PACIN MNM 6000
TADAG 2B TAG 2B 124.700	at MNM 3000 RT intercept R267 MCT to RASEC - TADAG	RASEC MNM 9000 TADAG MNM 11000

02-FEB-2017


CEB-RPVM**5-70****SIDs South**

SIDPT


ALDIN 2A / BACON 2A / BOHOL 2A / COBOL 2A / DIMLO 2A / ALDIN 2B / BACON 2B / BOHOL 2B / COBOL 2B / DIMLO 2B

RWYs 04 (046°) / 22 (226°)

DESIGNATOR	ROUTING	ALTITUDES
Runway 04		
ALDIN 2A ALD 2A 124.700	at MNM 2000 RT intercept R210 MCT to LAMOK - AROLA - ALDIN	LAMOK MNM 6000 AROLA MNM 8000
BACON 2A BCN 2A 124.700	at MNM 2000 RT intercept R132 MCT to LIBON - BACON	LIBON MNM 5000 BACON MNM FL80
BOHOL 2A BOL 2A 124.700	at MNM 2000 RT intercept R152 MCT to DAHOY - BOHOL	DAHOY MNM 5000 BOHOL MNM FL130
COBOL 2A CBL 2A 124.700	at MNM 2000 RT intercept R176 MCT to TUBIG - COBOL	TUBIG MNM 5000 COBOL MNM FL60
DIMLO 2A DML 2A 124.700	at MNM 2000 RT intercept R162 MCT to MABID - DIMLO	MABID MNM 5000 DIMLO MNM FL60
Runway 22		
ALDIN 2B ALD 2B 124.700	at MNM 2000 LT intercept R210 MCT to LAMOK - AROLA - ALDIN	LAMOK MNM 6000 AROLA MNM 8000
BACON 2B BCN 2B 124.700	at MNM 2000 LT intercept R132 MCT to LIBON - BACON	LIBON MNM 5000 BACON MNM FL80
BOHOL 2B BOL 2B 124.700	at MNM 2000 LT intercept R152 MCT to DAHOY - BOHOL	DAHOY MNM 5000 BOHOL MNM FL130
COBOL 2B CBL 2B 124.700	at MNM 2000 LT intercept R176 MCT to TUBIG - COBOL	TUBIG MNM 5000 COBOL MNM FL60
DIMLO 2B DML 2B 124.700	at MNM 2000 LT intercept R162 MCT to MABID - DIMLO	MABID MNM 5000 DIMLO MNM FL60



Mactan-Cebu Intl Lapu Lapu Philippines



02-FEB-2017


CEB-RPVM

Philippines Lapu Lapu Mactan-Cebu Intl

STAR
STAR

6-30

Mactan-Cebu Intl Lapu Lapu Philippines

NIL
STARS

Effective 12-OCT-2017


05-OCT-2017

Philippines Lapu Lapu Mactan-Cebu Intl

CEB-RPVM

7-10

RNAV (GNSS) 04



Effective 12-OCT-2017

05-OCT-2017


CEB-RPVM

Philippines Lapu Lapu Mactan-Cebu Intl

IAC

7-20

RNAV (GNSS) 22



226°
at MNM 2000 LT (MAX 250KT)
(Do not turn before MAPt)
direct DAROD -
ALMAR (MAX 250KT)
climb 4000

GS	120	140	160
VM22B	640	740	850
-MAPt	3:39	3:07	2:44

DIST to THR

RW22
N10 19.1
E123 59.4

MDA

700

0 5 7.3 10

B10 to RNN						
22		RNAV GNSS LNAV				Circling
C	ft - m/km ft	430 - 1.3 460				Not authorized
D	ft - m/km ft	430 - 1.3 460				Not authorized

Changes: MSA, DIST ALT table


02-FEB-2017

Philippines Lapu Lapu Mactan-Cebu Intl

CEB-RPVM

7-30

VOR 04



Changes: LDA, TDZE, QFU, THR ELEV, AD ELEV, Editorial


02-FEB-2017

Philippines Lapu Lapu Mactan-Cebu Intl

CEB-RPVM

7-40

VOR Z 22



Changes: Completely revised

02-FEB-2017


Philippines Lapu Lapu Mactan-Cebu Intl

IAC

CEB-RPVM

7-50

VOR Y 22



Changes: Completely revised

02-FEB-2017

Philippines Lapu Lapu Mactan-Cebu Intl **RC** **RC** **Mactan-Cebu Intl Lapu Lapu Philippines**


CEB-RPVM

8-10

The MRC logo consists of the letters "MRC" in a bold, black, sans-serif font. Above the letter "M", there is a small rectangular box containing the letters "NIL" in a white, bold, sans-serif font.

MRC
100

Mactan-Cebu Intl **Lapu Lapu** Philippines



Changes: Completely revised