

02-NOV-2017

YDF-CYDF

1-10

AOI

AOI

GENERAL**Operational Hours****ATS Hours:** RDO, RCO**AD OPS Hours:** Not published**Airport Information****RFF:** CAT 6 0830-0430‡, CAT 7 30min PN. Other times O/R**PCN:** O/R**Customs:** AOE/120 (250 with stage off-loading)

FEB 01 - MAY 30: MON-FRI 1830-0230‡.

JUN 22 - SEP 30: MON-FRI 1130-1930‡.

Operation**Aerodrome Level of Service**

RWY 07/25: 1200R/0.25V

RWY Restriction

RWY surface condition AVBL 0830-0430‡.

Warnings

No winter MAINT 0430-0830‡, O/T 2HR PN.

Water tower 1NM N of THR RWY 25, 225ft AMSL.

ARRIVAL**Speed**

MAX IAS 250KT below 10000ft.

MAX IAS 200KT below 3000ft AGL within 10NM of AD.

Communication**COM Failure:** See CRAR Canada.**Arrival Procedure****Non-standard GP intercept position on RWY 25**

GP intercepts RWY 25 at 349m / 1145ft after landing threshold.

Remaining LDG DIST beyond GP is 2091m / 6860ft.

02-NOV-2017

YDF-CYDF

1-20

AOI

DEPARTURE**Take-off Minima**

RWY		07	
All ACFT	ft - ft/SM	0 - 0.5V	No LT BLW 1400
RWY		25	
All ACFT	ft - ft/SM	0 - 0.5V	MNM climb gradient 4.8% up to 1900. Climb on RWY HDG to 1200 BPOC

Communication**COM Failure:** See CRAR Canada and in addition;

On recognition of COM failure 10min or less after TKOF and IFR WX conditions proceed as follows:

- Upon reaching last assigned ALT proceed on course.
- Maintain last assigned ALT for 10min after TKOF.
- Climb to flight planned ALT.

Note: If COM failure occurs more than 10min after TKOF, comply with the appropriate PROC for COM failure ENRT.

Effective 13-SEP-2018

06-SEP-2018

YDF-CYDF


Canada Deer Lake

AGC
AFC

Deer Lake Canada

AGC
AFC

2-10



Gander Center
RCO (Halifax RDO)

134.600
123.375 FIS
126.700 BCST
122.200 MF 5NM up to 3100

RDO

Landing RWY system:

PAPI for EWH <26ft
07 83.0° 60 HL
732 2440 x 46

HL-P1 THR 44 (2hPa) / TDZ 57 (---%) +0.3%
60 HL 46 x 2440 732
-0.3% TDZ 72 (---%) / THR 72 (3hPa) HL-P1R

Effective 13-SEP-2018

06-SEP-2018

YDF-CYDF

Canada Deer Lake

AGC

Deer Lake Canada

AGC

3-20


W057°24.5'

W057°24'

W057°23.5'

RWY	TORA	ASDA	TODA
07	2440	2440	2740
25	2440	2440	2740

RCO (Halifax RDO) 123.375 FIS
126.700 BCST
RDO 122.200 MF 5NM up to 3100



Changes: Nil

Effective 13-SEP-2018

06-SEP-2018

YDF-CYDF

Canada Deer Lake

NIL

DEER LAKE 9 (CYDF 9)

Deer Lake Canada


NIL

DEER LAKE 9 (CYDF 9)

SID

SID

4-10



DEER LAKE 9

RWYs 07 (066°) / 25 (246°)

	GS	120	150	180	210	240	270
4.8%	ft/MIN	600	800	900	1100	1200	1400

DESIGNATOR	ROUTING	ALTITUDES
DEER LAKE 9 CYDF 9 134.600		initial climb 6000
RWY 07	climb RWY HDG - expect radar vectors no LT below 1400	
RWY 25 4.8% to 1900	climb RWY HDG - expect radar vectors no LT below 1200	

Obstacle Departure

	GS	120	150	180	210	240	270	
4.8%	ft/MIN	600	800	900	1100	1200	1400	

RWY	Routing
07	no LT below 1400
25	climb MNM 4.8% (290ft/NM) to 1900 climb RWY HDG to 1200 before proceeding on course; or in visual conditions: climb over CYDF at or below 1300 before proceeding on course.
RWY	Notes
07	Trees to 138ft ASL approximately 0.1NM past DER, 550ft left and right of RWY centerline.
25	Trees to 117ft ASL approximately 0.1NM past DER, 600ft left and right of RWY centerline.

Effective 13-SEP-2018

06-SEP-2018


YDF-CYDF

Canada Deer Lake

IAC

7-10

ILS 25



Changes: Completely revised

Effective 13-SEP-2018

06-SEP-2018


Canada Deer Lake

YDF-CYDF

7-30

RNAV (RNP) Y 07

IAC



Changes: new

Effective 13-SEP-2018

06-SEP-2018


Canada Deer Lake

YDF-CYDF

7-40

RNAV (RNP) Y 25

IAC



Changes: new

Effective 13-SEP-2018

06-SEP-2018


YDF-CYDF

Canada Deer Lake

IAC

7-50

RNAV (GNSS) Z 07



Changes: Completely revised

Effective 13-SEP-2018

06-SEP-2018


YDF-CYDF

Canada Deer Lake

7-60

RNAV (GNSS) Z 25

IAC



Changes: Completely revised