

15-JAN-2015

**MPA-FYKM****1-10****AOI****AOI****GENERAL****ATS Hours**

SUN-FRI 0600-1100‡ and 1200-1500‡, SAT CLSD. Other times O/R.

**Airport Information**

**RFF:** CAT 5, MON-FRI 0600-1500‡, SUN 0800-1200‡, SAT not AVBL

**Fuel:** MON-FRI 0600-1500‡, SAT, SUN and HOL O/R

**PCN:** RWY 09/27: LCN 29

**Customs:** 24HR PN

**Operation****Taxi/Parking**

ACFT must backtrack and use RWY-TWY intersection abeam old TWR only. Former full length parallel TWYs and intersections permanently CLSD.

**ARRIVAL****Communication****COM Failure**

ACFT to join overhead the AD at 2000ft AGL.

Observe and join the AD traffic.

Make all turns to the left whenever possible.

Land as soon as possible and report to ATC.

**Arrival Procedure****VFR Traffic Pattern**

RWY 09 right-hand circuit.

**DEPARTURE****Take-off Minima**

RWY		09/27	
All ACFT	ft - m/km	0 - 400V	HJ only



15-JAN-2015

MPA-FYKM

Namibia Katima Mulilo

3-20

AGC

Katima Mulilo Namibia

AGC

E024°10'

E024°10.5'

E024°11'

Katima TWR 125.600 SUN-FRI  
0400-1600

S17°38'

09

088°

3144

2292 x 21



ARP  
S 17 38.1  
E 024 10.6

27

268°

3126

S17°38.5'

VAR 8° W  
MAG UP

AD ELEV 3144

