

05-APR-2018

RCQ-SATR

1-10

AOI

AOI

GENERAL**Operational Hours****ATS Hours:** 1000-2200**Airport Information****RFF:** CAT 3**PCN:** Not published**Operation****Taxi/Parking**

Taxi at reduced speed and strictly follow TWY CL.

Enter APN via TWY A, unless access via TWY C and B is authorized by TWR.

Taxi into/out of stands under own PWR, with marshalling assistance whenever required, unless otherwise indicated by ATC.

Engine Run-up

Engine tests not allowed BTN 0100-1100.

Warnings

Birds in vicinity of AD.

ARRIVAL**Speed**

MAX IAS 250KT below FL100 within airspace classes B, C, D and G.

Communication**COM Failure:** See CRAR.**Arrival Procedure****VFR Traffic Pattern:** RWY 10/28 right-hand circuit.**DEPARTURE****Take-off Minima**

RWY		10/28		
Multi ENG	ft - m/km	0 - 550V	HJ only	For conditions check CRAR
		0 - 800V	HN	
RWY		02/20		
Multi ENG	ft - m/km	0 - 1.5V	HJ only	For conditions check CRAR

Speed

MAX IAS 250KT below FL100 within airspace classes B, C, D and G.

Communication**COM Failure:** See CRAR.**Departure Procedure****Noise Abatement Procedure:** Use TKOF PROC B.

24-MAY-2018

RCQ-SATR


Argentina Reconquista

AGC
AFC

Reconquista Argentina

AGC
AFC

2-10



APP	119.000 1000-2200
	118.500 1000-2200
TWR	119.000 1000-2200
	118.500 1000-2200

Landing RWY system:

02

1250 x 34

THR 159 (6hPa) / TDZ --- (---%) 0.0%

20

34 x 1250

0.0% TDZ --- (---%) / THR 159 (6hPa)

10

60 L

L-N 2800 x 50 360 THR 159 (6hPa) / TDZ --- (---%) 0.0%

28

50 x 2800

0.0% TDZ --- (---%) / THR 162 (6hPa)

Changes: Completely revised

24-MAY-2018

RCQ-SATR

Argentina Reconquista


3-20

AGC

AGC

Reconquista Argentina

AGC



Changes: Nil


12-JUL-2018

RCQ-SATR

7-10

IAC

VOR Z 10



Changes: Nil


12-JUL-2018

RCQ-SATR

7-20

IAC

VOR Y 10



Changes: HLGD


24-MAY-2018

RCQ-SATR

7-30

IAC

VOR Z 28



Changes: New


24-MAY-2018

RCQ-SATR

7-40

IAC

VOR Y 28



Changes: New