

05-APR-2018

CPC-SAZY**1-10****AOI****GENERAL****Operational Hours****ATS Hours:** 1200-2100**Airport Information****RFF:** CAT 4**PCN:** RWY 06/24: 38/F/B/X/T**Operation****TWY Restrictions**

TWY A width 18m / 59ft.

Taxi/Parking

Taxi at reduced speed and strictly follow TWY CL.

Taxi into stands under own PWR, unless otherwise indicated by ATC.

Marshalling assistance mandatory for code letter C ACFT entering stands 1 and 2.

Taxi out of stands under own PWR with reduced thrust in order to avoid damage due to jet blast.

Engine Run-up

Engine tests not allowed BTN 0100-1100.

Warnings**CHP VOR/DME** unusable:

Between R290-R330

Below FL80

Birds in vicinity of AD.

ARRIVAL**Speed**

MAX IAS 250KT below FL100 within airspace classes B, C, D and G.

Communication**COM Failure:** See CRAR.**DEPARTURE****Take-off Minima**

RWY		06/24		
Multi ENG	ft - m/km	0 - 550V	HJ only	For conditions check CRAR
		0 - 800V	HN	

Speed

MAX IAS 250KT below FL100 within airspace classes B, C, D and G.

Communication**COM Failure:** See CRAR.**Departure Procedure****Noise Abatement Procedure:** Use TKOF PROC B.

05-APR-2018

Argentina San Martin De Los Andes Aviador C.Campos

AGC

AFC


Aviador C.Campos **San Martin De Los Andes** Argentina

AGC

AFC

CPC-SAZY

2-10



Chapelco APP	119.600
	118.200
Chapelco TWR	119.600
	118.200
Chapelco GND	121.700

Landing RWY system:

0

THR 2588 (90hPa) / TDZ --- (---%) -0.5%

PAPI angle not AVBL

45 x 2500

+0.5% TDZ --- (---%) / THB 2543 (80hPa)

10.1111/j.1467-9543.2009.01615.x

1
H
I
G
H
S
C
O
R
P
U
S

Digitized by srujanika@gmail.com

© 11/10/2018

Changes: New

05-APR-2018

Argentina San Martin De Los Andes Aviador C.Campos


CPC-SAZY

3-20

AGC

AGC

Aviador C.Campos San Martin De Los Andes Argentina



Changes: New

05-APR-2018

Argentina San Martin De Los Andes Aviador C.Campos

IAC

CPC-SAZY

7-10

VOR DME One Circling

