

DryFast Restoration LLC — Repair Estimate

Estimate #DF-9921 · for CLM-2026-44817

Property	742 Birchwood Lane, Springfield, IL 62704
Prepared for	Jordan & Sam Avery
Inspection date	2026-03-16
Cause	Burst supply line under kitchen sink — water damage

Estimated Costs

Description	Category	Amount
Remove & replace hardwood flooring (180 sq ft)	Dwelling	\$8,500.00
Replace lower cabinets + countertop section	Dwelling	\$4,200.00
Emergency water extraction + 3-day drying	Mitigation	\$3,100.00
Area rug (not restorable)	Contents	\$900.00
	Total claimed	\$16,700.00

Notes: Damage limited to kitchen and adjacent hallway. No evidence of long-term leakage; failure appears sudden.
Estimate valid 30 days.